

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001 No.F6/DFS/MS/GH/2024/ | 8 Dated: 34/04../2024

FIRE SAFETY CERTIFICATE

Certified that the Metro Plaza Guest House located at 2691-95, Chuna Mandi, Rajguru Road, Pahar Ganj, New Delhi is comprised of Ground floor reception, 1st floor to 3rd floor 05 guest rooms at each floor total 15 guest rooms up to third floor only, was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/2021/85 dated 11/02/21 for 15 guest room up to third floor only. Now, the premises was re-inspected by the officer concerned of this department on 23/01/24 in the presence of Manager and found that the said guest house building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential Group -A-1' Ground floor reception, 1st floor to 3rd floor 05 guest rooms at each floor total 15 guest rooms and valid up to 31.03.2027 from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ... 31 01 2.2.4 ... at New Delhi by.

DIRECTOR elhi Fire Service

Copy to:-

 The Commissioner, North MCD Civic Centre, New Delhi. : to ensure the deviation if any and occupancy as detailed above

- The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony, New Delhi ID NO. 2024011600513 dated 16.01.2024.
- 3. The Manager, Metro Plaza Guest House, 2691-95, Chuna Mandi, Rajguru Road, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction, use of occupancy, height of building, electric installation, set back area etc. shall be checked & verified by the concerned authority.

This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

9. Any flammable material for interior decoration is strictly prohibited.

er floors	1.25 mur. Olu	mtr. /	case) N/A		
	1.25 mtr. Old	1.50 mtr.to 1.40	MR(old		
th of staircase	or Khi eez		1 m (11		
ements	N/A	N/A	N/A		
er floors	01 Nos.	01 Nos.	MR		
nber of staircases	Tend all len				
er, Width Type & Arı		its			
th of internal road	N/A	N/A	N/A		
width	N/A	N/A	N/A		
d width	N/A	06 mtr. /	MR		
ccess to Building	Lowerson				
um Standards on fire tion and fire safety	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR		
construction:- it's letter No:- prised of ground and the ploaded.	id no. 202401 uree upper floors a	1600513 dated 16. nd one staff room a	01.2024. t terrace as p		
& designation of office he building side:-	Manager				
of the inspecting office		a Dinga (•		
f inspection:-		er Singh (ADO/CC)		
Fire safety directives No N/A Date of inspection:- 23/01/24					
2 40 1	11/02/21.				
s of previous FSC:-	No.F6/DFS/MS/GH/2021/85 dated				
f case:-	Renewal				
f occupancy: -	Residential	l, Sub Division-A-I er floors (total 15 Gues reception, 1st floor to 3	et rooms)		
& address of the building	95 Chuna	95 Chuna Mandi, Raiguru Road, Panar			
INS	PECTION REPO	ORT	d at 2601.		
& a	INS address of the building	INSPECTION REPO	INSPECTION REPORT address of the building Metro Plaza Guest House locate 95, Chuna Mandi, Rajguru Rog Ganj, New Delhi. Gr.+ three u		

N/A

30 ACPH

12 a/c per hour

1 mtr.

C. Protection of exits

D. No. of continuous staircase to terrace

E. Width of corridor

Compartmentation

2) Sealing of electrical shafts

Smoke Management System

3) Fire rating of shaft door

1) Fire check door

4) Water curtain

5) Fire Dampers

1) Basements

2) Upper floors

F. Door size

3.

4.

1. Fire check door

2. Pressurization

N/A

N/A

N/A

N/A

N/A

MR

N/A

N/A

N/A

N/A

N/A

N/A

MR

N/A

N/A

N/A

N/A

N/A

1 mtr.

N/A

N/A

N/A

N/A

N/A

N/A

Natural

5.	The Total		1	
J.	Fire Extinguishers		/	4
mpa)	1) Total numbers	08 Nos.	10 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR *
5.	3) ISI marking	Required	Provided	MR
0.	First-Aid Hose Reel			
	1) Total number of eachfloor	01 no.	01 no.	MR
	2) Length of hose reel hose	30 mtr.	Provided	MR
7	3) Nozzle diameter	N/A	Provided	MR
7.	Automatic Fire Detection &	Alarming Syste	em	
	1) Type of detectors	Required	Provided	MR
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided (MR
9.	Public Address System	Required	Provided /	MR
10.	Automatic Sprinkler System		/	1
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants		100	1
	1) Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			1
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			1
	1) Ground level	N/A	N/A	N/A
	 a) Discharge of main pump 	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM /	MR
	b) Head of pump	30 mtr.	30 mtr. /	MR
14.	c) Power supply	Required	Provided	MR
	d) Auto starting of pump Required Provided MR			
14.	Captive Water Storage for F 1) Under ground tank		1570	
	capacity	N/A	N/A	N/A
1	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A

	c) Access to tank	N/A	N/A	N/A
bord	d) Over head tank capacity	5,000 ltrs.	5,000 ltrs.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		1.00	A. 144
1.6	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided /	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19. F	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any: ABC & CO ₂	m for Protecti	ion of special	N/A

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. F6/DFS/MS/GH/2021/85 dated 11/02/21, under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)