

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/EH/2024/SZ/40 No.

Dated. 0.7/02/2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Circle café and Bar located at F-1 First Floor, Kalkaji, New Delhi 110019 in the building Comprised of Basement Ground plus Three upper floor owned/Occupied by A unit of Bliss Hospitality Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 01/02/2024 on in the presence of Mr. Rahul and found that the premise is fit for occupancy Group "D" (Assembly Building) Restaurant at First floor only and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 07 / 02 /2024 at New Delhi by

olu

Copy to: -

1. The Dy. Health Officer, MCD, Public Health Department, Central Zone, Jal Vihar, Lajpat Nagar New Delhi-110024. (Ref. MHA Portal ID 2024011000299 dated 10-01-2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of UBBL 2016 /NBC Part- IV.

4. All the staff members must know the correct method of operation of fire fighting

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



Name & Address of the Building Type of Occupancy Building comprised of	M/s Circ Pvt Ltd) 110019	le café	and Bar, (A unit of Bliss . First Floor, Kalkaji,	Hospitality New Delh		
Type of Occupancy Building comprised of	110019	le café at F-1	and Bar, (A unit of Bliss . First Floor, Kalkaji,	Hospitality New Delh		
Building comprised of	110019		35			
Building comprised of	Assembly		110019			
	Assembly 'Group-D'					
	Basement, Ground plus 03 upper floors (Restauran running at First Floor only)					
Type of Case	New		THE RESERVE TO THE RE			
Details of Previous NOC	NEI					
Fire Safety Directives Letter No	Nil					
Date of Inspection	UBBL 2016/ NBC Part IV					
500000000000000000000000000000000000000	01.02.2023					
Name of the Inspecting Officers	DO (South) & ADO (BCP)					
from the building side	Sh. Rahul					
Year of construction/ date of conversion	2015					
Applicant letter No.	MHA Portal ID 2024011000299 dated 10-01-2024					
Minimum standards on Fire Prevention and Fire Safety U/R 33			Provided at Site	Remarks		
Access to Building.	7 Thill is	n ment	Ag mentaning about			
Road width	06 m		15 mtr	MR		
Gate width	4.5 m		Direct accessible	MR		
Width of internal road		alice N	NA	-NA-		
Number, width, type & arrangement of e	xits		and shall be a			
a. Number of Staircase		-57	SAL DOLLAR PROPERTY.	64		
Upper floors	02 Nos		03 Provided	MR		
	-NA		NA	-NA-		
	-NA- NA		-NA-			
The state of the s		William	A GREEK PROPERTY.			
	NA		NA	NA		
70 - 2 - 1144 - 1174 - 1			NA NA	-NA-		
				MR		
				N/A		
EST COMMINAGENESIA	2 X 1.3	vm _	1.60 m, 1.60 & 1.50 m	MR		
Compartmentation.			bead sorters.			
Fire check door.	N/A		N/A	N/A		
 Sealing of electrical shafts. 	N/A		N/A	N/A		
 Fire rating of shaft door. 	N/A		N/A	N/A		
Water curtain			N/A	N/A		
Fire dampers.	N/A	First :	N/A	N/A		
	72.0	es Au	Lindayacenda			
Basement			N/A	N/A		
Upper floors	12 AC	PH	N/A	N/A		
Fire Extinguishers.			I I I I AND N			
Total numbers	06 Nos		06 Provided	MR		
• Types	ABC / CO2			MR		
ISI Marking	ISI ma	ked	Provided	MR		
PARTITION IN THE PARTIT						
First Aid Hose Reels.	One					
	Name & Designation of Officers from the building side Year of construction/ date of conversion Applicant letter No. Minimum standards on Fire Prevention and Fire Safety U/R 33 Access to Building. Road width Gate width Width of internal road Number, width, type & arrangement of ea. Number of Staircase Upper floors Basement floor Width of Staircase Upper floors Basement floor Pressurization No. of continuous staircase to terrace Width of corridor Door size Compartmentation. Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers	Name & Designation of Officers from the building side Year of construction/ date of conversion Applicant letter No. Minimum standards on Fire Prevention and Fire Safety U/R 33 Access to Building. Road width Gate width Width of internal road Number, width, type & arrangement of exits NA Number of Staircase Upper floors Basement floor Basement floor Fire check door Pressurization NA No. of continuous staircase to terrace Width of corridor Fire check door Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Basement Upper floors NA	Name & Designation of Officers from the building side Year of construction/ date of conversion Applicant letter No. Minimum standards on Fire Prevention and Fire Safety U/R 33 Access to Building. • Road width • Gate width • Width of internal road Number, width, type & arrangement of exits a. Number of Staircase • Upper floors • Basement floor b. Width of Staircase • Upper floors • Basement floor c. Protection of exits • Fire check door • Fire check door • Fire check door. • Sealing of electrical shafts. • Fire rating of shaft door. • Water curtain • Fire dampers. Smoke Management system. • Total numbers O MHA Portal ID 2 UBBI/NBC Requirement UBBI/NBC Requirement 0 08 m 1.50 m NA NA NA NA NA NA NA Pressurization -NA- 0 1 NA NA NA NA NA NA NA NA NA N	Name & Designation of Officers from the building side Year of construction/ date of conversion Applicant letter No. MHA Portal ID 2024011000299 dated 10 Minimum standards on Fire Prevention and Fire Safety U/R 33 Access to Building. Road width O6 m		





	Length of hose-reel hose.	30m	Provided	MR
	Nozzle Diameter	5mm	Provided	MR
7				
	Type of detectors	-NA-	Provided	-NA
ese, i	Location of Main Panel	-NA-	NA	-NA
	Location of Repeater Panel	-NA-	NA	-NA
	Alternate source of power	-NA-	NA	-NA
	Hoofer's location	-NA-	NA NA	-NA
8	MOEFA	Required	Provided	MR
9	Public Address System	-NA-	NA	-NA
	25 AN P 4	-NA-	and the same	1
10	Automatic Sprinkler System	er-muli	ALC: NO	
	Basement	100mm	Provided	MR
	Upper floors	01 No	Provided	MR
	Sprinkler above false ceiling	01 No	Provided	MR
11	Internal Hydrants.		THE RESERVE	
		-NA-	-NA-	-NA
	Size of Riser/Down-comer	-NA-	-NA-	-NA
	Number of Hydrant per floor	-NA-	-NA-	-NA
	Hose box.	-NA-		
12	Yard Hydrants.		fit (v. 1847) 💉	
	Total number of hydrants.	-NA-	NA -	-NA
	Hose box.	-NA-	NA NA	-NA
13	Pumping arrangements.		vicingly - upper X	
				-
	Ground Level			-NA
1	Discharge of main pump.	-NA-	-NA-	1
	> Head of main pump.	-NA-	-NA-	-NA
	Number of main pumps.	-ΝΛ-	-ΝΛ-	-NA
. 1	Jockey Pump output.	-NA-	-NA-	-NA
- 1	> Jockey Pump head.	-NA-	-NA-	-NA
-	> Standby Pump output.	-NA-	-NA-	-NA
	> Standby Pump head.	-NA-	-NA-	-NA
	Auto Starting / Manual Stopping.	-NA-	-NA-	-NA
	> Pump House Access	-NA-	-NA-	-NA
			THE ENDER	1
	Terrace Level	450 LPM	Provided	MR
	Discharge of pump.	430 EF W	Provided	MR
	Head of pump.Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
4	Captive water storage for Fire Fighting.			
-	Underground tank capacity.	-NA-	-NA-	-NA-
1	> Draw-off connection.	-NA-	-NA-	-NA-
	> Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	20,000 Ltrs	20,000 ltr	MR
5	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		T RSZ ISW	1
	 Pressurization of lift shaft. 	-NA-	NIA	-NA-
	- 1 10000112attOll Of lift Shart.	*INA.	-NA-	*NA*







	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	 Communication in lift car. 	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
	 Lift signage. 	-NA-	-NA-	-NA-
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	Total area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	-NA-
19	Fire Control Room.			
-	Detector System Panel.	-NA-	-NA-	-NA-
	Flow Switch Panel.	-NA-	-NA-	-NA-
	PA system Panel.	-NA-	-NA-	-NA-
	Battery backup	-NA-	-NA-	-NA-
	Building floor plan	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any:	-NA-	-NA-	-NA-

M/s Circle café and Bar, (A unit of Bliss Hospitality Pvt Ltd) at F-1, First Floor, Kalkaji, New Delhi 110019

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 679 dated 19/12/2023.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

merse.

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ)

5 21 204

Deneta

Any pc

F-7. 1

letter -

6/2/24

Director

my

02/02/24

B