

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. 16/DFS/MS/2024/WZ/Club/ \$3

Dated: 07 02 2024

FIRE SAFETY CERTIFICATE

Certified that the D. D. Club, situated at Dr. K. N. Katju Marg, Sector-13, Rohini, Delhi-110085, comprised of Double basement, Ground + 03 upper floors owned/occupied by M/s IUA Trust (Regd) has already been issued FSC by this department vide letter No. F.6/DFS/MS/112 dated 12.02.2021. The premises was re-inspected by the officer concerned of this department on 30.01.2024 in the presence of Sh. Viny Mehra (GM) and found that 01 hall & swimming pool at terrace of 3rd floor (i.e. 4th Floor) & 01 hall on terrace of 2nd floor have been added. Now the building is comprised of Two Basements, Ground Plus Four Upper Floors and have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy Group-D "Assembly Building" (Club House) with effect from OF 02 2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 07 02 2024 at New Delhi by

(Atul Garg) DIRECTOR Ph; 011-23414000

Copy to: -

1. MHA Portal ID No. 2024012400798 dated 24.01.2024

Conditions for the validity of Fire Safety Certificate:

- All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- The access of the above club building from the main road is closed by covering the Nullah. It should be provided within 06 months time at the risk & responsibility of D.D. Club management. Otherwise FSC will be null & void automatically.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

1			INSPE	CTION I	REPORT				
1	Name &	address of the building					Guest House, sit	uated at Dr. K	
			4 4	Katju Marg, Sector-13, Rohini, Delhi-110085. Assembly					
2. Type of Occupancy				Additional /alternation (02 Basement, Ground + 04 upper floors)					
3. Type of Case			room a	room at terrace of 3 rd floor & hall on terrace of 2 rd floor)					
4. Details of Previous NOC				(F.6/DFS/MS/112 dated 12.02.2021. Previous NOC-02 Basement, Ground + 03 upper floors)					
				F.6/DFS/MS/BP/2009/3095 dated 27.10.2009.					
			★ 5 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	F.6/DFS/MS/BP/2020/433 dated 17.11.2020.					
	かんついんこう こうこうしょ	inspection		30.01.2024.					
	VI 2024 VI VI VI VI	Inspecting Officer ad designation of officers		Ajay Kumar Sharma ADO(Rohini) Sh. Viny Mehra (GM)					
		e building side	, J	,,					
	Year of	Construction	\$ 5500 KID \$15	2014 & 202					
0.	Applica	nt's letter No.				124007	98 dated 24.01.202	4. & OD	
1	Minimum Standards on fire preventi		N. M. M. C. L.	No.11035 dated 21		Provi	ded at site	Remarks	
)	fire safety U/R 33			Requirement		20/2//2/2		MR/NMR	
	Access to building						74 74 75	1 10 C (
	ĕ	Road width		09m	Appl		ven application to PWD	MR for 6 month	
		Gate width		5m			ovided	MR	
		Width of internal road		6m			ovided	MR	
	Number, Width, Type & Arrangement of Ex				- 11			J. M.	
				1					
	a. Number of staircases			03			Provided	MR	
	Upper Floors Basements			02 & 01 ramp		1	Provided	MR	
						- 5			
	b. Width of staircases						n See		
	Upper Floor			1.5m & 2.0m		- 8	Provided	MR	
	Basements				1.5m	- 1	Provided	MR	
	c. Pr	otection of exits							
		Fire check door		Required			Provided	MR	
	Pressurization			Required			Provided	MR	
	d. No. of continuous staircases to terrace			Olnos.			Provided	MR	
	e. Width of Corridor			-NA-			-NA-	-NA-	
	f. Door Size Compartmentation			2mtr, 1.5mtr & 2.0mtr Provided			Provided	MR	
							×		
	Fire check door			Required			Provided	MR	
	Scaling of electrical shafts		1	Required			Provided	MR	
	Fire Rating of shaft door Water Curtain			Required -NA-			Provided	MR	
	Fire Dampers			-NA- Required		-ΝΛ-	-NA-		
	Smoke Management System			-	Required		Provided	MR	
			Mee	Mechanical ventilation Provided			MR		
		Upper floors		Mechanica	al/	Mech	anical ventilation	MR	
				tural venti	lation		Provided		
5.	Fire Extinguishers		1 020	40					
	.9.			18nos.		48nos. O ₂ , 23 ABC, 10 CO ₂ , 04		MR	
		Types	ABC/C	O_2	foam trol		IV CO. 01	MR	
		IS marking	151	marked	Ι	Y	es	MR	





_ (1				4			
6.	First-Aid Hose Reels						
	Total numbers on each floor	02	Provided	MR			
-	 Length of hose reel hose 	30mm	Provided	MR			
	Nozzle diameter	5m	Provided	MR			
7.	Automatic fire detection and alarming syste	the second secon	TTOTIGGG				
	Type of detectors	Heat/Smoke	Provided	MR			
	Location of Main Panel	GF	Provided	MR			
	Location of Repeater Panel	-ΝΛ-	-NA-	-NA-			
	Alternate source of power	Required	Provided	MR			
	Hooters' Location	Strategic location	Provided	MR			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	Required	Provided	MR			
10.	Automatic Sprinkler System						
	Basement	Required	Provided	MR			
	Ground & Upper Floors	Required	Provided	MR			
	Sprinkler above false ceiling	Required	Provided	MR			
11.							
	Size of riser/down-comer	150mm	Provided	MR.			
	Number of hydrants per floor	02nos.	Provided	MR			
	Hose Box	02nos.	Provided	MR			
12.	Yard Hydrants			MD			
	Total number of hydrants	05nos.	Provided	MR			
	Hose Box	05nos.	Provided	MR			
13.	Pumping Arrangements						
	Ground Level		n	MR			
	 Discharge of main Pump 	2280lpm	Provided Provided	MR			
	➤ Head of Main pump	70m	Provided	MR			
	Number of main pumps	01	Provided	MR			
	> Jockey Pump out put	1801pm 70m	Provided	MR			
	Jockey pump head	2280lpm	Provided	MR			
	Standby Pump out put	70m	Provided	MR			
	 Standby Pump Head Auto Starting/Manual Stopping 	Required	Provided	MR			
	Pump House Access	Required	Provided	MR			
	(A) 10 March 2012 (25)	Required					
	Terrace level	-NA-	-ΝΛ-	-ΝΛ-			
	> Discharge of pump	-NA-	-ΝΛ-	-ΝΛ-			
	➤ Head of the pump	-NA-	-ΝΛ-	-NΛ-			
	Power Supply	-NA-	-ΝΛ-	-ΝΛ-			
	Auto Starting of pump	1 - 1					
14.	Captive Water Storage for fire fighting	75000 ltr	Provided	MR			
	 Underground tank capacity 		Provided				
	> Draw-off connection	Required	Provided	MR			
	Fire service inlet	Required	C STATES SALES	MR			
	- Access to tank	Required	Provided	MR			
	o Land Tank canacity	10,000 ltr	Provided	MR			
	Exit Signage.	Required	Provided	MR			
15.	Provision of Lifts.	-					
16.	Pressurization of Lift Shaft	Required	Provided	MR			
	Pressurization of Lift lobby	Required in basement	Provided	MR			
	• Plessurvas	NH/	Acr				

M

or

1	1	Communication In lift Car	Required	Provided	MR	
		Fireman's Grounding Switch	Required	Provided	MR	
		Lift Signage	Required	Provided	MR	
	standb	y power supply	Required	Provided	MR	
1	Refuge Area.					
		Total Arca	-NA-	-ΝΛ-	-NA-	
	>	Location	-NA-	-ΝΛ-	-NA-	
19.	Fire Co	ntrol Room		,		
	•	Detector System Panel	GF	provided	MR	
		Flow Switch Panel	Required	Provided	MR	
	•	PA System Panel	Required	Provided	MR	
	•	Battery backup	Required	Provided	MR	
	•	Building Floor Plans	Required	Provided	MR	
	STATE OF STREET	Fire Protection System for tion of special Risks, if any:	-ΝΛ-	-ΝΛ-	-ΝΛ-	

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Note: 1 .The access of the above club building from the main road is closed by PWD for covering the Nullah. It should be provided within 06 months time at the risk & responsibility of D.D. Club management.

2. The shortcomings issued by this department vide letter No. F.6/DFS/MS/WZ/2023/236 dated 29.11.2023 have been complied with by the club management.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act- 2007 & Rules- 2010.

Accordingly, DFA is put up please.

Signature of the Inspecting Officer Name: - Ajay Kumar Sharma Designation:- ADO/Rohini