



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2024/45

Dated: 07/02/2024

FIRE SAFETY CERTIFICATE

Certified that M/s Lavonne Hospitality Private Limited located at Upper Ground Floor, D-16, Defence Colony, New Delhi-110024, comprised of Basement, Stilt, Ground plus three upper floors but the restaurant at Upper Ground/First Floor only, owned/occupied by M/s Lavonne Hospitality Private Limited, have complied with the fire prevention and Fire Safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 23/01/2024 in the presence of Sh. Rakesh Ranjan and observed that the that said premise is fit for occupancy class "Assembly Group D" (Eating House) up to 31/03/2027 in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rules, 2010.

Issued on <u>67</u> / <u>62</u>. /2024 at New Delhi by

(ATUL CARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

- The Dy. Health Officer, Central Zone, Municipal Corporation of Delhi, Jal Vihar, Lajpat Nagar, New Delhi-110024 (w.r.t. MHA ID: 2024011000284 dated 10/01/2024)
- Sh. Naresh Chand Thakran M/s Lavonne Hospitality Private Limited located at Upper Ground Floor, D-16, Defence Colony, New Delhi-110024

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

1	Name & Address of the Building	M/s Lavonne Hospitality Pvt. Ltd, Upper Ground Floor, D-16, Defence Colony, New Delhi-110024 Group-D, "Assembly" (Restaurant at Upper Ground/First Floor)			
2	Type of Occupancy				
3	Building Comprised of	Basement, Stilt, Ground & Three Upper floors.			
4	Type of Case	New			
5	Details of Previous NOC	Nil			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	23/01/2024			
8	Name of the Inspecting Officers	Santosh Kumar (ADO/SJ)			
9	Name & Designation of Officers	Mr. Rakesh Ranjan			
	from the building side	10000			
10	Year of construction	2022 MHA ID No. 2024011000284 dated 10/01/2024			
11	Applicant letter No. MHA ID No.	UBBL/NBC-2016	Provided at Site		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement	Provided at Site	Remarks MR/NMI	
1	Access to Building.	6m	Provided	MR	
	Road width Gate width	4.5m	Abuts on road	MR	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of	- T. C.		1	
	a) Number of Staircase				
	> Upper floors.	2 Nos	Provided	MR	
	➤ Basement floor.	N/A	N/A	N/A	
	b) Width of Staircase			1	
	> Upper floors	1.5m (each)	1.5m (each)	MR	
	➤ Basement floor	N/A	N/A	N/A	
	c) Protection of exits		1011	IVA	
	> Fire check door	N/A	N/A	NI/A	
	> Pressurization	N/A	N/A	N/A	
	d) No. of continuous staircase to terrace	Required	Provided	N/A	
	e) Width of corridor	N/A	TO STATE OF THE PARTY OF THE PA	MR	
	f) Door size	1.5m x 2 Nos	N/A	N/A	
3	Compartmentation.	1.3m x 2 Nos	Provided	MR	
	Fire check door.	N/A	N/A	1577	
	Sealing of electrical shafts.	N/A	3.70	N/A	
	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	ENGINEERS.	N/A	N/A	
	2000 - 200	N/A	N/A	N/A	
4.	- me dunipers.	N/A	N/A	N/A	
70	Smoke Management system. Basement				
	Upper floor	N/A	N/A	N/A	
5.	Fire Extinguishers.	N/A	N/A	N/A	
	Total numbers	Paguina 1	Locat		
	Types	Required ABC/CO ₂ /W.CO ₂	06 Nos	MR	
	ISI Marking	Required		MR	
6.	First Aid Hose Reels.	required	Provided	MR	
	 Total numbers on each floor. 	0==	1	1	
	• Length of hose seed to	One	Provided	MR	
	Length of hose-reel hose. Nozzle Dispute.	30m	Provided	MR	
	Nozzle Diameter	5mm	Provided	MR	



7	Automatic fire detection & alarming s		TATIA	NI/A
	Type of detectors	N/A	N/A	N/A N/A
- 1	 Location of Main Panel 	N/A	N/A	
	 Location of Repeater Panel 	N/A	N/A	N/A N/A
- 1	 Alternate source of power 	N/A	N/A	
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
)	Public Address System	N/A	N/A	N/A
0	Automatic Sprinkler System		Towns	157/4
	Basement	N/A	N/A	N/A
	 Upper floors. 	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
1	Internal Hydrants.			
	 Size of Riser/Down-comer 	100mm	Provided	MR
	 Number of Hydrant per floor 	One	Provided	MR
	Hose box.	One	Provided	MR
2	Yard Hydrants.		***	
	 Total number of hydrants. 	N/A	N/A	N/A
	 Hose box. 	N/A	N/A	N/A
13	Pumping arrangements.			
	Ground Level			
	 Discharge of main pump. 	N/A	N/A	N/A
	> Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.	450 LPM	Provided	MR
	> Head of pump.	40m	Provided	MR
	> Power supply.	Required	Provided	- Sandiero - Ca
	> Auto starting of pump.			MR
		Required	Provided	MR
14	Captive water storage for fire fightin			
	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	➤ Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	20,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	required	Trovided	IVIK
	Pressurization of lift shaft.	N/A	N/A	1277
			N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	 Communication in lift car. 	N/A	N/A	N/A
	 Fireman's switch. 	N/A	N/A	N/A
	 Lift signage. 	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	10 18:30 55:
18	Refuge Area	required	riovided	MR
10		27/4	Tarr	
	Total area Location	N/A	N/A	N/A
	Location	N/A	N/A	

9	Fire Control Room.			LAMA
	Detector system panel. Flow switch panel.	N/A	N/A	N/A
		N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	 PA system panel. 	N/A	N/A	N/A
	 Battery backup. 			N/A
	 Building floor plan. 	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	I IVA

The Fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection.

In view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, issuance of fire safety certificate, under rule 35 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

10+0

Name: Santosh Kumar Designation: ADO (SJ)

of site vicited on 1817.

at is meeting with the require