

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI-110001**

No.F.6/DFS/MS/EH/2024/SZ/ 49

Dated..14./02/2024

**FIRE SAFETY CERTIFICATE**

Certified that the Eating House in the name & style of **M/s Home** located at 3<sup>rd</sup> Floor, Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070 in the building comprised of 03 tier Basement, Ground plus Three upper floors owned/occupied by A unit of PVR Limited was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/SZ/2021/104 dated 20/04/2021. The restaurant premise was re-inspected by the officer concerned of this department on 07/02/2024 in the presence of Mr. Dhruve (Manager) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building" (Restaurant at Third Floor only)** and **validity upto 31/03/2027** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 14 / 02 / 2024 at New Delhi by

**ATUL GARG**  
**DIRECTOR**  
**DELHI FIRE SERVICE**

Copy to: -

1. The Dy. Health Officer, Public Health Department, MCD, Green Park, Delhi-110016 (Ref. MHA Portal ID 2024011600507 dated 31/01/2024)

**Conditions for the validity of Fire Safety Certificate: -**

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The basement shall be used as per the provisions of UBBL /NBC Part- IV.
5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

M19

## INSPECTION REPORT

INSPECTION REPORT				
1	Name & Address of the Building	M/s Home (A unit of PVR Limited) at 3 <sup>rd</sup> Floor, Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070		
2	Type of Occupancy	Assembly Building –D (Restaurant)		
3	Building Comprised of	Three tier Basement, Ground + 03 upper floors (Restaurant running at 3 <sup>rd</sup> Floor)		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/EH/SZ/2021/104 dated 20/04/2021		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	07/02/2024		
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Dhruve		
10	Year of construction	2008		
11	Applicant letter No.	MHA Portal ID 2024011600507 dated 31/01/2024		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR
1	Access to Building. FSC No.F.6/DFS/MS/Mall/2023/SZ/35 Dated 25/01/2023 of Ambience Mall			
	• Road width	9m	Provided *	MR
	• Gate width	5m	Provided *	MR
	• Width of internal road	6m	Provided *	MR
2	Number, width, type and arrangements of exits.			
	a. Number of Staircase	Provided & Maintained by Ambience Mall		
	• Upper floors	02 Nos	17 Provided *	MR
	• Basement floor	02 Nos	Provided *	MR
	b. Width of Staircase	Provided & Maintained by Ambience Mall		
	• Upper floors	1.50 mtr	Provided *	MR
	• Basement floor	Required	Provided *	MR
	c. Protection of exits	Provided & Maintained by Ambience Mall		
	• Fire check door	Required	Provided *	MR
	• Pressurization	Required	Provided *	MR
	d. No. of continuous staircase to terrace	Required	Provided *	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	Required	1.50 mtr	MR
3	Compartmentation.	Provided & Maintained by Ambience Mall		
	• Fire check door.	Required	Provided *	MR
	• Sealing of electrical shafts.	Required	Provided *	MR
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4.	Smoke Management system.	Provided & Maintained by Ambience Mall		
	• Basement	Required	Provided *	MR
	• Upper floors	Required	Exhaust fans provided	MR
5.	Fire Extinguishers.			
	• Total numbers	06 Nos	12 Nos.	MR
	• Types	ISI marked	ABC-04, W.CO <sub>2</sub> -02	MR
	• ISI Marking		Provided	MR
6.	First Aid Hose Reels.	Provided & Maintained by Ambience Mall		
	• Total numbers on each floor.	Hose Reel	01 near restaurant	MR
	• Length of hose-reel hose.		30m	MR
	• Nozzle Diameter		5mm	MR
7	Automatic Fire Detection and Alarming system. (Provided & Maintained by Ambience Mall)			
	• Type of detectors	Required	Smoke & Heat	MR

2/20

	<ul style="list-style-type: none"> <li>Location of Main Panel</li> <li>Location of Repeater Panel</li> <li>Alternate source of power</li> <li>Hooter's location</li> </ul>	Required	Provided *	MR
		N/A	N/A	N/A
		Required	Provided *	MR
		Required	Provided *	MR
8.	MOEFA	Required	Provided *	MR
9.	Public Address System	Required	Provided *	MR
10.	Automatic Sprinkler System	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> <li>Basement</li> </ul>	Required	Provided *	MR
	<ul style="list-style-type: none"> <li>Upper floors</li> </ul>	Required	Provided *	MR
	<ul style="list-style-type: none"> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A
11.	Internal Hydrants.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> <li>Size of Riser/Down-comer</li> </ul>	Required	Provided *	MR
	<ul style="list-style-type: none"> <li>Number of Hydrant per floor</li> </ul>	Required	Provided *	MR
	<ul style="list-style-type: none"> <li>Hose box.</li> </ul>	Required	Provided *	MR
12.	Yard Hydrants.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> <li>Total number of hydrants.</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>2. Hose box.</li> </ul>	N/A	N/A	N/A
13.	Pumping arrangements.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> <li>Ground Level</li> </ul>	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> <li>➤ Discharge of main pump.</li> </ul>	4500 LPM	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Head of main pump.</li> </ul>	70 mtr	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Number of main pumps.</li> </ul>	Two	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Jockey Pump output.</li> </ul>	450 LPM	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Jockey Pump head.</li> </ul>	70 mtr	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Standby Pump output.</li> </ul>	4500 LPM	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Standby Pump head.</li> </ul>	70 mtr	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Auto Starting / Manual Stopping.</li> </ul>	Required	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Access to pump house</li> </ul>	Required	Provided *	MR
	<ul style="list-style-type: none"> <li>Terrace Level</li> </ul>	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> <li>➤ Discharge of pump.</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>➤ Head of pump.</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>➤ Power supply.</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>➤ Auto starting of pump.</li> </ul>	N/A	N/A	N/A
14.	Captive water storage for Fire Fighting.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> <li>Underground tank capacity.</li> </ul>	5,00,000 Ltrs	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Draw-off connection.</li> </ul>	Required	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Fire Service Inlet.</li> </ul>	Required	Provided *	MR
	<ul style="list-style-type: none"> <li>➤ Access to tank.</li> </ul>	Required	Provided *	MR
	<ul style="list-style-type: none"> <li>Overhead tank capacity.</li> </ul>	20,000 Ltrs	Provided *	MR
15.	Exit Signage.	Required	Provided *	MR
16.	Provision of Lifts.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> <li>Pressurization of lift shaft.</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>Pressurization of lift lobby.</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>Communication in lift car.</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>Fireman's switch.</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>Lift signage.</li> </ul>	N/A	N/A	N/A
17.	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> <li>Total area</li> </ul>	N/A	N/A	N/A
	<ul style="list-style-type: none"> <li>Location</li> </ul>	N/A	N/A	N/A
19.	Fire Control Room.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> <li>Detector System Panel.</li> </ul>	N/A	Provided *	N/A
	<ul style="list-style-type: none"> <li>Flow Switch Panel.</li> </ul>	N/A	Provided *	N/A
	<ul style="list-style-type: none"> <li>PA system Panel.</li> </ul>	N/A	Provided *	N/A

1/21

	• Battery backup	N/A	Provided *	N/A
	• Building floor plan	N/A	Provided *	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	Provided *	N/A

Note- Fire safety arrangement provided and maintained by Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/SZ/2021/104 dated 20/04/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer  
Name: Sh. Manoj Kumar Sharma  
Design: DO (South)

Signature of the Inspecting Officer  
Name: Sh. Rajesh Kumar  
Design: ADO (BCP)

CFO (HQ)

*Handwritten signatures and dates:*  
12/21/2021  
Director  
13/2/21  
13/2/21  
13/2/21

As approved, F-1 letter is put up for your signature OI

*Handwritten signatures and dates:*  
Director  
13/2/21  
13/2/21  
13/2/21

1/14  
14/2

Unrecorded  
13/2/21

*Handwritten mark*