## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001 Dated: 12./67/2024

No.F6/DFS/MS/6H/NDZ/2024/24

#### FIRE SAFETY CERTIFICATE

Certified that the M/S Hotel IMPERIAL VIEW located at 2289-2291, Chuna Mandi, Pahar Ganj, New Delhi comprised of Basement + Stilt +Ground + 03 Upper floors (total 24 Guest rooms), basement for storage, Stilt -parking, Ground to 3rd floor (06 guest rooms at each Floor), was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2021/56 dated 01/02/2021 for 24 guest room up to third floor only. Now, the premises was re-inspected by the officer concerned of this department on 06.02.2024 in the presence of Manager and found that the said guest house building has complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, (Sub Division-A-1) basement for storage, Stilt - parking, Ground to 3rd floor (06 guest rooms at each Floor), total 24 guest rooms up to third floor only, and valid up to 31.03.2027 from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued...12 02 24.at New Delhi by.

DIRECTOR Delhi Fire Service

### Copy to:-

1. The Commissioner, MCD, Civic Center, New Delhi. : kindly to ensure the occupancy and deviation in construction if any.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID no.

2024012300734 dated 23/01/2024.

3. The Manager, M/S Hotel IMPERIAL VIEW 2289-2291, Chuna Mandi, Pahar Ganj, New Delhi.

# Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 2. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction, use of occupancy, height of building, electric installation, set back area etc. shall be checked & verified by the concerned authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an

The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

9. Any flammable material for interior decoration is prohibited.

#### NIT INSPECTION REPORT

1. Name & address of the building: M/S Hotel Imperial VIEW, 2289-2291

Chuna Mandi Pahar Ganj, New Delhi.

2. Type of occupancy:-Residential, Sub Division-A-1

B+ Stilt +Gr. + 03 Upper floors (total 24 Guest rooms), basement for storage, Stilt -parking & reception, Ground to 3rd floor (06 guest rooms at

each floor)

Type of case:-Renewal

4. Details of previous FSC:-No.F6/DFS/MS/GH/NDZ/2021/56 dated 01/02/2021

5. Fire safety directives No.-

N/A

6. Date of inspection:-

06/02/2024

7. Name of the inspecting officer:-

Sh. Ravinder Singh

8. Name & designation of officer From the building side:-

9. Year of construction:-

Manager 2020

10. Applicant's letter No:-

ID No. 2024012300734 dated 23/01/2024.

Old Case Minimum Standards on fire as per previous Provided at site Remarks Prevention and fire safety inspection report MR/NMR U/R 33 1. Access to Building 1) Road width 06 15 mtr MR 2) Gate width N/A N/A N/A 3) Width of internal road N/A N/A N/A Number, Width Type & Arrangement of Exits 2. A. Number of staircases 1. Upper floors 02 Nos. 02 Nos. MR 2. Basements 02 Nos. 03 Nos. B. Width of staircase N/A 1. Upper floors 1.5mtr. 1.5 m each 2. Basements MR 1.5mtr. C. Protection of exits 1.5 m each MR 1. Fire check door Required in Provided MR basement 2. Pressurization N/A N/A D. No. of continuous N/A 02 02 staircase to terrace MR E. Width of corridor 1.5m F. Door size (Room) 1.5m MR 1.0 meter 3. 1.0 meter Compartmentation MR 1) Fire check door N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers N/A N/A N/A 4. Smoke Management System N/A N/A 1) Basements 12 ACPH Exhaust fan 2) Upper floors MR 12 a/c per Exhaust ducting MR hour

5.	Fire Extinguishers			1	
	1) Total numbers	12 Nos.	14 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
,	3) ISI marking	Required	Provided	MR	
6.	First-Aid Hose Reel				
	1) Total number at each floor	01	01 /	MR	
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR	
7	3) Nozzle diameter	05 mm	05 mm /	MR	
7.	Automatic Fire Detection & Alarming System				
	1) Type of detectors CO	Required	Provided	MR	
	2) Location of main panel	Ground floor	Provided	MR	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	Required	Provided	MR	
0	5) Hooter's Location	At each floor	Provided	MR	
8.	MOEFA	N/A	Provided	N/A	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System	Not part			
	1) Basement (less than 200 sqm)	N/A	Provided	N/A	
	2) Upper floors	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants				
	1) Size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A	N/A	
V	3) Hose box	N/A	N/A	N/A	
12.	Yard Hydrants				
	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement		-1		
	Ground level	N/A	N/A	N/A	
	a) Discharge of main pump	N/A	N/A	N/A	
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump		N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual stopping	N/A	N/A	N/A	
	2) Terrace level				
	a) Discharge of pump	450 LPM	2x450 LPM	MR	
	b) Head of pump	30 mtr.	30 mtr. /	MR	
	c) Power supply	Required	Provided	MR	
	d) Auto starting of pump	Required	Provided	MR	

14.	Captive Water Storage for Fire Fighting					
. 64	Under ground tank     capacity	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank cap.	5000 ltr.	5,000 ltr.	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.		1			
	a) Pressurization of lift shaft	N/A	N/A	N/A		
	<ul> <li>b) Pressurization of lift lobby</li> </ul>	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection Syste Risk, if any: fire extinguisher	MR				

The fire protection systems provided in the building were randomly tested, checked and same found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. No.F6/DFS/MS/GH/NDZ/2021/56 dated 01/02/2021, under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Rayinder Singh Designation: - ADO (CC)

Picto (205)

Kin o Joshu

7.0 - Mudi

24/1/18

Anne