## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI -110001

No: F6/DFS/MS/WZ/Hospital/2024/ 101

Dated:

161 02 12024

## FIRE SAFETY CERTIFICATE

Certified that the Maharaja Agrasen Hospital, located at Punjabi Bagh, New Delhi – 110026 comprised of Basement + Ground + 06 Upper Floors owned/occupied by Maharaja Agrasen Hospital was issued NOC vide Letter no. F6/DFS/MS/2021/WZ/Hospital/92 dated 04/02/2021. The premises was re inspected by the officer concerned of this department on 02/02/2024 in the presence of Ms. Poonam Ittan and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with the requirements under rule 33 of the Delhi Fire Service Rule 2010 and the building/premises is fit for Class-C (Institutional) occupancy with effect. I 6 0.2 2024 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

Issued on . 16 02 2024 at New Delhi.

Copy to:-

1. The Medical Director, Maharaja Agrasen Hospital Bagh, New Delhi 110026.

Conditions for the validity of Fire Safety Certificate: -

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The Basement shall be used as per building bye laws.
- The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

MAN

INSPECTION REPORT

		-					
1.	Name	& address of the building	Maharaja Agrasen Hospital, Located at Punjabi Bagh, New Delhi-110026.				
2.	Type o	of Occupancy	Institutional (Hospital)				
3.	Type	of Case	Renewal				
_		ager w server con	E6/DES/MS/2021/WZ/Hospital/02 dated 04/02/2021				
4.				DFS/MS/2021/WZ/Hospital/92 dated 04/02/2021 DFS/MS/Hospital/91/2182 dated 31/12/91			
5.					1/2182 dated 31/12/91		
6.	Date of inspection 02/03			/02/2024			
7.				Sarabjeet Singh ADO (MN)			
8.	Name and designation of M officers from the building side		Ms. P	Ms. Poonam Ittan			
9.	Year of	Construction	1991-	92			
10	. Applic	ant's letter No.	Email	dated: 17/11/2023	3		
he S	Said Ho	spital is Comprised of Basvide letter No. F6/DFS/MS	sement	+ Ground + 06 i	upper floors was issued lated 04/02/2021.	d FSC by this	
		nimum Standards on fire		BBL /NBC	Provided at site	Remarks	
lo.	preve	ntion and fire safety U/R 3	33	Requirement		MR/NMR	
	Access	s to building			D. 201.1	X/D	
		Road width		12Mtr	Provided .	MR	
	•	Gate width		5 Mtr	Provided	MR MR	
	•	Width of internal road		6 Mtr	Provided	IVIK	
	Number, Width, Type & Arrangemen			nt of Exits			
	3500 No. 1202 N	Number of staircases		2	2	MR	
		Upper Floors			3 & 1 ramp	MR	
	Basements     Width of staircases			3 & 1 ramp	3 & 1 Tamp	IVIK	
	b. W10	Upper Floors		2Mtr	1.78cm, 175cm	MR (Being old case)	
		Basements		1.5Mtr	142cm, 152cm, 120cm & 5Mtr ramp	MR (Being old case)	
	c. Protection of exits						
		Fire check door		Required	Provided	MR	
	•	Pressurization		NR 02	NR 03	NR MR	
	e. No. of continuous staircases to terrace		errace	03			
	f. Width of Corridor			2.4Mtr	2.2Mtr	MR(Being old case)	
				1.5Mtr	1.5Mtr	MR(Being	
	g. Doo	or Size		2000 C		old case)	
	Comp	artmentation.					
		Fire check door     Sealing of electrical shafts		Required	Provided	MR	
				Required	Provided	MR	
		Fire Rating of shaft door		Required	Provided	MR	
	1	Water Curtain		NR Provinced	NR Provided	NR MR	
		Fire Dampers		Required	Provided	WIK	
	Smoke Management System.						
		Basements		Required	Provided	MR	
	I VIII	Upper floors		Required	Provided	MR	
		Opper moors					
5	1	1					
5	1	Extinguishers Total numbers		50 nos.	Provided	MR	
5	1	Extinguishers		50 nos.		MR MR	

Sey.

	7	173				
6	First-Aid Hose Reels.			MR		
	<ul> <li>Total numbers on each floor</li> </ul>	03	·03 each floor	100000		
	<ul> <li>Length of hose reel hose</li> </ul>	30 m required	Provided	MR		
	Nozzle diameter	5 mm required	Provided	MR		
7	Automatic fire detection and alarmin					
	Type of detectors	Smoke & Heat	Provided	MR		
	Location of Main Panel	G.floor	Provided	MR		
	Location of Repeater Panel	Required	Provided	MR		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Required	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.	1,725.8	*******			
	Basement	T 6		N/D		
	Upper Floor	Required NA (as per DFS guidel	Provided Inc) NA	MR NA		
		Required	Provided	MR		
11	Sprinkler above false ceiling     Internal Hydrants	- sequirou	Flovided	IVIIX		
****				40.		
	Size of riser/down-comer	150 mm	Provided	MR		
	Number of hydrants per floor	03	03 Provided	MR		
12	Hose Box	03	03 Provided	MR		
12	Yard Hydrants.					
	<ul> <li>Total number of hydrants</li> </ul>	05	05	MR		
	Hose Box	05	05	MR		
13	Pumping Arrangements.					
	Ground Level			E.		
	Discharge of main Pump	2400 LPM	2400 LPM			
	Head of Main pump	80 mtrs	80 mtrs	MR		
	Number of main pumps	02	02	MR		
	Jockey Pump out put	180 LPM	Provided	MR		
	Jockey pump head	80 mtr	80 mtr	MR		
	Standby Pump out put	2400 LPM	2400 LPM	MR		
	Standby Pump Head	80 mtr	80 mtr	MR		
	Auto Starting/ Manual stopping	Required	Provided	MR MR		
	➤ Pump House Access	Required	Provided			
	Terrace level	4)1		MR		
	Discharge of pump	Not Required	NR			
	Head of the pump	Not Required	NR	NR		
	Power Supply	Not Required	NR	NR		
	Auto Starting of pump	Not Required	NR	NR NR		
14	Captive Water Storage for fire fighting	ıg.		INK		
	Underground tank capacity	2,00,000 litres	2,00,000 litres			
	> Draw-off connection	NA	NA NA	MR		
	> Fire service inlet	Required	Provided	NA		
	> Access to tank	Required	2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	MR		
	Overhead Tank capacity	50, 000 litres	Provided 50, 000 litres	MR		
5	Exit Signage.	Required	Provided	MR		
S.ITX			riovided	MR		

Kes

6	Provision of Lifts.						
/	Pressurization of Lift Shaft	Required	Provided	MR			
	<ul> <li>Pressurization of Lift lobby</li> </ul>	NR	NR	NR			
	Communication In lift Car	Required	Provided	MR			
	Fireman's Grounding Switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
7	Standby power supply	Required	Provided	MR			
17 18	Refuge Area.						
	> Total Area	Required	Provided	MR			
	> Location	3 <sup>rd</sup> & 4 <sup>th</sup> floor (As per previous NOC)	Provided	MR			
19	Fire Control Room						
	Detector System Panel	Required	Provided	MR			
	Flow Switch Panel	Required	Provided	MR			
	PA System Panel	Required	Provided	MR			
	Batter backup	Required	Provided	MR			
	Building Floor Plans	Required	Provided	MR			
20	Special Fire Protection Systems for Protection of special Risks, if any:	Co <sub>2</sub> flooding system installed for LT panel	NR I	NR			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/2021/WZ/Hospital/92 dated 04/02/2021, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

XO/MN 12/2024 Qy ch (m/2)

Signature of the Inspecting Officer

Name: - Sarabjeet Singh Designation: - ADO (MN)

yeto WZ

lo Winds

ecter CM

£7 P15

put up F. T

16/3/2024

ADO(MN)

XIN, F. T is

put up

for Jour