C115

FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI


No. F6/DFS/MS/Hospital/2024/SZ/ 86

Dated: |2/02/2024

FIRE SAFETY CERTIFICATE

Certified that the building of M/s Medeor Hospital, Located at Pocket-B, Sector-12, Phase-1, Dwarka - 110075, New Delhi in a building comprised of Two Basement + Ground + 05 Upper Floors owned/occupied by Medeor Hospital was issued FSC vide Letter No. F6/DFS/MS/2021/118, dated 12/02/2021. The premises was re inspected by the team of officers concerned of this department on 01/02/2024 in the presence of Dr. Ram and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Institutional building" Group C with effect from 12 | 02 | 2024 | for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 12 .6.2. 2.02.9... at New Delhi by.



Copy to: -

- The Authorized Signatory, M/s Medeor Hospital, Located at Pocket-B, Sector-12, Phase-1, Dwarka - 110075.
- 2. The, Directorate General of Health Service F-17, Arjun Gali Karkardooma Anand Vihar, New Delhi-110032.

Following fire safety directives must be adhered to:-

- 1. The lift is operating to common area shall be run from Ground Floor to upper Floors.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- Basement shall be used as per building bye laws.
- The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expired.

. INSPECTION REPORT

 Name & address of the building: Medeor Hospital, HAF Pocket-B, located at Sector-12, Phase-1, Dwarka, New Delhi.

2. Type of Occupancy:

Institutional C-1 (Hospital)

3. Type of Case : Re

: Renewal (2 Basement + Ground + 05 Upper Floors)

Details of previous NOC

: F6/DFS/MS/2021/118, dated 12/02/2021

5. Fire Safety directives L.No. :F6/DFS/MS /BP/Hospital/2009/3289 Dated 06/11/09

Date of inspection

: 01/02/2024

7. Name of the Inspecting Officer: DO/SW & ADO (DWK)

8. Name and designation of Officer

from the building side

: Dr. Ram

9. Year of Construction

: 2010-2011

10. Applicant's letter No.

: DFS Outdoor diary no. 11672 dated 09/01/2024

S	10. Applicant's letter No. Minimum standards on fire prevention and fire safety U/		Requi N/14,	rement N/15 &	ts as per & N/16	Provided site	at	Remarks MR/NMR	
No 1.	Road width Gate width Width of internal road Of m			ntr Direct accessible from to 6n			oad MR MR MR(Old case)		
2.	Number, width, Type & Arr	angem	ents of e	exits					
	a. Number of staircases Upper floors Basements Width of staircases Upper floors Basements Protection of exits Fire check door Pressurization No of continuous staircase to terrace Width Of Corridor f. Door Size	02 No 02 No 2 M e 1.40, Requi 02 No	2 Nos 2 Nos M each 2m & railin 40, 2.02 m Pro equired equired 2 Nos. 06-240 & 300cms		Provided Provided 02 Nos. Provided rame) & 142 cm at		MF MF MF	MR MR Old case) MR Old case) MR MR MR MR MR MR MR (Old case) MR(Old case)	
3.	Compartmentation ,			1	Provi	ded	MI	R	
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 			uired uired	Provid		MI		
				02 Hours Provi		YIUCU		MR	
				NA			NA NA		
				uired	Provided		MR		
4.	Smoke managements System			/c cha	rge F	rovided	-	MR	
	Basements Upper floors			30 a/c charge 12 a/c charge		Provided		MR	

N/30

4		tinguishers		, -		<u> </u>		Provided	MR
		Total numbers		6 nos. E			,	Provided	MR
		Types		ABC ,C		e wc	02	Provided	MR
		IS marking		ISI marl	ked			Provided	
		Aid Hose Reels				122	•		MR
		Total numbers on each f		2 Nos	100		Vos.		MR ·
	•	Length of hose reel hose	,	30 m	_	30 m			MR
		Nozzle diameter		5 mm	- 2	mm			IVAL
7.	Autom	atic fire detection and ala	arming						MR
1.0		Type of detectors		Heat/S	mok		rovide		MR
	•	Location of Main Panel		Requir		_		ment 1	NR
		Location of Repeater Pa	nel	Each F	111111111111111111111111111111111111111		rovide		MR
		Alternate source of pow		Requir	red	75.00	rovide		MR
	- 4	Hooters' Location		Appro Places		e I	Provid	ed	
8.	MOEF	PA I	Requi	ired	Pr	ovided			MR
9.			Requi		Pr	ovided	7		MR
•	1 done	Traditos of storm							
10.	Autor	natic Sprinkler System							I M
	•	Basements		Requir		Provi			MR
~		Upper Floor/		Requir	red	Provi			MR
	1 6	Sprinkler above false ce	iling	Requi	red	Provi	ded		MR
11.	Intern	al Hydrants:							1.00
• • • •		Size of riser/down-com	er	150	mm		ovided		MR
		Number of hydrants per		02 N	los.		rovide		MR
		Hose Box		02 N	los.	Pr	ovideo	i	MR
12.	Vard 1	Hydrants		. V					
12.	Ture.	Total number of hydran	ts	04 N	los	Provi	ded		MR
	5	Hose Box		Requ	uired	P	rovide	d	MR
	()	Hose Box						A	
13.	Pump	ing Arrangements:		- 107	10				
		Ground Level		E					
		Discharge of main pum	р [2280 lpi	n	Provi	ded		MR
	>			80 m		Provi	ded		MR
	>	Number of main pumps	-	02		Provi	ded		MR
	>	Jockey pump out put		180 lpm		Provi	ded		MR
	>	그 첫 사라이라 회사가 크라다		40 m		Provi	ded		MR
	>	Standby Pump out put		2280 lpr	n	Provi	ded		MR
	>			80 m	W.	Provi	ded		MR
F 2	>	 Auto Staring/Manual stopping 		Require	d	Provi	ded		MR
	>	Pump House Access		Required Provided				MR	
		Terrace level	7	redano	-	11011	uvu		IVIK
	>	Discharge of pump	-	900 lpm		Provi	ded		LAM
		Head of the pump	-	30 m		Provi			MR
ì		Power supply	}	Require	d	Provi	19,0,0,000	-	MR
	>	Auto starting of pump		Require		Provi			MR
14	. Capti	ve water Storage for fire f	ightin		4	FIOVI	uea		MR
	•	Under ground tank capacity		kh ltr.		Provi	ded		MR
	A		Requ	red	-	D	1.1		State
	À				-	Provi			MR
-11	Á	13	Requi		_	Provi			MR
		Overhead Tank	Regir	ed) litres	_	Provi		1 1/1	MR
		~ TOLLICAL LAUK	21 H H H	LITTOR		Provi	A COLUMN		MR

JO W

it Signage Req		ired	Provided	MR	
Provision of Lifts Pressurization of Lift Shaft Pressurization of lift lobby		Required	Provided	MR	
		Required	Provided	MR	
> Communication in lift Car > Fireman's Grounding	Required	Provided	MR		
	Required	Provided	MR		
	34	Required Provided		MR	
* **		Required	DG set 380 & 250 KVA	MR	
\$tandby power supply			A		
Refuge Area	_	NA	NA	NA	
> Total area > Location			NA	NA	
Fire control room		Required	Provided	MR	
 Detector system panel Flow Switch Panel PA System Panel 	NA	NA	NA		
	Required	Provided	MR		
		Provided	MR		
> Battery backup	_	Required	Provided	MR	
> Building Floor Plan	S	Required	Provided	MR	
Special Fire Protection Sys Protection of special Risks	tems for s, if any;	Required	FIOVICE	*******	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the FSC issued vide letter no. 6/DFS/MS/2021/118, dated 12/02/2021 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Sign of Inspecting Officer

Name: Vedpal

Designation: DO/SW

Sign of Inspecting Officer Name: Udai vir Singh

Designation: ADO/DWK