



No. F6/DFS/MS/NDZ/C.C/2024/ 10

Dated: 20 / 02 / 2024

FIRE SAFETY CERTIFICATE

Certified that the BYJU "S Tuition Centre located at ZB-487/11, Main GT Road, Dilshad Garden, Shahdara, Delhi-110095 running at second floor comprised building of Basement, Ground plus three upper floors only, owned/occupied by BYJU "S Tuition Centre have complied with the Fire Prevention and Fire Safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 07/02/2024 in the presence of Mr. Rajender kumar (Manager) and that the building /premises is fit for occupancy class "Educational" (Group-B) with effect from 20 / 02 / 2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued 20/02/2024 at New Delhi by.

(ATEL GARG)
DIRECTOR
o/c DELHI FIRE SERVICE
@

Copy to: -

1. The Manager, BYJU "S Tuition Centre located at ZB-487/11, Main GT Road, Dilshad Garden, Shahdara, Delhi-110095.

Condition for the validity of fire safety certificate

1. Fire Safety Certificate is valid for Second floor only.
2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
4. The trained fire fighting staff should be available round the clock.
5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
9. Basement shall be used strictly as per Building By-Laws 1983.
10. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

212

INSPECTION REPORT

1	Name & address of the building	BYJU "S Tuition Centre located at 2 nd floor, ZB-487/11, Main GT Road, Dilshad Garden, Shahdara, Delhi-110095.
2	Building is comprised of	Basement + ground + 03 upper floors only. (Coaching class running is second floor only)
3	Type of occupancy	Educational Building (Coaching Classes)
4	Type of case	New Case
5	Details of previous FSC	Nil
6	Fire safety directives letter no.	NBC Part IV
7	Date of inspection	07.02.2024
8	Name of the inspecting officers	Yashwant Singh Meena ADO (L.N)
9	Name of the designation of officer from the building side	Mr. Rajender (Manager)
10	Year of construction	2004
11	Applicant's letter no.	Outdoor dairy No. 11187 dated 26.12.2023

S.No	Minimum standard of fire prevention and fire safety U/R 33	NBC Part IV Requirement	Provided at site	Remarks MR/NMR
------	--	-------------------------	------------------	----------------

1	Access to Building:			
	A	Road width	6.0 mtrs.	On Main Road MR
	B	Gate width	N/A	On Main Road N/A
	C	Width of internal road	N/A	N/A N/A

2	Number, Width, Type and Arrangement of Exits:			
	A	Number of staircases		
	a	Upper floor	02 nos.	02 nos. ✓ MR
	b	Basement	02 nos.	02 nos. ✓ MR
	B	Width of staircases		
	a	Upper floor	1.50 mtrs. & 1.25 mtrs.	1.50 mtrs. & 1.25 mtrs. ✓ MR
	b	Basement	(4.0 mtrs. Ramp) & 1.25 mtrs.	(4.0 mtrs. Ramp) & 1.25 mtrs. ✓ MR
	C	Protection of exits	NA	N/A N/A
	a	Fire check door	N/A	N/A N/A
	b	Pressurization	N/A	N/A N/A
	D	No. of continuous staircases to terrace	01 no.	01 nos. MR
	E	Width of corridor	Required	Provided MR
	F	Door size	1.50 mtrs ✓	1.50 mtrs. x 02 ✓ MR

3	Compartmentation:			
	A	Fire check door	N/A	N/A N/A
	B	Sealing of electrical shafts	NA	NA NA
	C	Fire rating of shaft door	N/A	N/A N/A
	D	Water curtain	N/A	N/A N/A
	E	Fire dampers	N/A	N/A N/A

4	Smoke Management System:			
	A	Basement	Required	Provided (Exhaust Fan) MR
	B	Upper floor	Required	Natural Ventilation MR

W

5. Fire Extinguisher:				
A	Total numbers	06 nos.	06 nos.	MR
B	Types	ABC& CO ₂	ABC& CO ₂	MR
C	ISI marking	ISI Marked	ISI Marked	MR
6 First-Aid-Hose Reel:				
A	Total numbers each floor	01 no.	01 no.	MR
B	Length of hose reel hose	30 mtrs	30 mtrs	MR
C	Nozzle diameter	5 mm	5 mm	MR
7 Automatic Fire Detection and Alarming System:				
A	Type of detectors	Smoke	Provided	N/A
B	Location of main panel	Ground floor	Provided	N/A
C	Location of repeater panel	N/A	N/A	N/A
D	Alternate source of power	N/A	N/A	N/A
E	Hooters	N/A	N/A	N/A
8	MOEFA:	Required	Provided	MR
9	Public Address System:	N/A	N/A	N/A
10 Automatic Sprinkler System:				
A	Basement	Required	Provided	MR
B	Upper floor	Required	Provided	MR
C	Sprinkler above false ceiling	N/A	N/A	N/A
11 Internal Hydrants:				
A	Size of riser/down-comer	100 mm	100 mm	MR
B	Number of hydrants per floor	01 no.	01 no.	MR
C	Hose box	01 no.	01 no.	MR
12 Yard Hydrants:				
A	Total number of hydrants	N/A	N/A	N/A
B	Hose box	N/A	N/A	N/A
13 Pumping Arrangements:				
1 Ground level				
A	Discharge of main pump	N/A	N/A	N/A
B	Head of main pump	N/A	N/A	N/A
C	Number of main pumps	N/A	N/A	N/A
D	Jockey pump out put	N/A	N/A	N/A
E	Jockey pump head	N/A	N/A	N/A
F	Standby pump out put	N/A	N/A	N/A
G	Standby pump head	N/A	N/A	N/A
H	Auto starting /manual stopping	N/A	N/A	N/A
I	Pump house access	N/A	N/A	N/A
2 Terrace Level				
A	Discharge of pump	900 LPM	900 LPM /	MR
B	Head of the pump	40 M	40 M /	MR
C	Power supply	Required	Provided	MR
D	Auto starting of pump	Required	Provided	MR


(u)

50/

14 Captive Water Storage for Fire Fighting:				
A	Underground tank capacity	N/A	N/A	N/A
B	Draw-off connection	N/A	N/A	N/A
C	Fire service inlet	Required	Provided	MR
D	Access to tank	Required	Provided	MR
E	Overhead tank capacity	25,000 ltrs. ✓	25,000 ltrs. ✓	MR
15 Exit Signage:		Required	Provided	MR
16 Provision of Lifts:				
A	Pressurization of lift shaft	N/A	N/A	N/A
B	Pressurization of lift lobby	N/A	N/A	N/A
C	Communication in lift car	N/A	N/A	N/A
D	Firemen's grounding switch	N/A	N/A	N/A
E	Lift signage	N/A	N/A	N/A
17 Standby Power Supply:		Required	Provided	MR
18 Refuge Area:				
A	Total area	N/A	N/A	N/A
B	Location	N/A	N/A	N/A
19 Fire Control Room:				
A	Detector system panel	N/A	N/A	N/A
B	Flow switch panel	N/A	N/A	N/A
C	PA system panel	N/A	N/A	N/A
D	Battery backup	N/A	N/A	N/A
E	Building floor plans	N/A	N/A	N/A
20 Special Fire Protection systems for protection of special Risks, if any:		N/A	N/A	N/A

As per direction of FP wing inspection of the building was carried out. The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to grant Fire Safety Certificate under Rules 37 of Delhi Fire Service Rules 2010.


 Signature of the Inspecting Officer
 Name: Yashwant Singh Meena
 Designation: ADO (L.N)

BY.CFO/DZ

C.F.O.

16/21/2024

Director

ADOLN

P.T.O

KT PH

14/02/24

9/2/2024