

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/SZ/2024/FH 55 No.

Dated. 20.. / 02 / 2024

## FIRE SAFETY CERTIFICATE

Certified that the Entertainment & Recreational trade in the name & style of M/s Play House by Essex Situated at 4, Aurobindo Marg, New Delhi 110016 Comprised of two blocks Ground floor only, 1st Block, Lounge & 2nd block, Reception & Play House (Soft Play Area & Parents viewing gallery) Owned/occupied by A unit of Essex Farms (P) Ltd, was issued fire Safety certificate by this department vide letter No F6/DFS/MS/SZ/2021/32 dated 17/02/2021. The said premises was re-inspected by officer concerned of this department on 15/02/2024 in presence of Sh. Manoj Shah of the school and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class Group-D Assembly (Eating House) with effect from 20 / 02 / 2024 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 20 /02 /2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer, MCD, Public Health Department, Aurobindo Marg, Green Park, Delhi 110016

2. M/s Play House by Essex (A unit of Essex Farms (P) Ltd) Situated at 4, Aurobindo Marg, New Delhi 110016.

## Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first Service Rules 2010. www.dfs.delhigovt.nic.in The form is

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to



20	INSPECTIO	N REPORT				
1	Name & Address of the Building	M/s Play House by Essex (A unit of Essex Farms (P) Ltd) Situated at 4, Aurobindo Marg				
2	Type of Occupancy	New Delhi 110016.  Assembly 'Group-D'				
3	Building comprised of	Ground floor only				
4	Type of Case	My HI COLD 4				
5	Details of Previous NOC	Renewal galled safet soods related?   #				
6	The same of the sa	F6/DFS/MS/SZ/2021/32 dated 17/02/2021				
7	Fire Safety Directives Letter No	Nil	Liver wat in the			
	Date of Inspection	15/02/2024				
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)				
9	Name & Designation of Officers from the building side	Sh. Sandeep Anand				
10	Year of construction	2020				
11	Applicant letter No.	DHO/SZ/MCD/2024/D-3558 dated 08/02/2024				
S. No.	Minimum standards on Fire Prevention	Amount in deal a				
1	and Fire Safety U/R 33 Access to Building	NBC/ UBBL 2016	Provided at Site	Remarks MR/NMF		
II.	10 PE 2001   1001   1001	D poem beres	البرائي والإصابات	T		
	Koad width     Gate width	Required	06 m	MR		
581	Width of internal road	NA NA	N/A	N/A		
2	Number, width, type & arrangement of e	xits	N/A	N/A		
7	a. Number of Staircase			5		
	Upper floors	N/A	N/A	1 300		
	Basement floor	-NA-	N/A N/A	N/A		
	b. Width of Staircase		IVA	N/A		
	Upper floors	-NA-	N/A	N/A		
	Basement floor	-NA-	N/A	N/A		
	c. Protection of exits	4	Amon to tweet	IVA		
	Fire check door     Pressurization	-NA-	N/A	N/A		
	d. No. of continuous staircase to terrace	-NA-	N/A	N/A		
	e. Width of corridor	-NA-	N/A	N/A		
	f. Door size	N/A 2 m / 1.50 mtr	N/A	N/A		
3	Compartmentation.	2 m / 1.50 mt	Provided	MR		
-	The state of the s	1	Asian Sources and the			
41	• Fire check door.	-NA-	N/A	N/A		
	Sealing of electrical shafts.     Fire rating of shaft door.	-NA-	N/A	N/A		
	Water curtain	-NA-	N/A	N/A		
	Fire dampers.	-NA-	N/A	N/A		
4	Smoke Management system.	-NA-	N/A	N/A		
		-1100	CONTROL OF THE SECOND PROPERTY.			
	Basement     Upper floors	-NA-	N/A	N/A		
5	Fire Extinguishers.	Required	Natural ventilation	MR		
	Total numbers		Section of Delivery	*		
507	Tynes	Required	10 Nos	MR		
	ISI Marking	ABC / CO2	ABC & Co2	MR		
6	First Aid Hose Reels.	ISI marked	Provided	MR		
hij	Total numbers on each floor.	One	D. C. C.	dam'-		
	Length of hose-reel hose.	30m	Provided	MR		
	Nozzle Diameter	5mm	Provided	MR		
7	Automatic fire detection & alarming system.	J.IIII	Provided	MR		
7.1	Type of detectors	Paguind	Curio no management			
950	Location of Main Panel	Required	Smoke / Heat	MR		
,As	Location of Repeater Panel	Required	Reception at GF	MR		
13.1		-NA-	-NA-	-NA-		
44	Alternate source of power     Hoofer's location	Required	Provided	MR		
	A Hanfanl .	Required				

	2
•	5
۲	r

8	MOEFA	Required	Provided	MR
9	Public Address System			
10	The state of the s	-NA-	-NA-	-NA-
10	Automatic Sprinkler System			
	Basement	-NA-	-NA-	-NA-
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11	Internal Hydrants.		W	
	Size of Riser/Down-comer	Required	Provided	MR
	Number of Hydrant per floor	Required	Provided	MR
	Hose box.	Required	Provided	MR
12	Yard Hydrants.		Manual Page 8	amile T
	Total number of hydrants.	-NA-	-NA-	-NA-
	100	-NA-	-NA-	-NA-
4.4	Hose box.	-NA-	-NA-	-NA-
13	Pumping arrangements.	Transfer Was	Top device and	
2017	Ground Level		AL Hill enhanced	Ship.
	Discharge of main pump.	900 LPM	900 LPM	MR
	> Head of main pump.	28 mtr	28 mtr	MR
	➤ Number of main pumps.	One	one	MR
	➢ Jockey Pump output.	180 LPM	180 LPM	MR
	> Jockey Pump head.	28 M	28 mtr	MR
	Standby Pump output.	-NA-	-NA-	-NA-
	<ul> <li>Standby Pump head.</li> <li>Auto Starting / Manual Stopping.</li> </ul>	-NA-	-NA-	-NA-
	> Pump House Access	-NA-	-NA-	-NA-
	Terrace Level		Lorent Sensi	
	➤ Discharge of pump.	-NA-	-NA-	-NA-
	Head of pump.	-NA-	-NA-	-NA-
	➤ Power supply.	-NA-	-NA-	-NA-
11	<ul> <li>Auto starting of pump.</li> <li>Captive water storage for Fire Fighting.</li> </ul>	-NA-	-NA- u	-
14		-NA-	-NA-	-NA-
	Underground tank capacity.	-NA-	-NA-	-NA-
	<ul> <li>Draw-off connection.</li> <li>Fire Service Inlet.</li> </ul>	-NA-	-NA-	-NA-
	> Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	20,000 Ltr	20,000 Ltr	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	(2)	EINE DAY	
5000 P	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
	Fireman's switch.     Lift signage.	-NA-	-NA-	-NA-
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area		de Namil Sil	
345 	Total area	-NA-	-NA-	-NA
	Location	-NA-	-NA-	-NA
19	Fire Control Room.		The glate white W	
11.000	Detector System Panel.	-NA-	-NA-	-NA
		-NA-	-NA-	-NA
	Flow Switch Panel.	-NA-	-NA-	-NA
	PA system Panel.	-NA-	-NA-	-NA
				<ul> <li>SANTONIO</li> </ul>
	Battery backup     Building floor plan	-NA-	-NA-	-NA



The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/SZ/2021/32 dated 17/02/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Of

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)