

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

No. F6/DFS/MS/School/NDZ/2024/ 118

Dated: 20/02/2024

FIRE SAFETY CERTIFICATE

Certified that the Sarvodaya Kanya Vidyalaya, located at Anand Vihar, Delhi - 110092, now comprised of Ground plus three upper floors only for which Fire Safety Certificate was issued by this department vide letter No. F6/DFS/MS/School/2019/NDZ/973 dated 09/05/2019, have complied with fire prevention & fire safety requirements in accordance with 33 of the Delhi Fire Service Rules, 2010/ NBC Part -IV and verified by the officer concerned of Fire Service on 08/02/2024 in presence of Mrs. Alka Gogia (Principal) and that the building /premises is fit for occupancy class "Educational" (Group-B) with effect from 20/02/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DPS rule 2010.

Issued on 2002 2024 at New Delhi by.

Copy to:-

1. The Dy. Director of Education, D-Block Anand Vihar, Delhi-110092.

2. The Principal, Sarvodaya Bal Vidyalaya, located at Anand Vihar, Delhi-110092.

3. The Principal, Sarvodaya Kanya Vidyalaya, located at Anand Vihar, Delhi - 110092.

Conditions for the validity of Fire Safety Certificate

- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub 1. rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, 5. occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction 6. unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

N	2	A
1-1	-	-0

	INSPECTION REPORT					
1	Na	me & address of the building	Sarvodaya Ka Delhi-110092.	nya Vidyalaya, An	and Vihar	
2	Bu	ilding is comprised of	03 Block (A Block G+3, B-Block G+1, C-Block Ground floors) Educational Building Renewal			
3	Ту	pe of occupancy				
4	Ту	pe of case ·				
5	Details of previous FSC Fire safety directives letter no.		F6/DFS/MS/School/2019/NDZ/973 dated 09/05/2019 NBC Part IV			
5						
7	Date of inspection 08/02/2024					
	NEW YEAR OLD THE STATE OF THE S					
9	Na	me of the inspecting officers me of the designation of officer m the building side	Yashwant Singh Meena, ADO (L.N) Mrs. Alka Gogia (Principal)			
10	Year of construction		1989 &2005			
			Email dated-19/12/2023			
11 S.N 0	Mi	plicant's letter no. nimum standard of fire evention and fire safety U/R 33	NBC Part IV Requirement	Provided at site	Remarks MR/NMR	
1	Ac	cess to Building:	100	*		
	A	Road width	6.0 mtrs.	6.0 mtrs. /	MR	
1	В	Gate width	N/A	N/A	N/A	
- 1	C	Width of internal road	N/A	N/A	N/A	
	A	Number of staircases a Upper floor	02 nos.	02 nos.	MR	
		c Basement	N/A	N/A	N/A	
+	В	Width of staircases				
		a Upper floor	1.50 mtrs.	1.50 mtrs each	MR	
		b Basement	N/A	N/A	N/A	
1	C	Protection of exits		27/4	N/A	
1		a Fire check door	N/A	N/A		
		b Pressurization	N/A	N/A	N/A MR	
	D	No. of continuous staircases to	02 nos.	02 nos.	IVIK	
	E	Width of corridor	1.50 mtrs.	1.50 mtrs.	MR	
	F	Door size	1.0 mtrs.	1.0 mtrs.	MR	
+	Compartmentation:					
+	A	Fire check door	NA	NA	NA	
	В	Sealing of electrical shafts	N/A	N/A	N/A	
	C	Fire rating of shaft door	N/A	N/A	N/A	
	D	Water curtain	N/A	N/A	N/A	
	E	Fire dampers	N/A	N/A	N/A	
4	Sn	oke Management System:				
4 1			N/A	N/A	N/A	
+	A	Basement		N/A	N/A	

N/24 Fire Extinguisher: 5. 40 Nos. MR 38 Nos. Total numbers CO₂ & ABC MR CO₂ & ABC B Types MR ISI Marked ISI Marked ISI marking C First-Aid-Hose Reel: 6 MR 02 nos. Total numbers of each floor (G+3) 02 nos. MR 30 mtrs. Length of hose reel hose 30 mtrs. B MR 05 mm 05 mm Nozzle diameter C Automatic Fire Detection and Alarming System: 7 N/A N/A N/A Type of detectors N/A N/A N/A Location of main panel B N/A N/A N/A Location of repeater panel C N/A N/A N/A Alternate source of power D N/A N/A N/A Hooters E N/A N/A N/A MOEFA: 8 N/A N/A N/A Public Address System: 9 Automatic Sprinkler System: 10 N/A N/A N/A Basement N/A N/A N/A Upper floor B N/A N/A N/A Sprinkler above false ceiling N/A N/A Internal Hydrants: 11 N/A N/A N/A Size of riser/down-comer N/A N/A N/A Number of hydrants per floor B N/A N/A N/A Hose box Yard Hydrants: 12 N/A N/A N/A Total number of hydrants A N/A N/A N/A Hose box B **Pumping Arrangements:** 13 Ground level N/A N/A N/A Discharge of main pump A

N/A N/A N/A Head of main pump B N/A N/A N/A Number of main pumps C N/A N/A N/A Jockey pump out put D N/A N/A N/A Jockey pump head E N/A N/A N/A Standby pump out put F N/A N/A N/A Standby pump head G N/A N/A N/A Auto starting /manual stopping H N/A N/A N/A Pump house access Terrace Level 450 LPM MR 450 LPM Discharge of pump A 40 mtrs MR 40 mtrs Head of the pump B MR Required Provided Power supply C MR Provided / Required Auto starting of pump Sarvodaya Kanya Vidyalaya, Anand Vihar, Delhi-110092

4	Capt	tive Water Storage for Fire Fighting:				
	A	Underground tank capacity	N/A	N/A	N/A	
1	В	Draw-off connection	N/A	N/A	N/A	
ł	c	Fire service inlet	N/A	N/A	N/A	
1	D	Access to tank	N/A	N/A	N/A	
	E	Overhead tank capacity	10,000 ltr.	10,000 ltr.	MR	
15		Signage:	Required	Provided	MR	
16	Provision of Lifts:					
10	A	Pressurization of lift shaft	N/A	N/A	N/A	
	B	Pressurization of lift lobby	N/A	N/A	N/A	
	\rightarrow	Communication in lift car	N/A	N/A	N/A	
	C		N/A	N/A	N/A	
	D	Firemen's grounding switch	N/A	N/A	N/A	
	E	Lift signage and by Power Supply:	N/A	N/A	N/A	
17						
18	Re	fuge Area:	N/A	N/A	N/A	
	A	Total area	N/A	N/A	N/A	
	В	Location	N/A	IN/A		
19	Fi	Fire Control Room: N/A N/A N/A				
	A	Detector system panel	N/A	N/A N/A	N/A	
	В		N/A		N/A	
	C		N/A	N/A	N/A	
	D		N/A	N/A	N/A	
	E	THE CO. LEWIS CO.	N/A	N/A	N/A	
2	20 Special Fire Protection systems for protection of special Risks, if any:		N/A	N/A	IN/F	

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The shortcomings issued vide letter no. F6/DFS/MS/School/2022/NDZ/560 dated 12/09/2022 by this department have been rectified by the management.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no. NBC Part IV, the FSC issued vide letter no. F6/DFS/MS/School/2019/NDZ/973 dated 09/05/2019 is recommended to be renewed.

Signature of the Inspecting Officer
Name Yashwant Singh Meena
Designation ADO (L.N)

DY.CFØ/NDZ

16 21 2024

Dinestoky / 19

BONTON

Letter is Autup for Sign. Alea

Discust 9/178

16/2/2024