

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F6/DFS/MS/2024/School/142

Dated: 27/02/2024

FIRE SAFETY CERTIFICATE

Certified that the Bright Star Model School, located at 154,41 feet Road, Uttaranchal Enclave, Kamal Pur, Burari, Delhi-110084 comprised of Ground & 02 upper floors owned/ occupied by Bright Star Model School was issued Fire Safety Certificated vide this office letter no. F6/DFS/MS/2021/WZ/School/118 dated 15.02.2021. The premise was inspected by the officer concerned of this department on 19.02.2024 in the presence of Mr. Rajesh Chauhan (Manager) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Educational "Group B" with effect from ... 27/02/2024.. for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on . 27/02 2024 at New Delhi

Ph.-011-23414000

Copy to: -

The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

2. The Principal, Bright Star Model School, located at 154,41 feet Road, Uttaranchal Enclave, Kamal Pur, Burari, Delhi-110084

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

The owner / occupier shall submit a declaration every year in Form "K" provided in the first Delhi Fire Service Rules 2010. The form http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its N 21

INSPECTION REPORT

Name & address of the building

: Bright Star Model School at 154,41 feet Road, Uttaranchal Enclave, Kamal

Burari, Delhil 10084.

2. Type of Occupancy

: Educational

Type of Case 3.

: Renewal

Composition of building

: Ground & 02 Upper floors

5. Details of previous NOC

: F6/DFS/MS/2021/WZ/School/118 dated 15.02.2021

6. Fire Safety directives letter No

: NBC Part-4

7. Date of inspection

: 19.02.2024

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Sh. Rajesh Chauhan (Manager)

10. Year of Construction

: 2008

02 2024 & DES Dairy No 12857 dated 08.02.2024

A	Minim	um Standards on fire prevention and fire safety U/R 33	NBC Part-IV Requirements	Provided at site	Remarks MR/NMR		
k	Access	o building					
	•	Road width	06m	06m	MR		
	•	Gate width	Directly Accessible	Directly accessible	MR		
	•	Width of internal road	NA	NA	NA		
2	Number, Width, Type & Arrangement of Exits						
	a. Numb	er of staircases					
		Upper Floors	02	02	MR		
		Basements	NA	NA	NA		
	b. Width	of staircases	9				
		Upper Floors	1.50m	1.55m & 1.10m	MR(old case)		
		Basements	NA	NA	NA -		
	- 1						
	1 4	tion of exits	NA	NΛ	NΛ		
		Fire check door	NA NA	NA NA	NA NA		
	•	Pressurization	1874		3323		
	d. No.	f continuous staircases to terrace	01	01	MR		
	e. Width	of Corridor	1.50m	2m	MR		
	f. Door	Size	1 m	l m	MR		
3	Compa	tmentation.					
		Fire check door	NA	NA	NA		
		Sealing of electrical shafts	NA	NΛ	· NA		
	•	Fire Rating of shaft door	NA	NA	NA		
		Water Curtain	NA	NA	NA		
	* 1	Fire Dampers	NA	NA	NA		
4	Smoke Management System.						
	•	Basements	NA	NA NA	NΛ		
	•	Upper floors	Required	Natural Ventilation	MR		
5	Fire	Extinguishers	•	-1			
	•	Total numbers	08nos	10nos	MR		
		Types	ABC/Co2	ABC-10	MR		
	•	ISI marking	ISI Marked	Yes	MR		
6	First-A	d Hose Reels.	-				

	Total numbers on each floor	01	01 each floor			
	Length of hose reel hose	30m	30m	MR		
	Nozzle diameter	5mm	5mm	MR		
•	Automatic fire detection and alarming system.	T NA				
	Type of detectors	NA NA	NA NA	NA		
	Location of Main Panel		NA .	NA		
	 Location of Repeater Panel 	NA	NA	NA		
	Alternate source of power	NA	NA	NA		
	Hooters' Location	NA NA	NA [NA		
	MOEFA	NA	NA	NA		
	Public Address System.	NA	NA	NA		
0	Automatic Sprinkler System.					
	Basement	NA NA	NA NA	NA NA		
	Upper Floor	NA NA	NA NA	NA NA		
	Sprinkler above false ceiling	NA NA	INA	INA		
11	Internal Hydrants	37		NA		
	Size of riser/down-comer	NA	NA NA	NA NA		
	Number of hydrants per floor	NA _	NA NA	NA NA		
	Hose Box	NA	NA	NA		
12	Yard Hydrants.	T 314 T	NA I	NA		
	Total number of hydrants	NA		NA		
	Hose Box	NA	NA	INA		
13	Pumping Arrangements.					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	> Standby Pump out put	N/A	N/A	N/A		
	 Standby Pump Head Auto Starting/ Manual stopping 		N/A	N/A		
	> Auto Starting/ Manual stopping > Pump House Access	N/A	N/A N/A	N/A		
	Terrace level	N/A				
	Discharge of pump	450 LPM	450 LPM	MR		
	> Head of the pump	40m	40m NA	MR NA		
	> Power Supply	NA NA	NA NA	NA		
	> Auto Starting of pump	NA	575			
14	Captive Water Storage for fire fighting	NA I	NA			
	Underground tank capacity	NA	NOTE OF THE PERSON OF THE PERS	NA		
	> Draw-off connection	NA NA	NA NA	NA NA		
	> Fire service inlet	NA	NA NA	NA NA		
	> Access to tank	NA		MR		
	Overhead Tank capacity	10,000 LTR	Provided			
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					

1	- 10	ressurization of Lift Shaft	N/A	N/A	N/A		
	-	ressurization of Lift lobby	N/A	N/A	N/A		
-		 Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A		
	1		N/A	N/A	N/A		
			- N/A	N/A	N/A		
i i	Standby	power supply	N/A	N/A	N/A		
IE.	Refuge	luge Area.					
	7	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire Control Room						
	-	Detector System Panel	N/A	N/A	N/A		
	1	Flow Switch Panel	N/A	N/A	N/A		
		PA System Panel Batter backup	N/A	N/A	N/A		
			N/A	N/A	N/A		
	- Isanon	Building Floor Plans	N/A	N/A	N/A		
20	Speci	al Fire Protection Systems for ction of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part 4, the FSC issued vide letter of even no. F6/DFS/MS/2021/WZ/School/118 dated 15.02.2021 renewal under rule 37 of the Delhi Fire Service Rules, 2010.

Dy. Chief Fire Officer (WZ)

Signature of the Inspecting Officer
Name :- C.L. Meena

Designation:- ADO/RN

Son Linder Land

Sincetor Mynn

Anten