



C53

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/2024/School/143

Dated: 27/02/2024

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Senior Secondary School (School I.D. No- 1207116/1207117) located at Burari, Delhi-110084 comprised of 03 blocks- 01 block comprised of ground + 01 upper floors (old building) & 02 new blocks comprised of ground & 03 upper floors owned/ occupied by Govt. Girls Sec. School was issued Fire Safety Certificated vide this office letter no. F6/DFS/MS/2020/WZ/School/528 dated 02.12.2020 the premise was re-inspected by the officer concerned of this department on 19.02.2024 in the presence of Smt. Richa Luthra Gill (Principal) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy class "Group B Educational" with effect from 27/02/2024 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on 27/02/2024..... at New Delhi by

(A. P. Garg)
Director

Ph:-011-23414000

Copy to :-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.
2. The Principal, Govt. Girls Senior Secondary School (School I.D. No- 1207116/1207117) located at Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3 All the staff members must know the correct method of operation of firefighting system.
- 4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <http://delhi.gov.in/wps/wcm/connect/doit/fire/FIRE/Home/Forms>.
- 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : Govt. Girls Sr. Sec. School at Burari, Delhi-110084. (I.D. No- 1207116/1201717)
2. Type of Occupancy : Educational
3. Type of Case : Renewal Case
4. Composition of building : 03 blocks- 01 block- G+01 floors (Old building) &
02 block- G + 03 upper floors each (New building)
5. Details of previous NOC : F6/DFS/MS/2020/WZ/School/528 Dated: 02.12.2020
6. Fire Safety directives letter No : Nil
7. Date of inspection : 19.02.2024
8. Name of the Inspecting Officers : ADO (RN)
9. Name and designation of officers
from the building side : Smt. Richa Luthra Gill (Principal)
10. Year of Construction : --
11. Applicant's letter No. : Online E-Mail I.D dated: 01.02.2024

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part-IV Requirements	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	Accessible	Accessible	MR
	• Gate width	Accessible	Accessible	MR
	• Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	Block-I, 01 s/c Block-II, 02 s/c	Block-I, 01 s/c Block-II, 02 s/c	MR
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	1.50m	Block-I- (G+1)- 1.50m Block-II (G+3)- 02 nos. of 1.80m each blocks	MR
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	01	Provided	MR
	e. Width of Corridor	Required	Provided	MR
	f. Door Size	01m	1.10m	MR
3	Compartmentation.			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	• Basements	Required	Provided	MR
	• Upper floors	NA	NA	NA
5	Fire Extinguishers			
	• Total numbers	50nos	60nos	MR
	• Types	ABC/Co2	ABC-40/Co2-20	MR
	• ISI marking	ISI Marked	Provided	MR
6	First-Aid Hose Reels. (New Block- G+03 each)			

	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	03	Provided		
		30m	Provided		
		5mm	Provided		MR
7	Automatic fire detection and alarming system.				
	• Type of detectors	NA	NA		NA
	• Location of Main Panel	NA	NA		NA
	• Location of Repeater Panel	NA	NA		NA
	• Alternate source of power	NA	NA		NA
	• Hooters' Location	NA	NA		NA
8	MOEFA	NA	NA		NA
9	Public Address System.				
10	Automatic Sprinkler System.				
	• Basement	NA	NA		NA
	• Upper Floor	NA	NA		NA
	• Sprinkler above false ceiling	NA	NA		NA
11	Internal Hydrants				
	• Size of riser/down-comer	NA	Provided		NA
	• Number of hydrants per floor	NA	Provided		NA
	• Hose Box	NA	01		NA
12	Yard Hydrants.				
	• Total number of hydrants	NA	NA		NA
	• Hose Box	NA	NA		NA
13	Pumping Arrangements. (New Block- G+03 each)				
	• Ground Level				
	➤ Discharge of main Pump	N/A	N/A		N/A
	➤ Head of Main pump	N/A	N/A		N/A
	➤ Number of main pumps	N/A	N/A		N/A
	➤ Jockey Pump out put	NA	NA		NA
	➤ Jockey pump head	NA	NA		NA
	➤ Standby Pump out put	N/A	N/A		N/A
	➤ Standby Pump Head	N/A	N/A		N/A
	➤ Auto Starting/ Manual stopping	N/A	N/A		N/A
	➤ Pump House Access	N/A	N/A		N/A
	• Terrace level				
	➤ Discharge of pump	450 LPM	450 LPM at 02nos. of each block		MR
	➤ Head of the pump	40m	40m		MR
	➤ Power Supply	Required	Provided		MR
	➤ Auto Starting of pump	Required	Provided		MR
14	Captive Water Storage for firefighting. (New Block- G+03 each)				
	• Underground tank capacity	NA	NA		NA
	➤ Draw-off connection	NA	NA		NA
	➤ Fire service inlet	NA	NA		NA
	➤ Access to tank	NA	NA		NA
	• Overhead Tank capacity	10,000 LTR	Provided each block		MR
15	Exit Signage.	Required	Provided		MR

16	Provision of Lifts.			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/2023/School/523 dated 31.10.2023.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, the FSC issued vide letter of even no. F6/DFS/MS/2020/WZ/School/528 dated 02.12.2020 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

Signature of the Inspecting Officer
 Name :- C.L. Meena
 Designation:- ADO/RN

Dy. Chief Fire Officer (WZ)

ACFOI.....611
 Dated.....20/12/2024

20/12
 Cfo
 21/12/2024
 Director
 21/12/24
 ADO/RN