

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELHI- 110001

र्गाजादी _व आज़ादी _व अमृत महोत्सव

No.F6/DFS/MS/Metro/NDZ/2024/132

Dated: 05/03/2024

FIRE SAFETY CERTIFICATE

Certified that the PD Area located at ground and first floor at Station Box at Dilshad Garden Metro Station, Delhi-110095 owned/occupied by Delhi Metro Rail Corporation was issued Fire Safety Certificate vide letter No. F6/DFS/MS/2021/NDZ/203 dated 05/04/2021. The building was re-inspected by the officer concerned of this department on 27/02//2024 in presence of Mr. Fatehveer Singh (State Manager) and found that the Metro Station (PD Area) have deemed complied with fire prevention and fire safety requirement in accordance with the rule 33 of Delhi Fire Service Rules 2010 and verified by team of officer form this department on 27.02.2024 in the presence of Mr. Fatehveer Singh (State Manager) and observed that building are fit occupancy "Class - D" "Assembly / Mercantile Building" with effect from 05/03/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the condition under rule 38 of the Delhi Fire Service rule 2010. Subject to condition printed overleaf.

Issued on 05/03/2624 at New Delhi by.

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

- Delhi Metro Rail Corporation Ltd., Metro Bhawan, Fire Brigade Lane, Barakhamba Road, New Delhi-110001.
- Mr. Sunil Kumar Jain, Vice President of Unity Group G-3, Aggarwal Corporate Tower, Plot No. 23, Distt., Centre, Rajindra Place, New Delhi-110008.

Conditions for the validity of Fire Safety Certificate

- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

	_		116	_			
		INSPE	CTION REPORT				
1	Nan	ne & address of the building	PD Area at Stat	tion Box located at 1	Main Dilshao		
			Garden Metro St	tation, Delhi - 11009	5.		
2	Bui	ding is comprised of	Ground and first		1167		
3	Тур	e of occupancy	Business Building (Assembly/Mercantile)				
4	Typ	e of case	Renewal				
5	Det	ails of previous FSC	F6/DFS/MS/2021/NDZ/203 dated 05/04/2021.				
6	Fire	safety directives letter no.	F6/DFS/MS/BP/2017/151 dated 17/04/2017				
7	C. C. Carrier	e of inspection	27.02.2024.				
8		ne of the inspecting officers	5-17-24	Meena ADO (L.N)			
9		ne of the designation of					
, I		cer from the building side	Mi. Patenveer 5	ingh (State Manager)			
10		r of construction	2007 - 2008				
11	67000	olicant's letter no.		100511 . 100 00 0			
11		Minimum standard of fire		o.13351dated 20.02.2	101-101		
S.No			NBC	Provided at	Remarks		
	pr	evention and fire safety U/R	Requirement	site	MR/NMR		
		33					
1		cess to Building:					
	A	Road width	12 mtrs.	18 mtrs. /	MR		
	B	Gate width	N/A	N/A	N/A		
2	C	Width of internal road	06 mtrs.	06 mtrs.	MR		
2	Number, Width, Type and Arrangement of Exits:						
	A	Number of staircases					
		a Upper floor	03 nos.	03 nos.	MR		
	Ļ	c Basement	N/A	N/A	N/A		
	В	Width of staircases					
		a Upper floor	1.50 mtrs.	1.50 mtrs each	MR		
		b Basement	N/A	N/A	N/A		
	C	Protection of exits					
		a Fire check door	Required	Provided	MR		
	_	b Pressurization	Required	Provided	MR		
	D	No. of continuous staircases to terrace	03 nos.	03 nos.	MR		
	E	Width of corridor	2.0 mtrs.	20	-		
	F	Door size	Other area 02 mtrs.	2.0 mtrs. 02 mtrs & 1.50 mtrs./	MR		
1		Character (1945)	Restaurant 02 mtrs	02 mirs & 1.50 mirs./	MR (
3	1000	mpartmentation:		1			
	A	Fire check door	Required	Provided	MR		
	В	Segregation of PD area from	Required	Provided	MR		
	В	Station area (wall/door 02 hrs rating)		7			
	C	Sealing of electrical shafts	Dogwins	Dec. 11.1	1 (7)		
	D	Fire rating of shaft door	Required Required	Provided	MR		
	E	Water curtain	Required	Provided Provided	MR		
	F	Fire dampers		Provided	MR		
	-	The dampers	Kenniren	F 14 147 11 1447 1	NA D		
4	-	oke Management System:	Required	Flovided	MR		
4	-	oke Management System: Basement	N/A	N/A	N/A		

W

N17

PD Area, at Station Box at main Dilshad Garden Metro Station, Delhi.

5.	Fire Extinguisher:						
	A	Total numbers	23 nos.	25 nos.	MR		
	В	Types	CO ₂ & ABC	CO ₂ & ABC	MR		
	C	ISI marking	ISI Marked	Provided	MR		
6	First-Aid-Hose Reel:						
_	A	Total numbers of each	04 nos.	04 nos.	MR		
	A	Branch	04 1103.	(
	В	Length of hose reel hose	30 mtrs.	30 mtrs	MR		
	C	Nozzle diameter	05 mm	05 mm	MR		
7	Automatic Fire Detection and Alarming System:						
1			Smoke	Multi Sensor	MR		
	A	Type of detectors	Concourse	Station (C.R.)	MR		
	В	Location of main panel	Concourse	Concourse			
	C	Location of repeater panel	Main Entry	Each Floor	MR		
		Alternate source of power	Required	Provided	MR		
	D E	Hooters	Required	Provided	MR		
0	_	TANDARA TONIO	Required	Provided	MR		
8	micros.	OEFA:	Required	Provided	MR		
9	1	blic Address System:	Required	Tioyidod	5.007		
10	-	tomatic Sprinkler System:	N/A	N/A	N/A		
	A	Basement	THOSE TO SEC.	N/A N/A	N/A		
	В	Upper floor	N/A	20.74	MR		
	C	Sprinkler above false ceiling	Required	Provided	MIN		
11							
	A	Size of riser/down-comer	150 mm	150 mm (MR		
	В	Number of hydrants per	04 nos.	04 nos. (MR		
		Branch	04	04 nos. /	MR		
	C	Hose box	04 nos.	04 1105.	IVIIC		
12	Yard Hydrants: 14 nos 14 nos MR						
	A	Total number of hydrants	14 nos.	14 nos.	CEMPLETER		
	В	Hose box	14 nos.	14 nos.	MR		
13	Pu	mping Arrangements:					
1	Ground level						
	A	Discharge of main pump	1800 LPM	(Common with Metro Station)	MR		
	_	Head of main numn	70 m	70 m	MR		
	B	Head of main pump	01 no.	01 no. /	MR		
	D D	Number of main pumps Jockey pump out put	225 LPM	225 LPM (Common with/	MR		
		\	70 m	Metro Station)	MR		
	E	Jockey pump head	1800 LPM	1800 LPM /	MR		
	F	Standby pump out put	1000 LFW	(Common with Metro Station)			
	G	Standby pump head	70 m	70 m	MR		
	Н	Auto starting /manual stopping	Required	Provided (MR		
	I	Pump house access	Required	Provided ,	MR		
2	Terrace Level						
-	A	Discharge of pump	N/A	N/A	N/A		
	B	Head of the pump	N/A	N/A	N/A		
	C	Power supply	N/A	N/A	N/A		
	D	Auto starting of pump	N/A	N/A	N/A		

W

φ,

4		tive Water Storage for Fire Fig Underground tank capacity	2, 00,000 liters.	2,00,000 liters	- MR		
	A	Draw-off connection	Required	Provided	MR		
	В	Draw-off conflection	Required	Provided	MR		
	C	Fire service inlet	Required	Provided	MR		
-	D	Access to tank	N/A	N/A	N/A		
	E	Overhead tank capacity	Required	Provided	MR		
15		t Signage:	Requires				
16	Provision of Lifts:			Open glass lift N/A N/A N/A N/A			
	A	Pressurization of lift shaft	N/A		N/A		
	В	Pressurization of lift lobby	N/A	N/A	MR		
	C	Communication in lift car	Required	Provided	MR		
	D	Firemen's grounding switch	Required	Provided	27 0.7 0.1 (1.1)		
	E	Lift signage	Required	Provided	MR		
17		ndby Power Supply:	Required	Provided	MR		
18	Refuge Area:						
ACLAN .		Total area	N/A	N/A	N/A		
	A	Location	N/A	N/A	N/A		
10	_		• 11.5.2	*			
19	-	re Control Room:	Required	Provided	MR		
	A	Detector system panel	Required	Provided	MR		
	B	Flow switch panel	Required	Provided	MR		
	C	PA system panel	Required	Provided	MR		
	D	Battery backup	Required	Provided	MR		
	E	Building floor plans	N/A	N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if any:		N/A	IVA	1411		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Circular no F6/DFS/MS/BP/2017/151 dated 17.04.2017, the FSC issued vide letter no. F6/DFS/MS/2021/NDZ/203 dated 05/04/2021 is recommended to be renewed.

> Signature of the Inspecting Officer Name: -Yashwant Singh Meena

Designation: - ADO (L.N)

Dy. CFO (NDZ)