GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

ग्रिका आज़ादी न अमृत महोत्सव

No.F6/DFS/MS/School/SZ/2024/187

Dated: 08 03 2024

FIRE SAFETY CERTIFICATE

Director

Delhi Fire Service

Copy to:-

- The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.
- The Principal, M/s Children Tinu Public School located at B-5/1185, Sangam Vihar, New Delhi-80.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape shall be kept free of all the type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub Rule (1) of Rule 37] along with a copy of this certificate, six months prior to its expiry.

1	N	ame	& address of the building	M/s Children Tinu Public School located at B-5/1185, Sangam Vihar, New Delhi-80.			
				Ground + 2 upper	floors		
2			ng is comprised of	Ground + 2 upper	n B' (School)		
3		11/27/	of occupancy	Renewal	Educational 'Group B' (School)		
4			of case	Renewal	ol/2021/SZ/80 dated (1.02.2021	
5	D	Type of case Continue			5		
6			afety direction letter no.	02.03.2024	302 300		
7	D	ate o	of inspection	Daisah Kumar Shu	kla, ADO (M. Road)		
8	N	ame	of the inspecting officers	- t to: (Monager)			
9	Name of the designation of officer from the building side			Mr. Ranut Siwas (Manager)			
10	Year of construction			2006	101 01 0004		
11	5.0		cant's letter no.	CTPS/DFS/2024 d	lated 31.01.2024	Remarks	
S.No	Minimum standard of fire			THE STATE OF THE S	Provided at site	MR/NMR	
	1,000		ntion and fire safety U/R	Circular dated			
	33	3		17.01.2005			
			a to Building	1.4.100.000		T v m	
1	_		s to Building: oad width	Required	Accessible	MR.	
	A		ate width	NA	NA	NA	
	B	-	Ctd Cinternal road	NA	NA	NA	
2	Number, Width, Type and Arrangement of Exits:						
4	A	IN	umber of staircases			MR	
	A	а	0	Required	2 nos.	NA	
	-	b	Basement	NA	NA	INA	
	В		idth of staircases	/an 11	0.000	MR	
	D	a	Upper floor	2 nos. (Exits)	0.96 m & 0.90 m	11.40.00000	
		b	Basement	NA	NA	NA	
	C	P	rotection of exits		374	NA	
		a	Fire check door	NA	NA NA	NA	
		ь	Pressurization	NA	2 nos.	MR	
	D	N	o. of continuous	Required	Z nos.	A177	
	-	st	aircases to terrace	NIA	NA	NA	
Ì	E	W	idth of corridor	NA (for	1.0 mtrs (for	MR	
	F	D	oor size	1.0 mtrs. (for class rooms)	class rooms)		
	Compartmentation:						
	A	Fi	re check door	NA	NA	NA NA	
}	B	Se	ealing of electrical shafts	NA	NA	NA NA	
ŀ	C	Fi	re rating of shaft door	NA	NA	NA	
ŀ	D	w	ater curtain	NA	NA	NA	
ŀ	E	Fi	re dampers	NA	NA	1111	
	Smoke Management System:						
	A		sement	NA	NA NA	NA NA	
ŀ	B	1 1 1 1 1 1 1	oper floor	NA	NA	1	
	_		tinguisher:	10-1-1	Tayon or sore	MD	
	A		al numbers	07 nos.	07 nos.	MR	
	_		Section Country and Country an	CO ₂ & ABC	CO ₂ & ABC	MR	
	В	Тур		ISI Marked	Provided	MR	
			marking	101 1111111100			
	Firs	t-A	id-Hose Reel:	T 0.1	0 2 nos.	MR	
	A Total numbers of each floor			01 no.	30 m	MR	
-	В	Ler	gth of hose reel hose	30 m		MR	
			zzle diameter	05 mm	05mm	IVIK	

10 N/10

7	Au	tomatic Fire Detection and A	larming System	.				
	A	Type of detectors	NA	NA	NA			
	В	Location of main panel	NA	NA	NA			
	C	Location of repeater panel	NA	NA	NA			
	D	Alternate source of power	NA	NA	NA			
	E	Hooters	NA	NA	· NA			
8	MC	DEFA:	NA	NA	NA			
9	16900	blic Address System:	NA	NA	NA			
10								
10	A	Basement Systems	NA	NA	NA			
	B	Upper floor	NA	NA	NA			
	C	Sprinkler above false ceiling	NA NA	NA NA	NA			
	1000		NA	INA	INA			
11	Internal Hydrants:							
	A	Size of riser/down-comer	NA	NA	NA			
	B	Number of hydrants per floor	NA	NA	NA			
T. T.	C	Hose box	NA	NA	NA			
12	-	rd Hydrants:						
	A	Total number of hydrants	NA	NA	NA			
	В	Hose box	NA	NA	NA			
13		mping Arrangements:						
A	Ground level							
	a)	Discharge of main pump	NA	NA	NA			
	b)	Head of main pump	NA	NA	NA			
	c)	Number of main pumps	NA	NA	NA			
	d)	Jockey pump out put	NA	NA	NA			
	e)	Jockey pump head	NA	NA	NA			
	n	Standby pump out put	NA	NA	NA			
	g)	Standby pump head	NA	NA	NA			
	h)	Auto starting /manual	NA	NA	NA			
		stopping	1 1 - 1 5 - 51 :	550,550,55				
n.	i)	Pump house access	NA	NA	NA			
В	-	race Level						
	a)	Discharge of pump	220 LPM	Provided	MR			
	p)	Head of the pump	40 mtrs	40 mtrs	MR			
	c)	Power supply	Required	Provided	MR			
	d)	Auto starting of pump	Required	30 mtrs	MR			
14		otive Water Storage for Fire F	ighting:					
	A	Underground tank capacity	NA	NA	NA			
	B	Draw-off connection	NA	NA	NA			
7	C	Fire service inlet	NA	NA	NA			
	D	Access to tank	NA	NA	NA			
15	E	Overhead tank capacity t Signage:	2,500 liters	Provided	MR			
16		vision of Lifts:	Required	Provided	MR			
·	A		Tara					
H	B	Pressurization of lift shaft Pressurization of lift lobby	NA	NA	NA			
	C	Communication in lift car	NA NA	NA	NA			
	D	Firemen's grounding switch	NA NA	NA NA	NÁ			
	E	Lift signage	NA	NA NA	NA			
17	Star	ndby Power Supply:	NA	NA NA	NA NA			
18	Ref	uge Area:			INA			
	A	Total area	NA	NA	NIA			
	B	Location	NA	NA NA	NA NA			

M/s Children Tinu Public School located at B-5/1185, Sangam Vihar, New Delhi-80.

19	Fire Control Room:						
	A Detector system panel		NA	NA	NA		
	В	Flow switch panel	NA	NA	NA		
	C	PA system panel	NA	NA	NA		
	D	Battery backup	NA	NA	NA		
	E	Building floor plans	NA	NA	NA		
20			NA		NA		

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular 262-362 dated-17/01/2005, the FSC issued vide letter no. F.6/DFS/MS/School/2021/SZ/80 dated 01.02.2021 is recommended to be renewed.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

DO (SD)

MIN

Directer

HULL