6-38



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/2024/ 73

Dated: 08/03/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s One8 Restaurant (A Unit of Hill Stone Cafe LLP), Premises No. 21/31, 3rd Floor, Block-H, Mall Road, Delhi-110054 in the building comprised of Basement, Ground & 03 upper floors owned/occupied by M/s One8 Restaurant (A Unit of Hill Stone Cafe LLP) was issued fire safety certificate vide letter no. F6/DFS/MS/2021/EH/WZ/62 dated 10.03.2021. The premises was inspected by the officer concerned of Fire Service on 06.03.2024 in the presence of Mr. Kamal Kr. Gred and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rules 33 of the Delhi Fire Service Rules, 2010 and building premises is fit for occupancy class "Group D Assembly" (Restaurant) at third floor only with effect from Dala 2222 for a period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 0.8.103.120.2.4.... at New Delhi by

Ph-011-234 14000

Copy to:-

 M/s One8 Restaurant (A Unit of Hill Stone Cafe LLP), Premises No. 21/31, 3rd Floor, Block-H, Mall Road, Delhi-110054.

Conditions for the validity of Fire Safety Certificate:

This Fire Safety Certificate is valid for restaurant at third floor for assembly occupancy only. In case
of any violation, this FSC will be treated as null & void.

2. All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangements provided therein shall be maintained in good working condition
at all time as seen during inspection. Any loss of life or property due to non-functional fire safety
measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

: M/s One8 Restaurant (A Unit of Hill Stone Cafe LLP). Premises No. 21-31, 1. Name& address of the building

3rd Floor, Block-H, Mall Road, Delhi-110054.

: Assembly/Restaurant Type of Occupancy

: Basement, Ground & 03 upper floors but restaurant is running at 3rd floor only Composition of building

: Renewal Type of Case

: F6/DFS/MS/2021/EH/WZ/62 dated 10.03.2021 Details of previous NOC

: Nil Fire Safety directives letter No

: 06.03.2024 Date of inspection : ADO (RN) Name of the Inspecting Officers

Name and designation of officers

: Mr. Kamal Kr. Gred from the building side

: 2020 10. Year of Construction

: Online MHA Portal I. D. No- 2024020701308 dated 07.02.2024 11. Applicant's letter No.

Cov	Minin	- 302.86Sqm rum Standards on fire prevention and fire safety U/R 33	UBBL/NBC Part- IV Requirements	Provided at site	Remarks MR/NMR
1	Access to building				
*		Road width	09m	12m approx	MR
		Gate width	NA	NA	NA
	1 -1-	Width of internal road	NA	NA	NA
	Nambo	, Width, Type & Arrangement of Exits	Restaurant at third	floor only	
!					
	15-15-06 T	er of staircases	02	02	MR
		Upper Floors	- NA	02	NΛ
		Basements	The second section with	Haracal Care	
		of staircases	02m &1.50m	02m &1.50m	MR
	1	Upper Floors	NA	02m & 1.50m	NA
		Basements			
		ection of exits	Required	Provided	MR
		Fire check door	NA	NA NA	NΛ
		Pressurization			
		continuous staircases to terrace	NA	lm s	NA NA
		of Corridor	NA	NA	
	f. Door S		2m & 1.50m	2.0m & 1.5m	MR
	Compartmentation. Provided MR				
		Fire check door	Required	Provided NA	NA NA
		Sealing of electrical shafts	NA	NΛ	NA
		Fire Rating of shaft door	NA	aller of the second	
		Water Curtain	NΛ	NΛ	NA
	•	Fire Dampers	NA	NA	NΛ
	Smoke Management System.				
		Basements	NA	NA	NΛ
		Upper floors	Required	Provided	MR
5	Fire Extinguishers				
	•	Total numbers	06nos	08nos	MR
		Types	ABC/Co2	ABC-5 Co2-3	MR

	ISI marking	H8 Yes	Yes	MR		
6	First-Aid Hose Reels.	Section 2		12		
6	Language Goog	01	01	MR		
	Langth of bose real bose	30m	30m	MR		
	Length of hose reel hose Nozzle diameter	5mm	5mm	MR		
	Automatic fire detection and alarming system.					
7	Sanda (Hent Provided					
	Type of detectors	Third floor	Provided	MR		
	Location of Main Panel	NA	NA	NΛ		
	Location of Repeater Panel	Required	Provided	MR		
(6)	Alternate source of power	Third floor	Provided	MR		
	Hooters' Location	Required	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Require				
10	Automatic Sprinkler System.	1440 -1500		NΛ		
	Basement	NA	NA			
	Upper Floor	Required	Provided	MR		
	Sprinkler above false ceiling	, NA	NA	NΛ		
			Armer Land			
11.4	Internal Hydrants		Provided	MR		
	Size of riser/down-comer	100mm 01	Provided	MR		
	Number of hydrants per floor Hose Box	01	Provided	MR		
	111000000000000000000000000000000000000					
12	Yard Hydrants.	NA	NA	NΛ		
	Total number of hydrants		NA NA	NA		
	Hose Box	NA	NA.			
13	Pumping Arrangements.					
	Ground Level		222 1 114	MR		
	➤ Discharge of main Pump	2280 LPM	2280 LPM			
	➤ Head of Main pump	80m	80m	MR N/A		
	> Number of main pumps	N/A	N/A			
	> Jockey Pump out put	180 LPM	180 LPM	MR		
	> Jockey pump head	60m	60m	MR MR		
	Standby Pump out put	2280 LPM (Diesel operative)	2280 LPM (Diesel operative)			
	Standby Pump Head	80m	N/A	N/A		
	> Auto Starting/ Manual stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	, amp near					
	Terrace level			MD		
	> Discharge of pump	450 LPM	Provided	MR		
	➤ Head of the pump	40m	Provided	MR		
	The second second second second second second second	Required	Provided	MR		
	> Power Supply	Required	Provided	MR		
	➤ Auto Starting of pump	Required				
14	Captive Water Storage for fire fighting.					
14	Y 3	100,000 LTR	Provided	MR		
	Underground tank capacity	22 20 20 A 20 A 20 A 20 A 20 A 20 A 20		NA		
	> Draw-off connection	NA	NA	INZ		

		Access to tank	NΛ	NΛ	NΛ	
	>	Overhead Tank capacity	10,000 LTR	Provided	MR	
	•	- Common	Required	Provided	MR	
5	Exit Signage.		One Passenger Lif	η		
5	Provisio	on of Lifts.		N/A		
		Pressurization of Lift Shaft	N/A	N/A		
		Pressurization of Lift lobby	N/A	N/A	N/A	
		Communication In lift Car	Required	Provided	MR	
		Fireman's Grounding Switch	Required	Provided	MR	
	•		Required	Provided	MR	
	•	Lift Signage	Required	Provided	MR	
7	Standb	y power supply	Kedanoo			
3	Refuge Area.				N/A	
	>	Total Area	N/A	N/A	N/A	
	4	Location	N/A	N/A		
9	Fire Control Room					
			N/A	' N/A	N/A	
	•		N/A	N/A	N/A	
	•	NEW TOTAL CONTRACTOR C	N/A	N/A	N/A	
		1 - 2 - 3 - 3 - 4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	N/A	N/A	N/A	
	•	***************************************		N/A	N/A	
		Building Floor Plans	N/A		NA.	
)	Special Protecti	Fire Protection Systems for on of special Risks, if any:	NA	NA .	, NA	

Note: -

1. The total covered area of the ground floor Restaurant is 302.86sqm (Approx.) including scating area, kitchen area, toilet area,

2. As per the NBC Part IV, the number of occupants comes out to be approx. 168person's i.e. (302.86/1.8=168).

The fire protection systems provided in the building were tested/ checked and found in working

condition at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules. It is recommended to renew Fire Safety vide this department letter of even no. F6/DFS/MS/2021/EII/WZ/62 dated. 10.03.2021 Certificate under rule 37(3) of Delhi Fire Service Rules 2010.

Dy. Chie Fire Officer (WZ)

Signature of the Inspecting Name : C.L. Meena

Designation:- ADO/RN