

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/ 76

Dated: 11 / 63 /2024

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Galazio at Khasra No 261, Ground Floor, Block-C, Paryavaran Complex area, New Delhi 110024 comprised of Ground Floor owned/occupied by A Unit of V D Prime Hospitality have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of department on 01/03/2024 in the presence of Mr. Ajay (Accounts) and that the premise is fit for occupancy class Group-D Assembly Building and Validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 381 of the Delhi Fire Service Rules, 2010.

Issued on 11 /03 /2024 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Joint Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal 2024020901414 dated 09/02/2024, 2024021401616 dated 14/02/2024 &2024020701356 dated 08/02/2024)

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

-	INSPECTIO	μ/\ N REPORT	7/5		
1	Name & Address of the Building	M/s Galazio (A Unit of V D Prime Hospitality) at Khasra No 261, Ground Floor, Block-C,			
2	Type of Occupancy	Paryavaran Complex area, New Delhi 110024			
3	Building Comprised of	Restaurant at Ground floor			
4	Type of Case	Ground Floor only New Case			
5	Details of Previous NOC	New Case		4	
6	Fire Safety Directives Letter No	Nil	of the second of		
7	Date of Inspection	01/03/2024	AND REPORT F		
8	Name of the Inspecting Officers		DO (PCP)		
9	Name & Designation of Officers from the building side	DO (South) & ADO (BCP)  Mr. Ajay (Accounts)			
10	Year of construction	2016	Alan contracted	n)	
11	Applicant letter No.	MHA Portal 2024020901414 date 09/02/2024, 2024021401616 dated 14/02/2024 &2024020701356 dated 08/02/2024			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL/ NBC- 2016	Provided at Site	Remarks MR/NMR	
. 1	Access to Building.	HOOF ST WILLIAM	g Throwellings a	1111011111	
	Road width	06 mtr	Provided	MR	
90 "	Gate width	4.5 mtr	Provided	MR	
7	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of ex	ite	notive community and a mark		
	a) Number of Staircase	157	1970 J. Orthonia w		
	> Upper floors.	N/A	N/A	NT/A	
	Basement floor.	N/A	N/A	N/A	
	b) Width of Staircase	IVA	INA	N/A	
20	> Upper floors	N/A	N/A	N/A	
	➤ Basement floor	N/A	N/A	N/A	
(LAV	c) Protection of exits	in head.	nus udbreis 4	IN/A	
	> Fire check door	N/A	N/A	N/A	
	> Pressurization	N/A	N/A	N/A	
ANV	d) No. of continuous staircase to terrace	N/A	N/A	N/A	
	e) Width of corridor	N/A	N/A	N/A	
	f) Door size	1.50 mtr x 2	1.80m & 1.50m	MR	
3	Compartmentation.	71	THE PERSON NAMED IN COLUMN TWO	MIK	
11.07	Fire check door.	N/A	N/A	N/A	
IIV.	Sealing of electrical shafts.	N/A	N/A	N/A N/A	
	Fire rating of shaft door.	N/A	N/A	N/A N/A	
	Water curtain	N/A	N/A	N/A N/A	
	Fire dampers.	N/A	N/A	N/A N/A	
4	Smoke Management system.	IVA(p):	AL WILLIAM	IN/A	
P.L.	Basement	NA	N/A	N/A	
651	Upper floors	12 ACPH	Exhaust fan	MR	
5	Fire Extinguishers.	12	ADA TO BURDO	71 91	
	Total numbers	06 Nos	06 Nos	MR	
7	Types	ABC/CO <sub>2</sub>		MR	
	ISI Marking	ISI marked	ABC- & CO <sub>2</sub>	_	
6	ISI Marking     First Aid Hose Reels.	151 marked	Provided	MR	
0	Total numbers on each floor.	One	Provided	MI	
F	Total numbers on each Hoor.	Olic	Piovided	IVII	



/	The state of the s
आज़ार्द	
अमृत	महोत्सव

Ł

lin e	19( Tax Zilly Till San Jan San		आज़ार्द <sub>का</sub> अमृत महोत्सव	
1	<ul> <li>Length of hose-reel hose.</li> <li>Nozzle Diameter</li> </ul>	30m	Provided	MR
7 A		5mm –	Provided	MR
	Automatic fire detection & alarming system.			
	Type of detectors     Location of Main Panel	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel     Alternote assets	N/A	N/A	N/A
	<ul> <li>Alternate source of power</li> <li>Hooter's location</li> </ul>	N/A	N/A	N/A
8 N	MOEFA	N/A	N/A	N/A
5   6	ublic Address System	Required	Provided	MR
10 A	Automotic Sprink	N/A	N/A	N/A
	Automatic Sprinkler System			
	Basement	- N/A	N/A	N/A
	• Ground/ upper floors.	N/A	N/A	N/A
11 Ti	Sprinkler above false ceiling	N/A	N/A	N/A
AA S	nternal Hydrants.	All	A STATE	1117
KREEN	Size of Riser/Down-comer	Required	Provided	MR
	Number of Hydrant per floor	Required	Provided	MR
-	Hose box.	Required	Provided	MR
12 Y	ard Hydrants.	(#977-5.7 <sup>2</sup> / <sub>2</sub> )	- 1011000	IVIK
-	<ul> <li>Total number of hydrants.</li> </ul>	N/A	N/A	NT/A
Y)	<ul> <li>Hose box.</li> </ul>	N/A	N/A	N/A
13 P	umping arrangements.	Masongoign as	ty and man angentions	N/A
	Ground Level			
W.	Discharge of main pump.	N/A	N/A	NT/A
511	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A N/A	N/A
	Jockey Pump output.	N/A		N/A
	> Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A N/A	N/A	N/A
	Standby Pump head.		N/A	N/A
	Auto Starting/Manual Stopping.  Pump house access	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	W. T. o.	N/A	N/A	N/A
	Terrace Level     Discharge C	30	diena Kerfilaan -	
	<ul> <li>Discharge of pump.</li> <li>Head of pump.</li> </ul>	450 LPM	Provided	MR
	<ul><li>Head of pump.</li><li>Power supply.</li></ul>	40m	Provided	MR
nel l	<ul><li>Auto starting of pump.</li></ul>	Required	Provided	MR
		Required	Provided	MR
14 C	Captive water storage for fire fighting.	PROJECT SINCE	III III	-
	<ul> <li>Underground tank capacity.</li> </ul>	N/A	N/A	N/A
- [	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	
IX.	Overhead tank capacity.	20,000 Ltrs		N/A
15 E	xit Signage.	Required	Provided	MR
	rovision of Lifts.	rodunea	Provided	MR
	<ul> <li>Pressurization of lift shaft.</li> </ul>	XY/A T	urb ii Albayan	j n
	Pressurization of lift lobby.	N/A	N/A	N/A
100	<ul> <li>Communication in lift car.</li> </ul>	N/A	N/A	N/A
	<ul> <li>Fireman's switch.</li> </ul>	N/A	N/A	N/A
	<ul> <li>Lift signage.</li> </ul>	N/A	N/A	N/A
17 S	tandby Power Supply	N/A	N/A	N/A
- DYY	- Company of the control of the cont	Required	Provided	MR



18	Refuge Area			
	Total area	N/A	N/A	N/A
19	• Location	N/A	N/A	N/A
19	Fire Control Room.	/		
	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found

functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)