GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No.F.6/DFS/MS/EH/2024/SZ/74

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s TACO BELL situated at Space -8, T 316/A, 3rd Floor, Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070 in the building comprised of 03 tier Basement, Ground plus Three upper floors owned/occupied by A unit of Burman Hospitality Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/SZ/2021/43 dated 23/02/2021. The restaurant premise was reinspected by the officer concerned of this department on 19/02/2024 in the presence of Ms. Nita (Manager) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant at Third Floor only) and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 11/03/2024 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer, Public Health Department, MCD, Green Park, Delhi-110016 (Ref. MHA Portal ID 2024021201544 dated 12/02/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

The basement shall be used as per the provisions of UBBL /NBC Part- IV. 4.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of

UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

NIM



1	Name & Address Si	ON REPORT				
	Name & Address of the Building	M/s TACO BELL (A unit of Burman Hospitality Pv Ltd) Space -8, T 316/A, 3 rd Floor, Ambience Mall Plot No. 2, Nelson Mandela Marg, Vasant Kunj, Nev Delhi-110070				
2	Type of Occupancy					
3	Building Comprised of	Assembly Building -D (Restaurant)				
	Comprised of	Three tier Basement, Ground + 03 upper floor				
4	Type of Case	(Restaurant running at 3 rd Floor)				
5	Details of Previous NOC	Renewal	Principle Administration	711		
6	Fire Sofety Disasti	F6/DFS/MS/EH/SZ/2021/43 dated 23/02/2021				
7	Fire Safety Directives Letter No Date of Inspection	Nil				
8	Name of the Inspecting Officers	19/02/2024				
9	Name & Designation of Officers	DO (South) & A				
	from the building side	Ms. Nita (Manager)				
10	Year of construction	102() = 0 = 0	(this selfment is			
11		2008				
S. No.	Applicant letter No.	MHA Portal ID	2024021201544 dated 12	2/02/2024		
	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/	Provided at Site	Remarks		
		Existing Fire	CONTRACTOR TO	MR/NMF		
1	Access to Building. FSC No.F.6/DFS/MS/M Road width	Protection				
	Road width	9m	ed 25/01/2023 of Ambienc	e Mall		
	Gate width	5m	Provided *	MR		
	Width of internal road	6m	Provided *	MR		
2	Number, width, type and arrangements of	Fault	Provided *	MR		
	Upper floors	02 Nos	Maintained by Ambian	ice Mall		
	Basement floor		17 Provided *	MR		
	b. Width of Staircase		02 Nos Provided * N Provided & Maintained by Ambiance Ma			
	Upper floors	Provided &	ice Mall			
	Basement floor	1.50 mtr	Provided *	MR		
101	c. Protection of exits	Required	Provided *	MR		
	Fire check door	Provided &	ice Mall			
100	Pressurization	Required	Provided *	MR		
2	d. No. of continuous staircase to terrace	Required	Provided *	MR		
7	e. Width of corridor	Required	Provided *	MR		
ALTYS MITE	f. Door size	N/A	N/A	N/A		
3	Compartmentation.	Required	Open from all side	MR		
	Fire check door.	Provided & Maintained by Ambiance Mall				
58 1		Required	Provided *	MR		
R	Sealing of electrical shafts. Fire points of shaft door.	Required	Provided *	MR		
M	Fire rating of shaft door. Water protein.	N/A	N/A	N/A		
W.	Water curtain	N/A	N/A	N/A		
4	• Fire dampers.	N/A	N/A	N/A		
4.	Smoke Management system.	Provided & Maintained by Ambience Mall				
/	Basement	Required	Provided *	MR		
Tul.	Upper floors	Required	Exhaust fans provided	MR		
5.	Fire Extinguishers.		Alvedorance (T. V			
p	Total numbers	06 Nos	12 Nos.	MR		
064	Types	52. 2	ABC-04, W.CO ₂ -02	MR		
721	ISI Marking	ISI marked	Provided	MR		
6.	First Aid Hose Reels.	Provided & Maintained by Ambience Mall				
- T	Total numbers on each floor. Length of hose-reel hose.	Hose Reel	01 near restaurant	MR		
inde or			30m	MR		
	Nozzle Diameter		5mm	MR		

N/15

	Type of detectors	Required	Smoke & Heat	M	
	Location of Main Panel	Required	Provided *	М	
	Location of Repeater Panel	N/A	N/A	N/	
	Alternate source of power	Required	Provided *	M	
	Hooter's location	Required	Provided *	М	
8.	MOEFA	Required	Provided *	М	
9.	Public Address System	Required	Provided *	М	
10.	Automatic Sprinkler System	Provided & Maintained by Ambience Mall			
	Basement	Required	Provided *	M	
	Upper floors	Required	Provided *	M	
	Sprinkler above false ceiling	N/A	N/A	N/	
11.	Internal Hydrants.		Maintained by Ambie		
	Size of Riser/Down-comer	Required	Provided *	M	
	Number of Hydrant per floor	Required	Provided *	M	
7	Hose box.	Required	Provided *	M	
12.	Yard Hydrants.		Maintained by Ambie		
a ndi	Total number of hydrants.	N/A	N/A	N/	
VINC	2. Hose box.	N/A	N/A	N/A	
13.	Pumping arrangements.	IVA	IVA	14/2	
	Ground Level	Provided & Maintained by Ambience Mall			
	Discharge of main pump.	4500 LPM	Provided *	MI	
	Head of main pump.	70 mtr	Provided *	MI	
	Number of main pumps.	Two	Provided *	MI	
	Jockey Pump output.	450 LPM	Provided *	MI	
	> Jockey Pump head.	70 mtr	Provided *	MI	
	Standby Pump output.	4500 LPM	Provided *	MI	
	> Standby Pump head.	70 mtr	Provided *	MI	
	➤ Auto Starting / Manual Stopping.	Required	Provided *	MI	
	> Access to pump house	Required	Provided *	MI	
	Terrace Level		THE WAY OF THE PARTY.	US2.511.5	
		Provided & Maintained by Ambience Mall N/A N/A N/A			
	 Discharge of pump. Head of pump. 	N/A	N/A	N/A	
	Head of pump.Power supply.	N/A	N/A	N/A	
	Auto starting of pump.	N/A	N/A	N/A	
22/12		Provided & Maintained by Ambience Mall			
14.	Captive water storage for Fire Fighting.	5,00,000 Ltrs	Provided *	MF	
	Underground tank capacity.	Required	Provided *	MF	
	> Draw-off connection.		Provided *	MF	
	> Fire Service Inlet.	Required	Provided *	MF	
2	> Access to tank.	Required	Provided *	MF	
	Overhead tank capacity.	20,000 Ltrs	Provided *	MR	
15.	Exit Signage.	Required	근로(기계 전 기술) 선생님이		
16.	Provision of Lifts.	Provided & Maintained by Ambience Mall			
	 Pressurization of lift shaft. 	N/A	N/A N/A	N/A	
	 Pressurization of lift lobby. 	N/A	N/A N/A	N/A	
	 Communication in lift car. 	N/A	N/A	N/A	
	 Fireman's switch. 	N/A	N/A	N/A	
	Lift signage.	N/A	The state of the s	MR	
17	Standby Power Supply	Required	Provided (DG Set)	MIK	
18.	Refuge Area		27/4	NI/A	
77	Total area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
10	Fire Control Room.	Provided & Maintained by Ambience Mall			
19.	Detector System Panel.	N/A	Provided *	N/A	
	Detector System ranet.		Provided *	N/A	

आज़ादी क अमृत महोत



	PA system Panel. Battery backup	N/A	Provided *	N/A
	Building floor plan	N/A	Provided *	N/A
		N/A	Provided *	N/A
	Special Fire Protection System for the Protection of special Risk, if any:	N/A	Provided *	N/A

Vasant Kunj, New Delhi-110070

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/SZ/2021/43 dated 23/02/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ)

Two files is. dair Restaurant and this file are mistakenly clubbed with another guard file Hence delayed. Careidenatare approach please. Submitted for land careidenatare approach please.

serveta Mary

11/03/24

P