GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/72

Dated. 0.7./03/2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s The Chatter House at FC + S2 + S3, Lower Ground Floor, Epicuria, TDI Mall Nehru place New Delhi 110019 in the building comprised of Basement, Lower Ground & Upper Ground Floor was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/SZ/2021/42 Dated 23/02/2021. The restaurant premise was reinspected by the officer concerned of this department on 26/02/2024 in the presence of Mr. Swadeep Popli and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group-D Assembly Building" (Restaurant at Lower Ground Floor) and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on <u>07</u>/<u>03</u>/2024 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police, Lic Unit, 1st Floor PS Defence Colony, New Delhi 110049. (Ref. MHA Portal ID 2024021401629 dated 14/02/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system

 The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of

UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

NIS

	INSDECT	ION DEDODE	आजादी	FI		
1	Name & Address of the Building	ION REPORT		महोत्सव		
) 1	Tours of Mic Building	M/s The Chatter House at FC + S2 + S3, Low Ground Floor, Epicuria, TDI Mall Nehru place, Ne Delhi 19				
2	Type of Occupancy					
3	Building Comprised of	Group-D Assembly Building, Eating house at UGF only				
4	Type of Case	Basement, Lower ground floor & upper ground floor				
15	Details of Previous NOC	Renewal				
6		F6/DFS/MS/EH/SZ/2021/42 Dated 23/02/2021				
7	Fire Safety Directives Letter No	F6/DFS/MS/2022/SZ/434 dated 29/09/2022 (Mall NOC				
8	Date of Inspection	26/02/2024				
	Name of the Inspecting Officers	DO (South) & ADO (BCP) Mr. Swadeep Popli				
9	Name & Designation of Officers	Mr. Swadeep Popu				
10	from the building side Year of construction	2013				
11	Applicant letter No.	MHA Portal ID 2024021401629 dated 14/02/2024				
11	Applicant letter No.	WITH TOTAL ID 2	101 10101010101010101010101010101010101			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL 2016 Requirements	Provided at Site	Remarks MR/NMR		
1	Access to Building.	ed 29/09/2022				
20.00	Road width	30 mtr	Provided*	MR		
	Gate width	6 mtr	Provided*	MR		
381-5	Width of internal road	6 mtr	LW-Manager	MR		
	Production Internal road	o ma	Provided*	IVIK		
2	Number, width, type & arrangement of ex	its. itsalaj	mm 4 (Chillips Primi			
3814	a) Number of Staircase	Provi	ded & Maintained by	Mall		
30120	> Upper floors.	N/A	Restt. at LGF	N/A		
- 74.1-1	Basement floor.	N/A	N/A	N/A		
154	b) Width of Staircase	Provi	ded & Maintained by	Mall		
ASSE	> Upper floors	N/A	N/A	N/A		
1112	> Basement floor	N/A	N/A	N/A		
4-1	c) Protection of exits	Provided & Maintained by Mall				
	> Fire check door	N/A	N/A	N/A		
REA	> Pressurization	N/A	N/A	N/A		
RIFE	d) No. of continuous staircase to terrace	N/A	N/A	N/A		
10%	e) Width of corridor	N/A	N/A	N/A		
5114	O Dear size	2m	Provided	MR		
27	The sease (the hours)	Provided & Maintained by Mall				
3	Compartmentation.	Required				
	Fire check door.		Provided*	MR		
100	Sealing of electrical shafts.	Required	The state of the s	MR		
YALI	Fire rating of shaft door.	Required	Provided* N/A	N/A		
\$7.1×	Water curtain	N/A	N/A N/A	N/A		
1 3	Fire dampers.	N/A				
4	Smoke Management system.		vided & Maintained by Mall Provided* MR			
Nite	Basement	30 ACPH 12 ACPH	Provided*	MR		
	Upper floors	12 ACFR	1 TOYIGGU	1,414		
5	Fire Extinguishers.		resultant 6			
2.1/	Total numbers	06 Nos	07 Nos	MR		
	Types	ABC/CO ₂	ABC-04 & CO ₂ -03			
	ISI Marking	ISI marked	Provided	MR		
6	First Aid Hose Reels.	Provided & Maintained by Mall				
-21	Total numbers on each floor.	01 No near restt	Provided*	MR		
SIV	Length of hose-reel hose.	30m	Provided*	MR		
8.11	Nozzle Diameter	5mm	Provided*	MR		
. 7.	Automatic fire detection & alarming syste	m. Provided & Ma	intained by Mall	RG NA		
	Type of detectors	N/A	Provided*	MR		
-condV	Location of Main Panel	N/A	Provided*	MR		
	Location of Repeater Panel	Required	Provided*	MR		
	Alternate source of power	Required	Provided*	MR		
	The state of the s		Provided*	MR		
	Hooter's location	Required	Tiovided	MR		

	Public Address System	N/A	N/A	N/A		
	Automatic Sprinkler System	Provid	ded & Maintained by	Mall		
- 19	Basement	Required	MR			
	 Ground floor. 	Required	Provided* Provided*	MR		
	 Sprinkler above false ceiling 	Required	Provided*			
1	Internal Hydrants.			MR		
	Size of Riser/Down-comer	Provided & Maintained by Mall Required Provided* MR				
	Number of Hydrant per floor	Required	Provided*	MR		
	Hose box.		Provided*	MR		
2	Yard Hydrants.	Required	Provided*	MR		
		242				
	Total number of hydrants.	Required	Provided*	MR		
3	Hose box.	Required	Provided*	MR		
3	Pumping arrangements.					
	Ground Level	Provided & Maintained by Mall				
	Discharge of main pump.	2280 LPM	Provided*	MR		
	> Head of main pump.	70 m	Provided*	MR		
	Number of main pumps.	02	Provided*	MR		
	> Jockey Pump output.	280 &180 LPM	Provided*	MR		
	Jockey Pump head.	70 m	Provided*	MR		
	Standby Pump output.	2280 LPM	Provided*	MR		
	Standby Pump head. Auto Starting/Manual Storping	70 m	Provided*	MR		
	i i i i i i i i i i i i i i i i i i i	Required	Provided*	MR		
	amp nouse decess.	Required	Provided*	MR		
	Terrace Level		goli bernadi. s			
	Discharge of pump.	N/A	N/A	N/A		
	> Head of pump.	N/A	N/A	N/A		
	> Power supply.	N/A	N/A	N/A		
	➤ Auto starting of pump.	N/A	N/A	N/A		
14	Trovided & Maintained by Main					
	 Underground tank capacity. 	1,00,000 ltr	Provided*	MR		
	> Draw-off connection.	Required	Provided*	MR		
	Fire Service Inlet.	Required	Provided*	MR		
	Access to tank.	Required	Provided*	MR		
15	Overhead tank capacity. E-it Si	10,000 ltr	Provided*	MR		
15 16	Exit Signage. Provision of Lifts.	Required	Provided	MR		
10		Provided & Maintained by Mall				
	Pressurization of lift shaft.	N/A	N/A	N/A		
N.	Pressurization of lift lobby.	N/A	N/A	N/A		
	Communication in lift car. Figure 2.2 a width	N/A	N/A	N/A		
	• Fireman's switch.	N/A	N/A	N/A		
17	Lift signage. Standby Power Sample.	N/A	N/A	N/A		
18	Standby Power Supply Refuge Area	Required	Provided	MR		
10	Refuge Area					
	Total area	N/A	NI/A	****		
2	Location	N/A	N/A	N/A		
19	Fire Control Room.		N/A	N/A		
Ų.	Detector system panel.	Required	ded & Maintained by			
	Flow switch panel.	Required	Provided*	MR		
	DA custom man 1	Required	Provided*	MR		
	Battery backup.	Required	Provided*	MR		
	Building floor plan.	Required	Provided*	MR		
20	Special Fire Protection System for the	N/A	N/A	N/A		
1-7775	Protection of special Risk, if any.	N/A	N/A	A		

Note: - * Fire Safety arrangements provided & Maintained by TDI MALL, Nehru place Metro Station, New Delhi 110019.



The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/SZ/2021/42 Dated 23/02/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP

approved. F.T. Lettre et putup for en synatur 01 1/4