

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No.F.6/DFS/MS/Hospital/SZ/2024/176

Dated: 18 /03 /2024

## FIRE SAFETY CERTIFICATE

Certified that the Max Super Specialty Hospital, Situated at Plot No 1, Press Enclave Road, Saket, New Delhi-110017, comprised of Two Tier Basement, Ground and Six Upper Floors owned/occupied by Max Super Specialty Hospital was issued FSC by this department vide letter no. F6/MS/DFS/Hospital/SZ/2021/172 dated 15/03/2021. The premise was re-inspected by the officer concerned of this department on 07/03/2024 in the presence of Mr. Arjun Rawat (Fire Officer) and found deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy Group C"Institutional (Hospital)" with effect 18/03/2024 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on... 18.103..../2024 at New Delhi by.

DIRECTOR

**DELHI FIRE SERVICE** 

Copy to:-

 Dr. Pranav Shankar, Max Super Specialty Hospital, Situated at Plot No 1, Press Enclave Road, Saket, New Delhi-110017

 The Executive Engg. (Bldg.), Municipal Corporation of Delhi, 8th Floor, Civic Center, Minto Road, New Delhi

## Conditions for the validity of fire safety certificate:-

1. All the means of escape/entry/exit shall be kept free from any obstruction.

 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

4. All the staff members must know the correct method of operation of firefighting system.

 The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

6. This fire safety certificate may not in any way be treated as regularization of

unauthorized construction, if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



## INSPECTION REPORT

1. Name & address of the building: Max Super Specialty Hospital Plot No 1, Press Enclave Road, Saket Delhi 17

: Institutional "Group-C"

 Type of Occupancy
 Type of Case Renewal [2 Basement, Ground & Six Upper Floors] : F6/MS/DFS/Hospital/SZ/2021/172 dated 15/03/2021 4. Details of Previous NOC

4. Details of frevious Noc.

5. Fire Safety directives letter No : F6/DFS/MS/BP/Hospital/2004/1986 dated 02/09/2004 & even no 465

Dated 23/02/2006

6. Date of inspection

: 07/03/2024

7. Name of Inspecting Officer

8. Name and designation of officer

: DO (South) & ADO (BCP)

10.	Annli	nstruction : 2008-2009 cant's letter No. : outdoor diary no	7519 dated 17/10/2023			
S. No.	Mi	nimum Standards on fire prevention fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR	
	Ac	cess to building		Annah (February		
	-	Road width	9m	Provided	MR	
		Gate width	5m	Provided	MR	
		Width of internal road	6m	Provided	MR	
	Nu	mber, Width, Type & Arrangement of I	Exits	NO LANGE OF STREET		
•	a Number of staircases					
	۵.	Upper Floors	04 No's	Provided	MR	
		Market St. T.	04 Nos	B2 to GF :- 04 Nos	MR	
		Basements	benefits	B1 to GF :- 02 Nos		
	b.	Width of staircases	I have been been	eri Linux ×		
	1860	Rh-effW	02 mtr	Provided	MR	
		Upper Floors		B2 to GF: 2 of 2 m	MD(old Core	
		Parameter Comments	02 mtr	& 2 of 1.5 m	MR(old Case	
		Basements		B1 to GF : Provided		
			rumuri.	Splan X		
	C.	Protection of exits	Required 1999	Provided	MR	
		Fire check door	Required	Provided	MR	
		Pressurization	Required	Provided	MR	
		No. of continuous staircases to terrace	2 m	Provided	MR	
		Width of Corridor	11 1000000	1.7 m & 1.05 m	MR (old Case)	
	f.	Door Size	2m & 1m	1.7 III 60 1.03 III		
j	Co	mpartmentation	0(111111	and with a	MR	
35		Fire check door	Required	Provided	MR	
1374		Sealing of electrical shafts	Required	Provided	MR	
		Fire Rating of shaft door	Required	Provided	MR	
		Water Curtain	Required	Provided	MR	
		Fire Dampers	Required	Provided	IVIIX	
4.	Sm	oke Management System	(K-12-11-1	N 101 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MR	
			30 ACPH	M. V. Provided		
		Basements     Upper floors	12 ACPH	M. V. Provided	IVIK	
5.	Fir	• Festivatish	(6 ym)		MR	
	1	a Tesal month	Required	280 Nos		
		Types	ABC/W. CO <sub>2</sub> /CO <sub>2</sub>	100/100/80 Nos		
		IS marking	ISI marked	Yes	MR	
5.	Fi	st-Aid Hose Reels	1777-13		- i m	
	1		4 Nos	Provided	MR	
		Total numbers on each floor	30m	Provided	MR	
		<ul> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ul>	5mm	Provided	MR	
7.	A	tomatic fire data				
	-	tomatic fire detection and alarming syst	em	Provided	MR	
		Type of detectors	Smoke & Heat	Provided	MR	
	1 1	Location of Main Panel	Basement-1 Security Control Room	Provided	NA	

		14.
	//=	
	आज़ाव अमृ	त महोत्सव
Up	Provided	MR
υþ	Provided	MR
- di	Provided	MR
17	Provided	MR
Ħ	BE SELECTION	is Kilmothial t
r U	Provided	MR
itl	Provided	MR
	Provided	MR
(hd)		delign offeright
	Provided	MR
-	Provided	MR
-	Provided	MR
	Provided	MR
	Provided	MR
-	trata-la de de de de	IVIK
	Language Chromoso	
	Provided	MR
	Provided	· MR
	Provided Provided	MR
	Provided	MR
		MR
	NA	NA
	NA	NA
re-	NA	NA
	NA	NA
	1400	149
	Provided	MR
	Provided Provided	MR
Herry	Provided	MR
	Provided	MR
	Provided	MR
This ?	No. of the last of	MR
	Provided	MR
	Compensated by shaft pressurization (table -6	MR
	NBC 2016)	
	Provided Provided	MR
	Provided	MR
	Provided	MR
	No. of Land	MR
l bio	130 m <sup>2</sup>	
	3rd , 4th , 5th & 6th	MR
	floors	MR (Old Case)
	Provided	
ЛУ	Provided	MR
	14.00	Name -

	• A1	N/39	अमृ	रीका त महोत्सव
ketty)	Alternate source of power     Hooters' I am a series of power	Battery Back Up	Provided	MR
8.	Hooters' Location  MOEFA	All Floors	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic S.	Required	Provided	MR
	Automatic Sprinkler System	Required	Flovided	d printed and
	Basement	Required	Provided	MR
	• Upper Floors • Sprinkler			MR
11.	• Sprinkler above false ceiling	Required	Provided	11 71 574 574
	Internal Hydrants	Required	Provided	MR
	Size of riser/down-comer	150mm	T	100
DAGEN	Number of hydrants per floor     Hose Box	David State State Co.	Provided	MR
12.	Yard Hydrants	4 Nos	Provided	MR
£1 E.V.	• Total	4 1905	Provided	MR
HEA	Total number of hydrants     Hose Box	07 No's	Described	100
13.	Pumping Arrangements	07 No's	Provided	MR
	Ground	77 110 5	Provided	MR
	• Ground Level		tarento la últil	
	Discharge of main Pump	2850 LPM	Perceit 1	100
	riead of Main pump	60m	Provided	MR
	Number of main pumps  Jockey Pump out put	Two	Provided Provided	MR
	Jockey pump head	2 x 180 LPM	Provided	MR
	Standby Pump out put	60m	Provided	MR
2010	Standby Pump Head	2850 LPM	Provided	MR
4 11/10	Auto Starting/Manual Stopping	60m	Provided	MR
	Tump House Access	Required	Provided	MR
	Terrace level	Required	Provided	MR
	Discharge of pump			MR
	Head of the nump	NA	NA	NIA.
	Fower Supply	NA	NA	NA NA
80	rate Statung of pump	NA	NA	NA NA
14.	Captive Water Storage for fire fighting	NA	NA	NA NA
	Underground tank capacity	2.00		INA
- a-	➤ Draw-off connection	2,00,000 Ltrs	Provided	100
X.	Fire service inlet	Required	Provided	MR
174		Required Required	Provided	MR MR
15.	Overhead Tank capacity  Fried:	20,000 Ltrs	Provided	MR
16.	Exit Signage.	Required	Provided	MR
10,	Provision of Lifts.		Provided	MR
341.4	Pressurization of Lift Shaft	Required	D.	
late.	Pressurization of Lift lobby	Required	Provided  Compensated by shaft	MR
	Communication In lift Car	15 care-100	pressurization (table 6	MR
217	Fireman's Grounding Switch	Required	NBC 2016) Provided	
, on	• Lift Signage	Required	Provided	MR
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.	Required	Provided	MR
10.	201 F	novillation w	The state of the s	MR
517	Total Area Location	Required	130 m <sup>2</sup>	
	Location	6 <sup>th</sup> Floor	3rd , 4th , 5th & 6th	MR
19.	Fire Control Room	Marian to Service States	floors	MR (Old Case)
	Detector System Panel	Required	Provided	
-	Flow Switch Panel	Required	Provided	MR
			Dapty	





	PA System Panel	Required	Provided	MR
20.	Batter backup	Required	Provided	MR
	Building Floor Plans	Required	Provided	MR
	Special Fire Protection System for Protection of special Risks, if any:	Required	CO <sub>2</sub> flooding & trace tube system is provided.	MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/MS/DFS/Hospital/SZ/2021/172 dated 15/03/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ)

approved, F.1. letter in protup ba