Dated: 18 /03 /2024



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/School/ 213

## FIRE SAFETY CERTIFICATE

Certified that the Navodaya Public School located at Gali No. 07, B-Block, Amrit Vihar, Burari, Delhi-110084 comprised of Ground floor only owned/occupied by the Navodaya Public School was granted FSC by this department vide letter No F6/DFS/MS/2019/WZ/1764 dated 12.09.2019. The premises was inspected by the officer concerned of this department on 12.03.2024 in the presence of Sh. Balram Sharma (Principal) and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011and the building/ premise is fit for occupancy class "Group B Educational" with effect from ... 18.03 20.24... for a period of three years, subject to compliance of the conditions mentioned below:

Issued on .18/03/2024 at New Delhi

Director :-01/-23414000

## Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Principal, Navodaya Public School located at Gali No. 07, B-Block, Amrit Vihar, Burari, Delhi-110084.

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in./wps/wcm/connect/doit">http://delhi.gov.in./wps/wcm/connect/doit</a> fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building

:Navodaya Public School, Gali No-7, B-Block, Amrit Vihar Burari

Delhi-110084.

2. Type of Occupancy

: Educational

3. Composition of building

: Ground Floor Only

4. Type of Case

: Renewal

5. Details of previous NOC

: F6/DFS/MS/2016/School/WZ/1262 Dated 10.08.2016

6. Fire Safety directives letter No

: Nil

7. Date of inspection

: 12.03.2024

8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side

: Sh. Balram Sharma (Principal)

10. Year of Construction

: 2005-06

11. Applicant's letter No.

		inimum Standards on fire ention and fire safety U/R 33	Requirement as per Rule 35 (6)	Provided at site	Remarks MR/NMR		
	Access	Access to building					
	•	Road width	06m	06m	MR		
	•	Gate width	4.5m	4.5m	MR		
		Width of internal road	NA	NA	NA		
2	Number, Width, Type & Arrangement of Exits						
	a. Numl	er of staircases					
		Upper Floors	NA	NA NA	NA		
	•	Basements	NA	NA	NΛ		
	b. Width of staircases						
	•	Upper Floors	NA	NA	NA		
	•	Basements	NA	NA	NΛ		
	c. Protection of exits						
	•	Fire check door	NΛ	NA	NΛ		
		Pressurization	NΛ	NA	NA		
		f continuous staircases to terrace	NA	NA	NA		
		of Corridor	NA	NA	NA		
	f. Door	Size	01m	01m	MR		
3	Compartmentation.						
	•	Fire check door	NA	NA	NΛ		
		Sealing of electrical shafts	NΛ	NA	NΛ		
		Fire Rating of shaft door	NA	NA	NΛ		
		Water Curtain	NΛ	NA	NΛ		
	•	Fire Dampers	NA	NA	NA NA		
4	Smoke 1	Smoke Management System.					
	•	Basements	NA	NA	NΛ		
	•	Jpper floors	NA	NA	NΛ		

5	Fire Extinguishers.	MID						
	Total numbers	03nos	03nos	MR				
	Types	ABC/CO2	ABC—	3 MR				
	ISI marking	ISI Marked	Yes	MR				
6	First-Aid Hose Reels.							
	Total numbers on each floor	NA	NA NA	NΛ				
	Length of hose reel hose	NA	NA	NA				
	Nozzle diameter	NA	NA	NA				
7	Automatic fire detection and alarming system.							
	Type of detectors	NA	NA	NA				
	Location of Main Panel	NA	NA	NA				
	Location of Repeater Panel	NA	NA	NA				
	Alternate source of power	NA	NA	NA				
	Hooters' Location	NA	NA	NA				
3	MOEFA MOEFA	NA	NA	NA				
)	Public Address System.	NA NA	NA	NA				
0	A de Carlo Dia Canton							
V	Basement	NA NA	NA .	NA				
	Upper Floor	NA	NA	NA				
	Sprinkler above false ceiling	NA	NA	NA				
1	Internal Hydrants.							
11	Size of riser/down-comer	NA	NA	NA				
	Number of hydrants per floor	NA	NA	NA				
	Hose Box	NA	NA	NA				
2	Yard Hydrants.	NA	· NA	NA				
	Total number of hydrants		1200	NA				
	Hose Box	NA	NA	INA				
3	Pumping Arrangements.							
	Ground Level	-						
	Discharge of main Pump	N/A	N/A	N/A				
	Head of Main pump	N/A	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A				
	Jockey Pump out put	N/A	N/A	N/A				
	Jockey pump head	N/A	N/A	N/A				
	Standby Pump out put	N/A	N/A	N/A				
	Standby Pump Head	N/A	N/A	N/A				
	Auto Starting/ Manual stopping	N/A	N/A	N/A				
	Pump House Access	18/74						
	Terrace level	NA	NA.	NA				
	Discharge of pump	NA NA	NA	NA				
	➤ Head of the pump	N/A	NA	N/A				
	> Power Supply	N/A	NA	N/A				
	Auto Starting of pump	IN/A	<b>T</b>	E .				





	•	Inderground tank capacity	NA	NA	NΛ		
	>	Draw-off connection	NA NA	NA NA	NA		
	۶	ire service inlet	NΛ	NA <sub>A</sub>	NA		
	<b>A</b>	Access to tank	NA	NA	NΛ		
	•	Overhead Tank capacity	NΛ	NΛ	NΛ		
15 -	Exit Sig	nage.	N/A	N/A	N/A		
16	Provision of Lifts.						
		Pressurization of Lift Shaft	N/A	M) N/A = 11	· N/A		
		Pressurization of Lift lobby	N/A	N/A	- N/A		
		Communication In lift Car	N/A	N/A	N/A		
		Fireman's Grounding Switch	N/A	N/A	N/A		
		Lift Signage	N/A	N/A	N/A		
17	Standb	power supply	N/A	N/A	N/A		
18	Refuge	uge Area.					
	>	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire Co	Fire Control Room					
		Detector System Panel	N/A	N/A	N/A		
		Flow Switch Panel	N/A	N/A	N/A		
		PA System Panel	N/A	N/A	N/A		
		Batter backup	N/A	N/A	N/A		
		Building Floor Plans	N/A	N/A	N/A		
20	Specia Protect	Fire Protection Systems for ion of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in

good working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2019/WZ/1764 dated 12.09.2019.

> Signature of the Inspecting Diffeer Name & C.L. Meena Designation:- ADO/RN

Dy. Chief Fire Officer (WZ)