

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No.F.6/DFS/MS/Residential/2024/SZ/ 181

Dated: .19/.0.3./2024

FIRE SAFETY CERTIFICATE

Certified that the Boys Hostel (B1) & Girls Hostel (G1) at Indraprastha Institute of Information Technology-Delhi, Okhla Ph-III, New Delhi-110020 Comprised of Boys Hostel (B1) - Ground plus Six upper floors & Girls Hostel (G1) Stilt plus Six upper floors owned/occupied by Indraprastha Institute of Information Technology-Delhi was issued Fire Safety Certificate by this department vide letter F6/DFS/MS/Hostel/2019/SZ/1157 dated 31/05/2019. The premise was re-inspected by officer concerned of this department on 11/03/2024 in the presence of Mr. Anurag Tyagi and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class Group-A" "Residential Building" (Hostel) with effect from 1903/2024 for period of Five years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 20 14

Issued 19 03/2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. Dr. Deepika Bhaskar at Indraprastha Institute of Information Technology-Delhi, Okhla Ph-III, New Delhi-110020.

2. The Executive Engineer (Bldg) MCD, Aurobindo Marg, Green Park, Delhi 110016

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of UBBL-2016/NBC Part- IV.

4. All the staff members must know the correct method of operation of fire fighting system.

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



lλ ,	Name & Address of the Building	ON REPORT Boys Hostel (B1) & Girls Hostel (G1) Indraprasthal Institute of Information Technology-Delhi, Okhla Ph-III				
2	Type of Occupancy	New Deini-110020				
3	Building Comprised of	Residential, "Group-A" (Hostel Building)				
4	Type of Case	Boys Hostel (B1) G+6 and Girls Hostel (G1)Stilt+6				
5	Details of Previous NOC	Kenewal				
6	Fire Safety Directives Letter No	F6/DFS/MS/Hostel/2019/SZ/1157 dated 31/05/2019				
	- Journal Detter 140	F.6/DFS/MS/BP/2010/1094 dated 15-04-2010				
7	Date of Inspection	F.6/DFS/MS/BP/2015/103 dated 09/04/2015				
8	Name of the Inspecting Officers	11-03-2024				
9	Name & Designation of Officers	DO (South) & ADO (BCP)				
	from the building side	Mr. Anurag Tyagi				
10	Year of construction	2012 & 2016 2010				
11	Applicant letter No.	2012 & 2016–2019				
S. No.	Minimum standards on Fire Prevention and	NBC/BBL	D/GA/Fire NOC/2022/3293 dt 19/ BBL Provided at Site			
0.77	Fire Safety U/R 33	Requirements	Provided a	it Site	Remarks	
1	Access to Building.	1			MR/NMR	
10	Road width	6 mtr	Provid	lad	VOD	
TEX	Gate width	6 mtr	Provid		MR MR	
	Width of internal road	6 mtr	Provid			
2	Number, width, type & arrangement of ex	its.	110410	icu	MR	
F. F	a) Number of Staircase		Three mean			
oz I	> Upper floors.	Boys Hostel & Girls Hostel &	Boys Hostel & B1= 5+1 Girls Hostel &G1 = 4+1+1 Provided		i MR	
	Basement floor.	-NA-			-NA-	
	b) Width of Staircase > Upper floors	Artifus gines vs. issu 🗝			1 1121	
The last	December 1	1.5 mtr (each)	1.5 mtr each	provided	MR	
	a) Description of the	-NA-	NANA-		-NA-	
	> Fire check door	D	STAND ENHANCE	4		
	> Pressurization	Required -NA-		Provided		
27.	d) No. of continuous staircase to terrace		-NA		-NA-	
	e) Width of corridor	Required -NA-	Provid		MR	
1770	f) Door size	1m	-NA- Provided		-NA-	
3	Compartmentation.	****	PIOVIC	led	MR	
	Fire check door.	Required	ed Provided		MR	
w H	 Sealing of electrical shafts. 	Required		Provided		
	 Fire rating of shaft door. 	Required		Provided		
W -	Water curtain	-NA-	-NA		MR	
	Fire dampers.	-NA-	-NA		-NA-	
4	Smoke Management system.	.,,,	-11/2	7	-NA-	
100	Basement	30 ACPH	-NA	7 9:	-NA-	
100	• Upper floors	12 ACPH	Natural Ventilation		MR	
5	Fire Extinguishers.		historia ve	intiation	IVIK	
	Total numbers	ELU N	Boys H-101, Gi	rls H-102	MR	
	• Types	ISI marked	ABC, CO2 & W.CO2		MR	
6	ISI Marking	100 100	Provided Provided		MR	
0	First Aid Hose Reels.	ich de agrico		WIIN		
166	Total numbers on each floor.		Boys/Girls Hoste	el=06 each	MR	
Def.	Length of hose-reel hose.	Hose-reels	30m		MR	
	Nozzle Diameter Boys Hostel & Extn Block (B1), Girls Hostel & E.		2000			



7	Automatic fire detection & alarming system.	1500000			_
Tantani.	Type of detectors	Required	Sm	ke & Heat	MR
Fl alitat	AT OUR PARTIES OF THE WAY OF THE PARTIES OF THE PAR		1000000	NO-ALLES DE PROTO	MR
	Location of Main Panel	Required	Gre	ound floor	
	Location of Repeater Panel	-NA-		-NA-	-NA-
Adding	Alternate source of power	Required	. III	rovided	MR
	Hooter's location	Required	6513-1-16376	& Corridors	MR
8	MOEFA	Required	Pi	rovided	MR
9	Public Address System	Required	Pı	rovided	MR
10	Automatic Sprinkler System				
	Basement	-NA-	-NANA-		-NA-
	Upper floors	-NA-		NA-	-NA-
	Sprinkler above false ceiling	-NA-		NA-	-NA-
	11/2 11/2 11/2 11/2 11/2 11/2 11/2 11/2		HDIE ST		EAR
11	Internal Hydrants. Size of Riser/Down-comer	100 mm	Di Li	Provided	MR
		Boys/Girls Hostel-0	6 Fach	Provided	MR
COMMON	Number of Hydrant per floor			Provided	MR
06.41.4337	Hose box.	Boys/Girls Hostel-0	6 Each	Provided	IVIIC
. 12	Yard Hydrants.		YV. 4-1 0	I n	MR
(0) Z	 Total number of hydrants. 	Boys Hostel-7, Girl	Company of the Compan	Provided	MR
200	Hose box.	Boys- Hostel-7, Girl	s Hostel-8	Provided	IVIK
13	Pumping arrangements.	m: # 1/2		for all Uos	tal blocks
	Ground Level	Fire-fighting system 2280 LPM		LPM	MR
	Discharge of main pump.	Required	120,010,00	10m	MR
	> Head of main pump.	2 Nos		vided	MR
	 Number of main pumps. Jockey Pump output. 	180 LPM		M x 2 Nos	MR
	> Jockey Pump head.	Required		Om	MR
415	Standby Pump output.	2280 LPM		LPM	MR
	Standby Pump head.	Required	ahasin M	0m	MR
	Auto Starting/Manual Stopping	Required	Pro	vided	MR
	Terrace Level		CO LES INC		
	 Discharge of pump. 	900 LPM		80 LPM	MR
	➤ Head of pump.	Required		o 80m	MR
SHIR	Power supply.	Required		rided	MR
	> Auto starting of pump.	Required	Prov	rided	MR
14	Captive water storage for fire fighting.	2 00 000 T +-		71.1	N/m
	Underground tank capacity.	2,00,000 Ltr Required		rovided rovided	MR
	 Draw-off connection. Fire Service Inlet. 	Required		ovided	MR MR
	> Access to tank.	Required		ovided	MR
	Overhead tank capacity.	25,000 Ltr each Bl		ovided	MR
15	Exit Signage.	Required	-	ovided	MR
16	Provision of Lifts.		art to the last	ultra lancit	2
No.	Pressurization of lift shaft.	-NA-	-N	A-	-NA-
2015	Pressurization of lift lobby.	-NA-	-N.		-NA-
	Communication in lift car.	Required	Prov	ided	MR
	Fireman's switch.	Required	Prov	ided In II	MR
725/	Lift signage.	Required	Prov		MR
17	Standby Power Supply	Required	Provided	(DG Set)	MR
18	Refuge Area	701	A AP	8 1 1	
	Total area was the transfer and the	Required	25.06 SQ		MR
	Location Boys Hostel & Extn Block (B1), Girls Hostel & Extr	Required	6th F	oor	MR

Boys Hostel & Extn Block (B1), Girls Hostel & Extn Block (G1) IIIT-Delhi, Okhla Ph-III, ND-20





19	Fire Control Room.			1.00
-	Detector system panel.	Required	Provided	MR
	150 550	-NA-	-NA-	-NA
	Flow switch panel.	Required	Provided	MR
	 PA system panel. Battery backup. Building floor plan. 	Required	Provided	MR
			Provided	MR
		Required		MR
20	Special Fire Protection System for the Protection of special Risk, if any.	Required	HT & LT panel provided with CO2 type fire extinguishers	1,71,

Boys Hostel & Extn Block (B1), Girls Hostel & Extn Block (G1) IIIT-Delhi, Okhla Ph-III, ND-20

The fire protection system provided in the building were randomly checked and found

functional at the time of inspection. The Girls hostel G-1 Block is comprised of Stilt plus Six upper floors whereas in earlier FSC dated 31/05/2019 it was mentioned Ground plus Six upper floors, which is a

typographical mistake.

Keeping in view of the deemed compliance of the minimum standard on fire prevention fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Hostel/2019/SZ/1157 dated 31/05/2019, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Design: ADO (BCP)

CFO (HO)

Deneeta

Name: Sh. Rajesh Kumar

Let ee u prolép