

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

आज़ादी व अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2024/219

Dated: 2º /03/2024

FIRE SAFETY CERTIFICATE

Certified that the Rajdhani Public Sr. Sec. School located at Babu Nagar, Tiraha Shiv Vihar, Delhi-110096, comprised of Ground plus two upper floors only for which Fire Safety Certificate was issued by this department vide letter no. F6/DFS/MS/2017/School/537 dated 12/04/2017, have complied with fire prevention & fire safety requirements in accordance with 33 of the Delhi Fire Service Rules, 2010/ NBC Part - IV and verified by the officer concerned of Fire Service on 07/03/2024 in presence of Mrs. Monika Devi (Principal) and that the building /premises is fit for occupancy class "Educational Building" (Group-B) with effect from 20/03/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 20/03/2024 at New Delhi by.

DIRECTOR OCCUPELHI FIRE SERVICE

Copy to:-

- The Principal, Rajdhani Public Sr. Sec. School located at Babu Nagar, Tiraha Shiv Vihar, Delhi-110096.
- 2. The Dy. Director of Education, North East, B Block Yamuna Vihar, Delhi 110053.

Conditions for the validity of Fire Safety Certificate

- 1. Fire Safety Certificate is valid for (G + 02) old building only.
- 2. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 3. All the means of escape shall be kept free of all the type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 7. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

A				TION REPORT	16		
1	Name & address of the building			Rajdhani Public Sr. Sec. School located at Bab			
				Nagar, Tiraha Shiv Vihar, Delhi-110096.			
2	Building is comprised of			Ground plus two	upper floors. (Old Blo	ock)	
3	Type of occupancy			Educational Building			
4	Тур	e of case	70	Renewal			
5	Det	ails of pr	revious FSC	F6/DFS/MS/2017/School/537 dated 12/04/2017			
6	Fire	safety d	irectives letter no.	NBC Part - IV			
7	Dat	e of insp	ection	07/03/2024			
8	Nar	ne of the	inspecting officers	Yashwant Singh	Meena, ADO (L.N)		
9	Name of the designation of officer from the building side			Mrs. Monika Devi (Principal)			
10	Yea	ar of con	struction	1998			
11	Applicant's letter no.			Email dated- 28/02/2024			
S.No	Minimum standard of fire prevention and fire safety U/R 33			NBC Part -IV Requirement	Provided at site	Remarks MR/NMI	
1	Ac	cess to B	uilding:				
	A	Road v	vidth	6.0 mtrs.	6.0 mtrs.	MR	
	В	Gate w	ridth	· N/A	N/A	N/A	
	C Width of internal road		N/A	N/A	N/A		
2	Number, Width, Type and Arrangement of Exits:						
	A	Numbe	er of staircases				
1		a Upp	per floor	01 no.	02 nos. 🗸	MR	
į.	-	c Bas	ement	N/A	N/A	N/A	
-	В	Width	of staircases	2000204	e distance and	C	
			per floor	1.50 mtrs.	1.0 mtrs. & 0.90 mtrs.	MR	
		b Bas	ement	N/A	N/A	N/A	
	C	Protec	tion of exits				
			check door	N/A	N/A	N/A	
		b Pre	ssurization	N/A	N/A	N/A	
	D	No. c	of continuous staircases to	01 no.	01 no.	MR	
	E	Width	of corridor	1.50 mtrs.	1.50 mtrs.	MR	
	F	Doors		1.0 mtrs.	1.0 mtrs.	MR	
3	Compartmentation:						
	A	Fire cl	neck door	NA	NA	NA	
	В	Sealin	g of electrical shafts	N/A	N/A	N/A	
	C	Fire ra	ting of shaft door	N/A	N/A	N/A	
	D		curtain	N/A	N/A	N/A	
	E Fire dampers		N/A	N/A	N/A		
4	Smoke Management System:						
4	_			N/A	N/A	N/A	
	A	Basen	nent	N/A	17/7	TWA	

u

5.	Fire Extinguisher:							
	A	Total numbers	08 Nos.	12 Nos.	MR			
	В	Types	CO ₂ & ABC	CO ₂ & ABC	MR			
	C	ISI marking	ISI Marked	ISI Marked	MR			
6	First-Aid-Hose Reel:							
	A	Total numbers of each floor	01 no.	01 no.	MR			
	В	Length of hose reel hose	30 mtrs.	30 mtrs.	MR			
	C	Nozzle diameter	05 mm	05 mm	MR			
7	Automatic Fire Detection and Alarming System:							
	A	Type of detectors	N/A	N/A	N/A			
	В	Location of main panel	N/A	N/A	N/A			
	C	Location of repeater panel	N/A	N/A	N/A			
	D	Alternate source of power	N/A	N/A	N/A			
	E	Hooters	N/A	N/A	N/A			
8	M	OEFA:	N/A	N/A	N/A			
9	Pu	blic Address System:	N/A	N/A	N/A			
10	Au	tomatic Sprinkler System:		(m)				
	A	Basement	N/A	N/A	N/A			
	В	Upper floor	N/A	N/A	N/A			
	C	Sprinkler above false ceiling	N/A	N/A	N/A			
11	Int	ernal Hydrants:		N/A	N/A			
	A	Size of riser/down-comer	N/A	N/A	N/A			
	В	Number of hydrants per floor	N/A	N/A	N/A			
	C	Hose box	N/A	N/A	N/A			
12	Yard Hydrants:							
	В	Hose box	N/A	700 000 0000	N/A			
13	/2E	ACADOMIC SANDAR	N/A	N/A	N/A			
13	Pumping Arrangements: Ground level							
	A	CONTROL CONTRO	1 27/1	1				
		Discharge of main pump	N/A	N/A	N/A			
	В	Head of main pump	N/A	N/A	N/A			
	С	Number of main pumps	N/A	N/A	N/A			
	D	Jockey pump out put	N/A	N/A	N/A			
	E	Jockey pump head	N/A	N/A	N/A			
	F	Standby pump out put	N/A	N/A	N/A			
	G	Standby pump head	N/A	N/A	N/A			
	H	Auto starting /manual stopping	N/A	N/A	N/A			
	I	Pump house access	N/A	N/A	N/A			
2	Terrace Level							
	A	Discharge of pump	450 LPM	450 LPM	MR			
	В	Head of the pump	40 mtrs	40 mtrs	MR			
	C	Power supply	Required	Provided	MR			
	D	Auto starting of pump	Required	Provided				

1	Captive Water Storage for Fire Fighting:							
7	A	Underground tank capacity	N/A	N/A	N/A			
t	В	Draw-off connection	N/A	N/A	N/A			
ŀ	C	Fire service inlet	N/A	N/A	N/A			
ł	D	Access to tank	N/A	N/A	N/A			
1	E	Overhead tank capacity	10,000 ltr.	10,000 ltr.	MR			
15	Exit Signage:		Required	Provided	MR			
16	Provision of Lifts:							
	A	Pressurization of lift shaft	N/A	N/A	N/A			
	В	Pressurization of lift lobby	N/A	N/A	N/A			
	C	Communication in lift car	N/A	N/A	N/A			
	D	Firemen's grounding switch	N/A	N/A	N/A			
	E	Lift signage	N/A	N/A	N/A			
17		andby Power Supply:	N/A	N/A	N/A			
18	_	Defuge Area						
10	A	Total area	N/A	N/A	N/A			
	B	Location	N/A	N/A	N/A			
19	Fire Control Room:							
-	A	Detector system panel	N/A	N/A	N/A			
	B	Flow switch panel	N/A	N/A	N/A			
	C	PA system panel	N/A	N/A	N/A			
	D	Battery backup	N/A	N/A	N/A			
	E		N/A	N/A	N/A			
20) S	pecial Fire Protection systems for rotection of special Risks, if any:	N/A	N/A	N/A			

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The shortcomings issued vide letter no. F6/DFS/MS/School/2020/720 dated 06/11/2020 by this department has been rectified by the management.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no. NBC Part IV, the FSC issued vide letter no. F6/DFS/MS/2017/School/537 dated 12/04/2017 is recommended to be renewed.

Signature of the Inspecting Officer Yashwant Singh Meena Name

ADO (L.N) Designation