GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2024/ 73

Dated: 20/03 /2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Meraj Guest House situated at 2298, Gali Qasim Jan, Ballimaran, Delhi - 06, comprised of Ground + 04 upper floors: Ground floor - Galib Ki Haveli, 1st floor reception + 04 guest rooms, 2nd floor - 04 guest rooms, 3rd floor - 03 guest rooms + 01 store room, 4th floor - (not in use as per affidavit dated 14.10.2021), total 11 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2021/128 dated 08.03.2021. The building/premises was re-inspected by the officer concerned from this department on 12.03.2024 in presence of Mr. Merajuddin (Owner) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit dated 13.03.2024 not to use any floor above third floor for any purpose. Accordingly, the premises is fit for occupancy of "Residential (Group A-1)" 1st floor- (04 guest rooms), 2nd floor - (04 guest rooms) & 3rd floor - (03 guest rooms) for total 11 guest room upto 3rd floor only, with effect from . 20/0.3/2024... for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Delhi Fire Service 1/

Tel: 011-23414000

Copy to:-

- 1. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above & deviation, if any.
- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2024030202485 dated 02.03.2024.
- 3. The Licensee, M/s Meraj Guest House at 2298, Gali Qasim Jan Ballimaran, Delhi 110006.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained there to before occupancy of the same.
- The occupancy of above 3rd floor not allowed as per clause 7.31 in UBBL-2016.

	Name & address of the building	SPECTION REPORT M/s Meraj Guest House situated at 2298, Gali Qasim Jan Ballimaran, Delhi - 06.				
	Building is comprised of	Ground + 04 upper floors				
		Ground floor Golib V	Cround Good Call W. W.			
		Ground floor - Galib Ki Haveli 1 st floor - reception + 04 guest rooms				
		2nd Gran Od and	guest rooms			
		2 nd floor - 04 guest room	is + 01store room			
		3rd floor - 03 guest room	ns + 01 store room			
	True of O	4th floor – not in use as per affidavit dated 13.03.2024				
	Type of Occupancy	Residential Group A-1				
	Type of Case	Renewal				
	Details of Previous FSC	F6/DFS/MS/GH/NDZ/2021/128 dated 08.03.2021				
5	Fire Safety direction letter No	Nil				
	Date of Inspection	12.03.2024				
8	Name of the Inspecting Officers	Sumit Kumar, ADO (SP)	VI)			
9	Name of the designation of Officer	Mr. Merajuddin (Owner)				
	from the building side	(Owner)				
10	Year of Construction	Old Haritage Building				
1	Tear of Construction	Old Heritage Building				
1	A 12	Date of change of occupancy: 1992				
11	Applicant's letter No	Online application I.D.20				
S.N	THE THEORY OF THE PROPERTY OF	Requirement/ Existing	Provided at Site	Remarks		
1	Prevention and fire safety	fire safety		MR/NMR		
	requirements U/R 33	arrangements				
1	Access to building					
	Road width	NA	06 m	NA		
	Gate width	NA	NA	NA		
1		NA	NA	NA		
2	Number, Width, Type and Arran	gement of Exits		_		
	A. Number of Staircases					
	Upper Floor	01 no.	01 no.	MR		
	Basement	NA	NA	NA		
	B. Width of Staircases					
	Upper Floor	80 cms	80 cms /	MR		
	Basement	NA	NA	NA		
	C. Protection of exits		75.40			
	Fire check door	NA	NA	NA		
	Pressurization	NA	NA	NA		
	D. No. of continuous staircases to	NA	NA	NA		
	E. Width of Corridor	NA	NA	NA		
		Source	Tak noon wa	CHICCIDE		
2	G. Door size	1.0 m	1.0 m	MR		
3	Compartmentation		1514	1314		
	Fire check door	NA NA	NA	NA		
	Sealing of electrical shafts	NA	NA	NA		
-	Fire rating of shaft door	NA	NA	NA		
	Water curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
-	Smoke Management System.	AAN LORON TOWN	Lyn	Towns -		
4	The second secon	100 January Lance	NA	NA		
4	Basement Upper floor	30a/cper hour 12 ACPH	Natural	NA		

- N/18-

5.	Fire Extinguisher Total numbers 08 no. 08 no.						
	Total numbers	08 no.	CO ₂ & ABC	MR MR			
	types	CO ₂ & ABC		MR			
	IS marking	Required	Provided	MIK			
6	First-aid-Hose Reels.						
	Total numbers of each floor	NA	01 no.	NA (as previous			
				I.R)			
	T and of the state of the	NA	30 m	NA			
	Length of hose reel hose	NA NA	5 mm	NA			
	Nozzie diameter						
7	Automatic fire detection and alarming		Provided	MR			
	Type of detectors (CO type)	Required	Provided at	MR			
	Location of main panel	Required	reception	NA			
	Location of repeater panel	NA	NA	MR			
	Alternate source of power	Required	Provided Provided	MR			
	Hooters	Required	NA	NA			
3	MOEFA	NA		NA			
)	Public address System.	NA	NA	INA			
10	Automatic Sprinkler System.		Tava	DIA			
	basement	NA -	NA	NA			
	upper floor	NA	NA	NA			
	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants						
	size of riser/down-comer	NA	NA	NA			
	Number of hydrants per floor	NA	NA	NA			
	Hose Box	NA	NA	NA			
12	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
13	Pumping Arrangements.						
	Ground Level						
	> Discharge of main Pump	NA	NA	NA			
	➤ Head of Main Pump	NA	NA	NA			
	> Number of main pumps	NA	NA	NA			
	> Jockey pump out put	NA	NA	NA			
	> Jockey pump head	NA	NA	NA			
	Standby pump out put	NA	NA	NA			
	Standby pump Head	NA	NA	NA			
	Auto Starting /Manual stopping	NA	NA	NA			
	> Pump House Access	NA	NA	NA			
	Terrace Level		,				
	➤ Discharge of pump	NA	450 LPM	NA (as per previous I.R)			
	➤ Head of the Pump	NA	40 m	NA			
	Power supply	NA	Provided	NA			
	Auto Starting of pump	NA	NA	NA			

84

4	Captive Water Storage for Fire Fighting.					
	Underground tank capacity	NA	NA	NA		
į	Draw-off connection	NA	NA	NA		
	Fire service inlet	NA	NA	NA		
	Access to tank	NA	NA	NA		
	Overhead Tank capacity	NA	3,000 ltrs /	NA (as per previous I.R)		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	NA	NA	NA		
	Pressurization of Lift lobby	NA	NA	NA		
	Communication in lift car	NA	NA	NA		
	Firemen's grounding switch	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17	Standby power supply	NA	NA	NA		
18	Refuge Area.					
	Total area	NA	NA	NA		
	Location	NA	NA	NA		
19	Fire Control Room					
	Detector system panel	NA	NA	NA		
	Flow switch panel	NA	NA	NA		
	PA system panel	NA	NA	NA		
	Batter backup	NA	NA	NA		
	Building Floor Plans	NA	NA	NA		
20	Special Fire Protection systems for protection of special Risks, if any:		NA	NA		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

The owner has submitted an affidavit on 13.03.2024 not to use any floor above third floor for any purpose in accordance with Gazette Notification dated 27.05.2019.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2021/128 dated 08.03.2021 upto 3rd floor only is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Sumit Kumar

Designation ADO (SPM)

DO (CD)

Bull 13/3424

Dyceologo

14/02/21

Minester 1 About

Directa Mary

Anysma