

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/Club/2024/SZ/ 187

Dated: 21/03/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Panch Shila Club, located at Panch Shila Park, New Delhi 110017 comprised of Basement, ground plus One upper floor only, owned/Occupied by The Panch Shila Co-op H. B. Society Ltd, was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/Club/2021/SZ/177 dated 16/03/2021. The premise was re-inspected by the officer concerned of this department on 19/03/2024 in the presence of Mr. Rahul Kaushik (Admin) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly (Club Building) and validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 21 03 2024 at New Delhi by

DIRECTOR DELHI FIRE SERVICE

Copy to: -

1. M/s Panch Shila Club, located at Panch Shila Park, New Delhi 110017.

2. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

 All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system

 The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of

UBBL-2016), if any.

 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	Dignor					
1	Name & Address of the Building		अमृत महोत्सव			
2		Panch Shila Club located at Panch Shila Park, Delhi-110007				
4	Type of Occupancy	(Assembly occupancy i.e. Eating house "Group-				
3	Building Comprised of	D") Club Building Basement, Ground plus One upper floor only				
4	Type of Case	Renewal	d plus One upper 1100r	only		
5	Details of Previous NOC	E0175	L Manas / Mary / Mary / Mary			
6	Fire Safety Directives Letter No.	Nil	b/2021/ SZ/177 dated 1	6/03/2021		
7	Date of Inspection	19/03/2024	No. of Hills of			
8	Name of the Inspecting Officers	LIAMONT AND	DO (DOD)			
9	Name & Designation of Officers	DO (South) & ADO (BCP)				
	from the building side	Mr. Rahul Kaushik (Admin)				
10	Year of construction	2009-10	7 101.01			
11	Applicant letter No.	S408086 #47				
S. No.		MHA Portal ID 2024031903201 dated 25/01/2021				
5. 140.	Minimum standards on Fire Prevention	Old FSC	Provided at Site	Remarks		
1	and Fire Safety U/R 33 Access to Building.	requirements	AMERICA DE	MR/NMR		
	Road width	Accessible	12 mtr	MR		
	Gate width Width of internal road	4.5 mtr	4.5 mtr	M/R		
2		N/A	N/A	N/A		
	Number, width, type & arrangement of ex	its.	in the country of			
Nº	a) Number of Staircase		word and a			
	Upper floors.	02 Required	03 Nos.	MR		
	➤ Basement floor.	01 Required	01 Nos.	MR		
	b) Width of Staircase					
	 Upper floors Basement floor 	1.50 mtr each	1.5 m, 1.25m, 0.97m,	MR(old case		
		Required	1.10 mtr	MR(old case		
4	c) Protection of exits	and the second of	7			
r]	➤ Fire check door ➤ Pressurization	N/A	N/A	N/A		
- 1	d) No. of continuous staircase to terrace	N/A	N/A	N/A		
M		01 Required	02 Nos	MR		
	e) Width of corridor	N/A	N/A	N/A		
	f) Door size	N/A	N/A	N/A		
3	Compartmentation.			.,,,,		
W	Fire check door.					
A 5	Sealing of electrical shafts.	N/A	N/A	N/A		
	Fire rating of shaft door.	Required	Provided	M/R		
	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
	CANDIDATE OF SERVICE	N/A mu	Mark N/A	N/A		
4	Smoke Management system.					
4						
4	Basement	30 ACPH	Exhaust Fans provided	d MD		
4		30 ACPH 12 ACPH	Exhaust Fans provided			
5	Basement	I Committee of the comm	Exhaust Fans provider Exhaust Fans provider	The second secon		
. 4	Basement Upper floors	I Committee of the comm	Exhaust Fans provided	d MR		
. 4	Basement Upper floors Fire Extinguishers.	12 ACPH	17 N. SALE 1980			

आज़ार्द	वत
अमृत	महोत्सव

6	First Aid Hose Reels.	1		
	Total numbers on each floor.	Two Nos	Provided	MF
	Length of hose-reel hose.	30m	30m	MR
	Nozzle Diameter		5mm	MR
7	Automatic fire detection & alarming syste	5mm	3 3mm	MIN
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System	Required	1707,000	
ALL VALUE	Basement	Required	Provided	M/
	Upper floor	Required in kitchen Restaurant area at	&	M/1
/	 Sprinkler above false ceiling 	floor N/A	N/A	N/A
11	Internal Hydrants.	1,7/12		1 5.00
	Size of Riser/Down-comer	100 mm	Provided	M/R
	Number of Hydrant per floor	02	Provided	M/R
	Hose box.	02	Provided	M/R
12	Yard Hydrants.			
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.	WE D	Sold state H 15	
4121-12	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	 Standby Pump output. Standby Pump head. 	N/A	N/A N/A	N/A N/A
	> Auto Starting/Manual Stopping.	N/A	N/A	N/A
	> Pump house access.	N/A		N/A
	ANTON THE RESERVE TO	N/A	N/A	IVA
	Terrace Level	900 & 180	Provided	MR
	Discharge of pump.	LPM	nestyres/	
	➤ Head of pump.	40 m	Provided	MR
	Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	em	M SARY -	
	Underground tank capacity.	35,000 Ltrs	Provided	MR
	> Draw-off connection.	Required	Provided	MR MR
	> Fire Service Inlet.	Required	Provided Provided	MR
	> Access to tank.	Required	15,000 Ltrs	MR
	 Overhead tank capacity. 	15,000 Ltrs	15,000 Lus	

~



15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
10	Pressurization of lift shaft.	N/A	N/A	N/A
- 1	Pressurization of lift lobby.	N/A	N/A	N/A
	 Communication in lift car. Fireman's switch. Lift signage. 	Required	Provided	MR
- 1		Required	Provided	MR
		Required	Provided	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
10	Total area Location	N/A	N/A	N/A
		N/A	N/A	N/A
19	Fire Control Room.			
-	 Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. 	N/A	N/A	N/A
		N/A	N/A	N/A
		Required	Provided	MR
		Required	Provided	MR
		N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	NA	N/A

The fire protection system provided in the premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/Club/2021/ SZ/177 dated 16/03/2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

21/3/22 NXELL.

21/03/24

J. 26.