

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/School/ 243

Dated: 26/03/2024

## FIRE SAFETY CERTIFICATE

Certified that the Suraj International School located at 25 Foota Road, Shastri Park Phool Bagh, Nathupura, Burari, Delhi-110084 comprised of 02 blocks interconnected, Ground & First Floors Each owned/ occupied by the Suraj International School have complied with the fire prevention and safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 16.03.2024 in the presence of Sh. Arun Schgal (Manager) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class 'Group B Educational' with effect from 26.193 2.024.... for a period of three years, subject to compliance of the conditions mentioned below:

Issued on 26/03/2024 at New Delhi

Director Ph:-011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Manager, Suraj International School located at 25 Foota Road, Shastri Park Phool Bagh, Nathupura, Burari, Delhi-110084.

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in/wps/wcm/connect/doit">http://delhi.gov.in/wps/wcm/connect/doit</a> fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

## INSPECTION REPORT

1. Name & address of the building : Suraj International School at 25 Foota Road, Shastri Park, Phool

Bagh Road, Nathupura, Burari, Delhi-110084.

Type of Occupancy

: Educational

Type of Case

: New Case

Composition of building

: 02 blocks interconnected (Ground & First Floor only each)

5. Details of previous NOC

6. Fire Safety directives letter No

: Director of education circular dated 01.03,20211

7. Date of inspection

: 16.03.2024

Name of the Inspecting Officers: ADO (RN)

9. Name and designation of officers

from the building side

: Mr. Arun Sehgal (Manager)

10. Year of Construction

: 2019

11. Applicant's letter No.

: Letter No. Nil & DFS Dairy No- 13984 dated 07.03.2024

	Minim	um Standards on fire prevention and fire safety U/R 33	Director of Education Circular dated 01.03.201	Provided at site	Remarks MR/NMR		
	Access to	to building					
		Road width	06m	Provided	MR		
		Sate width	4.5m	Provided	MR		
		Width of internal road	NA	NA	NA		
-	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	•	Jpper Floors	02	03	MR		
	•	Basements	NA	NA	NΛ		
	b. Width	of staircases					
	3€5	Upper Floors	1.5m each	1.5m ,1.90m & 1.50m (iron staircase)	MR		
	•	Basements	NA	NA NA	NA		
	c. Protection of exits						
	201	Fire check door	NA	NA	NΛ		
		Pressurization	NA	NA	NΛ		
	d. No. o	continuous staircases to terrace	NA	NA	NΛ		
	e. Width	of Corridor	NA NA	NΛ	NΛ		
	f, Door S	Size	1.20m	Provided	MR		
3	Compar mentation.						
		Fire check door	NA	NA	NΛ		
		Sealing of electrical shafts	NA	NΛ	NΛ		
		Fire Rating of shaft door	NA	NΛ	NΛ		
		Water Curtain	NA	NA	NΛ		
	•	Fire Dampers	NA	NΛ	NA		
4	Smoke Management System.						
		Basements	NA	NA	NΛ		
	•	Upper floors	Required	Natural Ventilation	MR		
5	Fire	ire Extinguishers					
	•	Fotal numbers	06nos	08nos	MR		
	<b>1</b>	Гуреѕ	ABC/Co2	ABC-08	MR		
		SI marking	Yes	Yes	MR		
-			0.				

6	First-Aid Hose Reels.		NA	NA.		
	Total numbers on each floor	NA		NA NA		
	Length of hose reel hose	NA	NΛ			
	Nozzle diameter	NA	NA	NΛ		
1	Automatic fire detection and alarming system					
	Type of detectors	NA	NΛ	NA NA		
	Location of Main Panel	NA	NA	NΛ		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	NA NA	NA	NΛ		
	Hooters' Location	NA	NA	NΛ		
8	MOEFA	NA /	NΛ	NΛ		
9	Public Address System.	NA	NΛ	NΛ		
10	Automatic Sprinkler System.					
	a Decement	NA	NΛ	NΛ		
	Basement     Upper Floor	NA NA	NΛ	NΛ		
	Sprinkler above false ceiling	NA NA	NA NA	NA NA		
		NA	iN/X			
11	Internal Hydrants  Size of riser/down-comer NA NA					
	Size of riser/down-comer     Number of hydrants per floor	NA NA	NA NA	NA NA		
	Hose Box	NA I	NA NA	NA NA		
12	Yard Hydrants.					
12		NA	NΛ	NA		
	Total number of hydrants	V03695	NΛ	NA NA		
	Hose Box	NA	IN/A	NA.		
13	The state of the s					
	Ground Level					
	> Discharge of main Pump	N/A	N/A	N/A		
	<ul> <li>Head of Main pump</li> <li>Number of main pumps</li> <li>Jockey Pump out put</li> <li>Jockey pump head</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	. N/A		
		N/A	N/A	N/A		
	> Jockey pump head > Standby Pump out put	N/A	N/A	N/A		
	> Standby Pump Head	N/A	N/A	N/A		
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	18/7		
	Terrace level	NA	NA	NΛ		
	<ul> <li>Discharge of pump</li> <li>Head of the pump</li> </ul>	NA NA	NA NA	NA NA		
	> Head of the pump > Power Supply	NA	NA NA	NΛ		
	> Auto Starting of pump	NA	NA	NA		
14						
	<ul> <li>Underground tank capacity</li> </ul>	NA	NA	NA		
	> Draw-off connection	NA	NA	NΛ		
	> Fire service inlet	NA	NA	NΛ		
	> Access to tank	NA	NA	NA		
	<ul> <li>Overhead Tank capacity</li> </ul>	NA	NA	NΛ		
	Overnead rank capacity	INA	1874	N/A		

	Exit Signage.	NA	NΛ	NΛ		
	Provision of Lifts.					
	Pressurization of Lift Shaft     Pressurization of Lift lobby	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Communication In lift Car      Wireman's Grounding Society	N/A	N/A	N/A		
	<ul> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
7	Standby power supply	N/A	N/A	N/A		
8	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
9	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	<ul> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/2023/School/298 dated 22.07.2023.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2011, it is recommended to grant Fire Safety Certificate

Signature of the Inspecting Officer
Name: - C.L. Meena

Designation:- Asst. Div. Officer (RN)

Dy. Chief Fire Officer (WZ)

0,742NW

19/3

2 neutopy

'ApyKN

Conf - - P.T.O.