८२) गणादी म अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2024/ 277

Dated: 04/04/2024

FIRE SAFETY CERTIFICATE

Certified that the Florida Public School located at 24, Madhuwan Duplex, Sewa Dham Road, Mandoli, Delhi - 110093, comprised of ground plus one upper floor only, owned/occupied Certificate vide Florida Public School issued Fire Safety by was F6/DFS/MS/School/2021/NDZ/225 dated 12/03/2021. The School building was re-inspected by the officer concerned of this department on 27/03/2024 in presence of Mr. Sanjay Kumar (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the Fire Prevention and Fire Safety requirements in accordance with Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education and that the building is fit for occupancy class "Educational Building" (Group-B) with effect from 04/04/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010. Subject to conditions printed below. 04 04 12024 at New Delhi by.

(ATVL GARG)
DIRECTOR

CLUELHI FIRE SERVICE

Copy to:-

- 1. The Director of Education, B Block, Yamuna Vihar, Delhi 110053.
- The Manager, the Florida Public School located at 24, Madhuwan Duplex, Sewa Dham Road, Mandoli, Delhi - 110093.

Conditions for the validity of Fire Safety Certificate

- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

4/10

			INSPE	CTION REPOR	<u>et</u>				
1	Na	ıme	& address of the building	Florida Public	School located at 24	, Madhuwan			
				Duplex, Sewa	Duplex, Sewa Dham Road, Mandoli, Delhi -				
				110093.					
2	Bu	ild	ing is comprised of	Ground + 01 up	Ground + 01 upper floors.				
3	-	-	of occupancy	Educational Building					
4		-	of case	And I					
5	-	•	The second secon	F6/DFS/MS/School/2021/NDZ/225 dated					
3	Details of previous FSC Fire safety directives letter no.								
,				12/03/2021 F16/Estate/CC/Fire Safety/2011/3298-3398 dated					
6				01.03.2011.					
				27.02.2024					
7			of inspection	Yashwant Singh Meena ADO (L.N)					
8			of the designation of	Mr. Sanjay Ku	· vr ··································				
9	Na	me	OI THE GOLDING	IVII. Daijay	IVII. Sailjay Assail (
			r from the building side	2009	2000				
10	(Vic)(2)		of construction	Email dated 01	1/03/2024				
11	A	pli	cant's letter no.	01.03.2011	Provided at	Remarks			
		M	inimum standard of fire	Circular	site	MR/NMR			
S.No	p	rev	ention and fire safety U/R	requiremen	t				
	*5		33	Tequii					
1	Access to Building:			T (0 to	7.0 mtrs.	MR			
•	A	R	toad width	6.0 mtrs.	N/A	N/A			
1	B	6	ate width	N/A	N/A	N/A			
ì			The second secon	N/A					
2	Ni	ıml	ber, Width, Type and Arra	ngement of Exit					
	A	I	Jumber of staircases		02 nos.	MR			
			Upper floor	01 no.	N/A	N/A			
	_	c	Basement	N/A					
	В	v	Vidth of staircases	The second second	1.0 mtr. & 0.95 mtr.	MR			
	Д	a	Upper floor	1.50 mtrs.	1,0 mir. & 0.55 mir.	(Old Case)			
		a	Оррег		N/A	N/A			
-		b	Basement	N/A	IVA				
}	-	D	rotection of exits	27/1	N/A	N/A			
	C	1	Fire check door	N/A	N/A	N/A			
-		1	Pressurization	N/A	02 nos.	MR			
ı d	D	N	o. of continuous staircases	01 no.					
	ע	to	terrace	N/A	N/A	N/A			
	E	V	idth of corridor	1.0 mtr.	1.0 mtr.	MR			
ŀ	F	D	oor size	1.0 ma.					
3	Co	mp	artmentation:	NA	NA	NA			
3	A Fire check door		re check door	N/A	N/A	N/A			
	_	S	ealing of electrical shafts	N/A	N/A	N/A			
	В	355	ire rating of shaft door	N/A	N/A	N/A			
	C	F		1 1/4 4		N/A			
	-	N	/ater curtain		N/A	45770-447			
	C D	W	/ater curtain	N/A	N/A				
4	C D	W	/ater curtain		N/A N/A	N/A N/A			

5.	Fire Extinguisher:			/			
	A	Total numbers	04 nos.	05 nos.	MR		
	В	Types	ABC/Co ₂	ABC/Co ₂	MR		
	C	ISI marking	ISI Marked	ISI Marked	MR		
6		rst-Aid-Hose Reel:	IOI IVIIII				
_	A	Total numbers of each floor	N/A	N/A	N/A		
	B	Length of hose reel hose	N/A	N/A	N/A		
	C	Nozzle diameter	N/A	N/A	N/A		
7	- A.S.						
	Automatic Fire Detection and Alarming System:			N/A	N/A		
	B	Type of detectors Location of main panel	N/A	N/A	N/A		
	C	Location of repeater panel	N/A	N/A	N/A		
	D	Alternate source of power	N/A	N/A	N/A		
	E	Hooters	N/A	N/A	N/A		
0			N/A	N/A	N/A		
8	To Philip	DEFA:	N/A	N/A	N/A		
9	Public Address System.						
10	-	tomatic Sprinkler System:	N/A	N/A	N/A		
	A	Basement	N/A	N/A	N/A		
	В	Upper floor	N/A	N/A	N/A		
	C	Sprinkler above false ceiling	14/21				
11	Inte	ernal Hydrants:	N/A	N/A	N/A		
	A	Size of riser/down-comer	N/A N/A	N/A	N/A		
Ì	В	Number of hydrants per floor	N/A	N/A	N/A		
ı		Hose box	IN/A				
2	Yard Hydrants:			N/A	N/A		
-	A	Total number of hydrants	N/A	N/A	N/A		
ŀ	B	Hose box	N/A	1.1/2.2			
+	Pumping Arrangements:						
-	Pun	ound level		N7/A	N/A		
		Discharge of main pump	N/A	N/A	N/A		
-	A	Discharge of mum pump	N/A	N/A			
_	В	Head of main pump	N/A	N/A	N/A		
	\boldsymbol{c}	Number of main pumps	N/A	N/A	N/A		
	D _	Jockey pump out put	N/A	N/A	N/A		
	E	Jockey pump head	N/A	N/A	N/A		
1	F	Standby pump out put	N/A	N/A	N/A		
1	G	Standby pump head	N/A	N/A	N/A		
	H	Auto starting /manual			1		
1		stopping	N/A	N/A	N/A		
I		Pump house access					
17	erra	ice Level	N/A	N/A	N/A		
A	-	Discharge of pump	N/A N/A	N/A	N/A		
B	-	Head of the pump	N/A N/A	N/A	N/A		
C	-	Power supply	0000000	N/A	N/A		
10	1	Auto starting of pump	N/A	XXXXX	90/		

M)17-Florida Public School located at 24, Madhuwan Duplex, Sewa Dham Road, Mandoli, Delhi -110093

14	Captive Water Storage for Fire Fig	nting:					
-	A Underground tank capacity	N/A	N/A	N/A			
	B Draw-off connection	N/A	N/A	N/A			
	C Fire service inlet	N/A	N/A	N/A			
	1 1 -1	N/A	N/A	N/A			
	1 1 seed conscity	N/A	N/A	N/A			
		N/A	N/A	N/A			
15	Exit Signage:						
16	Provision of Lifts:	N/A	N/A	N/A			
	A Pressurization of lift shaft	N/A	N/A	N/A			
	B Pressurization of lift lobby	N/A	N/A	N/A			
	C Communication in lift car	N/A	N/A	N/A			
	D Firemen's grounding switch	N/A	N/A	N/A			
	v Lift signage	N/A	N/A	N/A			
17	Glev	1,,,,					
18		N/A	N/A	N/A			
10	A Total area	N/A	N/A	N/A			
	B Location	N/A					
16	D I Doom!	T 34/4	N/A	N/A			
19	To the eviden name	N/A	N/A	N/A			
	The second	N/A	N/A	N/A			
	B Flow switch panel C PA system panel	N/A	N/A	N/A			
	1 - Jane	N/A	N/A	N/A			
	title disconficient	N/A	N/A	N/A			
	The standard of the state of th	N/A	TV/A				
20	protection of special Risks, if any:						

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no F16/Estate/CC/Fire Safety/2011/3298-3398 dated 01.03.2011, the FSC issued vide letter no. F6/DFS/MS/School/2021/NDZ/225 dated 12/03/2021 is recommended to be renewed.

> Signature of the Inspecting Officer Yashwant Singh Meena Name: -

Designation: - ADO (L.N)