

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F6/DFS/MS/School/NDZ/2024/272

Dated: 04 /04/2024

## **FIRE SAFETY CERTIFICATE**

Certified that the Stepping Stone Convent School running at ground, first, second floor of building comprised of Ground plus three upper floors at Acharya Niketan Mayur Vihar Phase – I, Delhi - 110091, owned / occupied by Stepping Stone Convent School, was issued Fire Safety Certificate vide letter No. F6/DFS/MS/School/2018/NDZ/2428 dated 29.10.2018. The School building was re-inspected by the officer concerned of this department on 26/03/2024 in presence of Mrs. Anu Kapoor (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the Fire Prevention and Fire Safety requirements in accordance with Circular no. 262 - 362 Dated 17.01.2005 issued by Director of Education and that the building is fit for occupancy class "Educational Building" (Group - B) with effect from 64 /04/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 04/04/2024 at New Delhi by.

(ATIOL GARG) DIRECTOR DELHI FIRE SERVICE

## Copy to:-

- The Director of Education, GNCT of Delhi, Old Secretariat, Delhi-110054.
- The Principal, Stepping Stone Convent School located at, Acharya Niketan Mayur Vihar Phase I, Delhi - 110091.

## Conditions for the validity of Fire Safety Certificate

- 1. Fire Safety Certificate is valid for Ground, first, second floor only.
- 2. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 3. All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method
  of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 7. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

MIL

			INSPEC	TION REPORT				
	Nam	e &	address of the building	Stepping Stone Convent School located at Acharya Niketan Mayur Vihar Phase – I, Delhi-110091.				
2	Building is comprised of			Ground + 03 Upper floors but School Running at Ground + 02 upper floors only.				
3	Тур	e of	foccupancy	Educational Building				
4	Тур	e of	f case	Renewal				
5	Details of previous FSC			F6/DFS/MS/School/2018/NDZ/2428 dated				
				29.10.2018				
6	Fire safety directives letter no. Circular no. 262-362 Dated 17/01/2005					05		
7	Date of inspection 26/03/2024							
8			of the inspecting officers	Yashwant Singh N	Meena ADO (L.N)			
9	Nar	ne	of the designation of from the building side	200 100 1000 200 100 100 100 100 100 100				
10	Year of construction			2001- 02				
111			ant's letter no.	Outdoor Diary No	o 13363 Dated 20/	02/2024		
S.No	Minimum standard of fire		nimum standard of fire ention and fire safety U/R	Old Circular requirement	Provided at site	Remarks MR/NMR		
1	Ac	ces	s to Building:			1 m		
<	A	R	oad width	6.0 mtrs.	3.0 mtrs.	MR (old accepted		
A.	В	G	ate width	N/A	N/A	N/A		
E	C	V	lidth of internal road	N/A	N/A	N/A		
2	Nu	ımt	er, Width, Type and Arra	ngement of Exits:				
	A	N	lumber of staircases					
		a	Upper floor	02 nos.	03 nos. ~	MR		
		b	Basement	N/A	N/A	N/A		
	В	V	Vidth of staircases					
		а	Upper floor	1.50 mtrs.	1.2 mtrs. & 02 nos. of 1.0 mtr.	MR		
		b	Basement	N/A	N/A	N/A		
	C	P	rotection of exits					
1		-	Fire check door	N/A	N/A	N/A		
		-	Pressurization	N/A	N/A	N/A		
	D		No. of continuous staircases terrace	01 no.	01 no.	MR		
	E	-	Width of corridor	1.50 mtrs.	1.50 mtrs.	MR		
		-	Door size	1.0 mtr.	1.0 mtr. /	MR		
	F							
3	F	_	partmentation:					
3	F	m		NA	NA	NA		
3	F Co	F	partmentation:	NA N/A	NA N/A	NA N/A		
3	F Co A B C	F S	Partmentation: Fire check door Sealing of electrical shafts Fire rating of shaft door					
3	F Co A B C D	F S F	Partmentation: Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain	N/A N/A N/A	N/A N/A N/A	N/A		
	F Co A B C D E	F S F V	Partmentation: Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain Fire dampers	N/A N/A	N/A N/A	N/A N/A		
3	F Co A B C D E Sr	F S F V	Partmentation: Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain Fire dampers Ke Management System:	N/A N/A N/A N/A	N/A N/A N/A	N/A N/A N/A		
	F Co A B C D E	F S F N N	Partmentation: Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain Fire dampers	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A		

W

5.	Fir	e Extinguisher:	12 nos.	12 nos.	MR				
	A	Total numbers	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR				
	В	Types	ISI Marked	Provided	MR				
	C ISI marking ISI Warked								
6	Fir	st-Aid-Hose Reel:	01 no.	01 no.	MR				
	A	Total numbers of each floor	30 mtrs.	30 mtrs.	MR				
	В	Length of hose reel hose	05 mm	05 mm	MR				
	C Nozzle diameter 03 mm								
7	Automatic Fire Detection and Alarming System:  A Type of detectors N/A N/A								
	A	Type of detectors	N/A	N/A	N/A N/A				
	В	Location of main panel	N/A N/A	N/A	N/A				
	C	Location of repeater panel	N/A	N/A	N/A				
	D	Alternate source of power	N/A	N/A	N/A				
0	E	Hooters	N/A	N/A	N/A				
8	17(0.000)	OEFA:		ASSESSED IN THE PROPERTY OF TH	N/A				
9	-	Public Address System: N/A N/A							
10	-	tomatic Sprinkler System:	27/4	T NIA T	NI/A				
	A	Basement	N/A	N/A	N/A				
	В	Upper floor	N/A	N/A	N/A				
	C	Sprinkler above false ceiling	N/A	N/A	N/A				
11	Internal Hydrants:								
12	A	Size of riser/down-comer	100 mm	100 mm	MR				
	В	Number of hydrants per floor	01 no.	01 no.	MR				
	C	Hose box	01 no.	01 no.	MR				
	-	Yard Hydrants:							
	A	Total number of hydrants	N/A	N/A	N/A				
	B	Hose box	N/A	N/A	N/A				
13	Pumping Arrangements:								
1	Ground level								
	A	Discharge of main pump	N/A	N/A	N/A				
	В	Head of main pump	N/A	N/A	N/A				
	C	Number of main pumps	N/A	N/A	N/A				
	D	Jockey pump out put	N/A	N/A	N/A				
	E	Jockey pump head	N/A	N/A	N/A				
2	F	Standby pump out put	N/A	N/A	N/A				
	G	Standby pump head	N/A	N/A	N/A				
	H	Auto starting /manual stopping	N/A	N/A	N/A				
	I	Pump house access	N/A	N/A	N/A				
2	Terrace Level								
	A	Discharge of pump	450 LPM	450 LPM /	\ \				
	В	Head of the pump	40 mtrs		MI				
	C	Power supply		40 mtrs.	MI				
	D	Auto starting of pump	Required	Provided	MI				
		g Stone Convent School locate	Required	Provided	MI				

Stepping Stone Convent School located at Acharya Niketan, Delhi -110091.



MAP	Stone Convent School located at, Acharya Niketan, Delhi - 110091.  Captive Water Storage for Fire Fighting:							
14	Underground tank capacity		N/A	N/A	N/A			
	4	Draw-off connection	N/A	N/A	N/A			
	B	Draw-off connection	N/A	N/A	N/A			
	¢	Fire service inlet	N/A	N/A	N/A			
	Þ	Access to tank	5,000 ltrs.	5,000 ltrs./	MR			
T	E	Overhead tank capacity	Required	Provided	MR			
15	Exit Signage:		Required	1101141	mysys as as			
16	Provision of Lifts:							
10	1	Pressurization of lift shaft	N/A	N/A	N/A N/A			
	A	Pressurization of lift lobby	N/A	N/A	N/A			
1	В	Communication in lift car	N/A	N/A	N/A			
ļ	C	Communication in interest	N/A	N/A	1.00			
	D	Firemen's grounding switch	N/A	N/A	N/A			
	E	Lift signage	N/A	N/A	N/A			
17	Standby Power Supply:							
18	Refuge Area:		N/A	N/A	N/A			
	A	Total area	N/A	N/A	N/A			
	В	Location	14/71					
19			N/A	N/A	N/A			
-	A	Detector system panel	N/A N/A	N/A	N/A			
	B	Flow switch panel	N/A	N/A	N/A			
	C		N/A	N/A	N/A			
	D	Battery backup	N/A	N/A	N/A			
		Puilding floor plans	N/A	N/A	N/A			
20	C.	pecial Fire Protection systems for otection of special Risks, if any:	1.07.2					

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The earlier shortcomings issued vide letter no. F6/DFS/MS/School/2023/NDZ/415 dated 20.09.2023 by this department have been rectified by the management.

the management.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measured as required under the rules. The FSC issued vide letter no. F6/DFS/MS/School/2018/NDZ/2428 dated 29.10.2018 renewal under the circular no.262-362 dated 17/01/2005 is recommended

Signature of the Inspecting Officer
Name Yashwant Singh Meena
Designation ADO (L.N)

CFQ/ND2

0. - Jon MIR

Director/M/

AMILIN P.T.D