

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/EH/2024/SZ/99 No.

Dated..93/04./2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s KFC Restaurant located at Shop No. 12 & 13, Upper ground floor, Suncity Vasant Square Mall, Vasant Kunj, New Delhi-110070 in the building comprised of two tier basement, lower ground, upper ground plus three upper floors, basement (not part of restt.) ground and three upper floor owned/occupied by M/s Sapphire Foods India, Pvt. Ltd was issued Fire Safety Certificate by this department vide letter no. F6/MS/DFS/EH/SZ/2021/30 dated 04/02/2021. The restaurant premise was re-inspected by the officer concerned of this department on 01/04/2024 in the presence of Mr. Madhu of the restaurant and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" Restaurant and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject/to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 03 /04 /2024 at New Delhi by

DIRECTOR

DEL'HI FIRE SERVICE

Copy to: -

The Joint Commissioner of Police, Lic Unit, 1st Floor PS Defence Colony, New Delhi 110049 (Ref. MHA Portal ID 2024030602642 dated 06/03/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



1	Nam	e & Address of the Building	ON REPORT	oods India, Pvt. Ltd, (K	FC Restaurant	
		ham Prof Belliquest & Salvas Francis	Shop No 12 & 1	3, Suncity Vasant Squar	e Mall, Vasan	
2	Туре	of Occupancy	Kunj, New Delhi-110070 Assembly Building "Group-D" Restaurant			
		ding Comprised of	Two tier Basement, lower ground, upper ground plus 0			
7.2		The state of	upper floors (restaurant running at upper ground floo only)			
4	Type	e of Case	Renewal			
5		ils of Previous NOC	Jan St. Berneller St.	SZ/2021/30 dated 04/02	/2021	
6	_	Safety Directives Letter No		/2005/2251 dated 28/10/		
T. iv		Market of Lawrendich A fact and T	F.6/DFS/MS/Mall/2022/SZ/CMT/566 Dated 13/12/2023 (Vasant Square Mall NOC)			
7	Dat	e of Inspection	01/04/2024			
8	Nar	ne of the Inspecting Officers	DO (South) & ADO (BCP)			
9	Nan	ne & Designation of Officers n the building side	Mr. Madhu			
10		r of construction	2000	a mana bad i dha badan said		
11	50.000	blicant letter No.	MHA Portal ID	2024030602642 dated 0	6/03/2024	
S. No.	Mii	nimum standards on Fire Prevention Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR	
1	Ace	ess to Building. FSC No. F.6/DFS/MS/	Mall/2022/SZ/CM	TT/566 Dated 13/12/2022	Vasant Mall	
		Road width	09 m	Provided *	MR	
		Gate width	05 m	Provided *	MR	
		Width of internal road	06 m	Provided *	MR	
2	Nu	mber, width, type and arrangements o	f exits.	Author there to see 21	6	
3170	a.	Number of Staircase		Maintained by Vasant		
		Upper floors	N/A	Provided *	MR	
		Basement floor	N/A	Provided *	MR	
	b.	Width of Staircase	The state of the	Maintained by Vasant		
		Upper floors	N/A	Provided *	MR	
		Basement floor	N/A	Provided *	MR	
	c.	Protection of exits		Maintained by Vasant		
		Fire check door	Required	Provided *	MR	
		Pressurization	N/A	Provided *	MR	
	d.	No. of continuous staircase to terrace		Provided *	MR	
	e.	Width of corridor	N/A	N/A	N/A	
	f.	Door size	(2 No's Required)	Provided	MR (old case)	
3	Co	mpartmentation.		Maintained by Vasan		
		Fire check door.	Required	Provided *	MR	
		Sealing of electrical shafts.	Required	Provided *	MR	
		Fire rating of shaft door.	2 hrs	Provided *	MR	
		Water curtain	N/A	N/A	N/A	
		Fire dampers.	N/A	N/A	N/A	
4.	Sn	oke Management system.		Maintained by Vasan		
		Basement Upper floors	N/A Required	As above Exhaust fans provided	N/A I MR	
5.	Fi	re Extinguishers.	1963	THE RESERVE OF THE PERSON OF T		
	4	Total numbers	04 Nos	06 Nos.	MR	
	ч	Types		ABC-04, W.CO ₂ -02	MR	
		The second secon	TCI 1			
		ISI Marking	ISI marked	Provided	MR	



आजादी ज अमृत महोत्स	6	W			
असृत महोत्स	f	- 1	7	नाट	311
	N		T	1मृ	3
	۱				

				50.00
	Length of hose-reel hose.	Hose Reel	30m	MR
d. De	Nozzle Diameter		5mm	MR
7	Automatic Fire Detection and Alarming	system. (Provide	ed & Maintained by Vasar	nt Square Mall
	Type of detectors	Required	Provided *	MR
Selection 1	Location of Main Panel	Required	Provided *	MR
il. bui	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided *	MR
	Hooter's location	Required	Provided *	MR
8.	MOEFA	Required	Provided *	MR
9.	Public Address System	Required	Provided *	MR
10.	Automatic Sprinkler System	The second secon	& Maintained by Vasan	- 255
10.	Basement	Required	Provided *	MR
	Upper floors	Required	Provided *	MR
		N/A	N/A	N/A
11	Sprinkler above false ceiling			BI-10
11.	Internal Hydrants.		ovided & Maintained by Vasant Squ	
	Size of Riser/Down-comer	Required	Provided *	MR
	Number of Hydrant per floor	Required	Provided *	MR
	Hose box.	Required	Provided *	MR
12.	Yard Hydrants.		& Maintained by Vasant	-
	Total number of hydrants.	N/A	As above	N/A
	2. Hose box.	N/A	As above	N/A
13.	Pumping arrangements.		nham a	4
	Ground Level		& Maintained by Vasant	Square Mall
	Discharge of main pump.	4500 LPM	Provided *	MR
	➤ Head of main pump.	60 mtr	Provided *	MR
	Number of main pumps.	Two	Provided *	MR
	Jockey Pump output.	2 x 180 LPM	Provided *	MR
	> Jockey Pump head.	60 mtr	Provided *	MR
	> Standby Pump output.	4500 LPM	Provided *	MR
	Standby Pump head.	60 mtr	Provided *	MR
	Auto Starting / Manual Stopping. Access to pump house	Required	Provided *	MR
(1)->	1 11 Tees to pump nouse	Required	Provided *	MR
	Terrace Level	Provided & Maintained by Vasant Square Mall		
	Discharge of pump.	N/A	N/A	N/A
	> Head of pump.	N/A	N/A	N/A
	Power supply.Auto starting of pump.	N/A	N/A	N/A
14.		N/A	N/A	N/A
OLINA:	Captive water storage for Fire Fighting.		Maintained by Vasant S	quare Mall
	 Underground tank capacity. Draw-off connection. 	2,50,000 Ltr	Provided *	MR
93	Fire Service Inlet.	Required	Provided *	MR
	Access to tank.	Required	Provided *	MR
	Overhead tank capacity.	Required	Provided *	MR
15.	Exit Signage.	30,000 Ltr	Provided *	MR
16.	Provision of Lifts.	Required	Provided	MR
	Pressurization of lift shaft.	Provided &	Maintained by Vasant S	quare Mall
	Pressurization of lift lobby.	Required	Provided *	MR
	Communication in lift car.	Required Required	Provided *	MR
	• Fireman's switch.	Required	Provided *	MR
	Lift signage.	Required	Provided *	MR
17	Standby Power Supply		Provided *	MR
18.	Refuge Area	Required	Provided (DG Set)	MR
	Total area	N/A	270	ta ta
	Total area	IVA	N/A	N/A



	Location	N/A	N/A	N/A
19.	Fire Control Room.	Provided & Maintained by Vasant Square Mall		
	Detector System Panel.	Required	Provided *	MR
	 Flow Switch Panel. PA system Panel. Battery backup Building floor plan 	Required	Provided *	MR
		Required	Provided *	MR
		Required	Provided *	MR
		Required	Provided *	MR
20.	Special Fire Protection System for the Protection of special Risk, if any:	Required	Provided *	MR

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/MS/DFS/EH/SZ/2021/30 dated 04/02/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

muy

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Déneter Many 300 M

Uploaded

A