

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/School/SZ/2024/ 284

Dated: 05 04 2024

FIRE SAFETY CERTIFICATE

Certified that the MRS Global School located at Plot NO. 61/62, Opp. Metro Piller No. 33, Main Nangli Dairy 100 ft. Road, Niranjan Park, Najafgarh Road, New Delhi- 110043. The school building comprised of basement, stilt, ground plus three upper floors, but school running at basement (office), stilt (reception), ground floor, first & second floor only and third floor is vacant, owned/occupied MRS Global School have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010, and verified by the officer concerned of this department on 19.03.2024 in the presence of Sh. R.K. Yadav (President) and found that the building/ premises is fit for occupancy class B 'Educational Building' (for basement, stilt, ground, 1st & 2nd floor only) with effect from ...05.04.12024 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 05 04 2024 at New Delhi by.

Director Delhi Fire Service

Copy to:-

 The Principal, MRS Global School located at Plot NO. 61/62, Opp. Metro Piller No. 33, Main Nangli Dairy 100 ft. Road, Niranjan Park, Najafgarh Road, New Delhi- 110043.

2. Director of Education, GNCT of NCT of Delhi, Old Secretariat, New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1 Name & address of the building

: MRS Global School, Plot No. 61/62, Near Nangli Metro Station, Near Nangli Dairy 100 ft Road, Niranjan Park,

New Delhi- 110043.

2. Building is comprised of

: Basement, stilt, ground plus three upper floors, but school

running at basement (office), stilt (reception), ground, 1st

and 2nd floor only and 3rd floor is vacant.

3. Type of Occupancy

Educational

4. Type of Case

New Case

5. Details of Previous NOC

N/A

6. Fire Safety direction letter No

N/A

7. Date of Inspection

19.03.2024

8. Name of the Inspecting Officers:

ADO R.K. YADAV

9. Name of the designation of Officer

from the building side

Mr. R. K. Yadav (President)

10 Year of Construction

S.No	Minimum Standards on fire preven and fire safety requirements U/R 33	ition	Requir	ement	Provided at Site	Remarks MR/NMR	
1	Access to building						
	Road width	6 m		06 m		MR	
	Gate width	4.5		Direct	accessible from road	MR	
	Width of internal road	N.A.		N.A.		N.A.	
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases				THE PARTY AND ADDRESS OF THE PARTY AND ADDRESS		
	Upper Floor	02 n	os.	2 no	s.	MR	
	Basement	02 n	os.	2 nos		MR	
	B. Width of Staircases						
	Upper Floor	1.5 n	n each	Provi	ded	MR	
	Basement	1.5 n	n each	Provi	ded	MR	
	c. Protection of exits						
	Fire check door	N.A.	181	N.A.		N.A.	
	Pressurization	N.A.		N.A.			
	e. No. of continuous staircases to terrace g. Width of Corridor	01		Provided		N.A.	
		Requ	ired	Provided		MR	
	h. Door Size	1 m	incu			MR	
3	Compartmentation.	1 111		1.10	m (double door)	MR	
	Fire check door				11-11-11		
	1929	N.A.		N.A.		N.A.	
	Sealing of electrical shafts Fire rating of shaft door	N.A.		N.A.		N.A.	
	Water curtain	N.A.	AF III	N.A.	5 24 9 7	N.A.	
	Fire Dampers	N.A.		N.A.		N.A.	
4	Smoke Management System.	N.A.		N.A.		N.A.	
	Basement		Required		Provided		
101	Upper floor	Requ	quired Natural ventilation		al ventilation	MR MR	

5,	Fire Extinguisher						
	Total numbers	07 Nos.	07 Nos.	MR MR			
	types	CO ₂ & ABC	CO ₂ & ABC	MR			
	IS marking	ISI marked	ISI marked	IVIK			
5	First-aid-Hose Reels. Total numbers of each floor 01 MR						
	Total numbers of each floor	01 at each floor	01	MR			
	Length of hose reel hose	30 m	30 m	100 MARCHES			
	Nozzle diameter	5 mm	5 mm	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	N.A.	N.A.	N.A.			
	Location of main panel	N.A.	N.A.	N.A.			
	Location of repeater panel	N.A.	N.A.	N.A.			
	Alternate source of power	N.A.	N.A.	N.A.			
	Hooters	N.A.	N.A.	N.A.			
8	MOEFA	N.A.	N.A.	N.A.			
9	Public address System.	N.A.	N.A.	N.A.			
10	Automatic Sprinkler System.						
	basement	Required	Provided	MR			
	upper floor	N.A.	N.A.	N.A.			
	sprinkler above false ceiling	N.A.	N.A.	N.A.			
11	Internal Hydrants	13.42.5	1				
11	size of riser/down-comer	N.A.	N.A.	N.A.			
	Number of hydrants per floor	N.A.	N.A.	N.A.			
	Hose Box	N.A.	N.A.	N.A.			
12	Yard Hydrants.	72.11.21		New Mean Section 1			
12	Total number of hydrants	N.A.	N.A.	N.A.			
	Hose Box	N.A.	N.A.	N.A.			
13	Pumping Arrangements.						
13	Ground Level	N.A.	N.A.	N.A.			
	➤ Discharge of main Pump	N.A.	N.A.	N.A.			
	➤ Head of Main Pump	N.A.	N.A.	N.A.			
	> Number of main pumps	N.A.	N.A.	N.A.			
	> Jockey pump out put	N.A.	N.A.	N.A.			
	> Jockey pump head	N.A.	N.A.	N.A.			
	> Standby pump out put	N.A.	N.A.	N.A.			
	> Standby pump Head	N.A.	N.A.	N.A.			
	➤ Auto Starting /Manual	N.A.	N.A.	N.A.			
	stopping	N.A.	N.A.	N.A.			
	> Pump House Access	S.M. M.	- 10.40	11.2			
	Terrace Level	900 LPM	900 LPM	MR			
	Discharge of pump	40 m	40 m	MR			
	Head of the Pump	Required	Provided	MR			
	Power supply	Required	Provided	MR			
	> Auto Starting of pump		1.5	.,			
14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	N.A.	50,000 ltrs	N.A.			
	Draw-off connection	N.A.	N.A.	N.A.			
	Fire service inlet	N.A.	N.A.	N.A.			
	Access to tank	N.A.	N.A.	N.A.			
	Overhead Tank capacity	10,000 ltrs	15,000 ltrs	MR			
15	Exit Signage.	Required	Provided	MR			

16	Provision of Lifts.					
	Pressurization of Lift Shaft Pressurization of Lift lobby Communication in lift car Firemen's grounding switch Lift Signage	N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
17	Standby power supply	N.A.	N.A.	N.A.		
18	Refuge Area.					
	Total area Location	N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
19	Fire Control Room					
	Detector system panel Flow switch panel PA system panel Batter backup Building Floor Plans	N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
20	Special Fire Protection systems for protection of special Risks, if any:	N.A.	N.A.	N.A.		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Note: As per undertaking (placed at C-06) building height is 14.96 mtrs. and School building comprised of basement, stilt, ground plus three upper floors, but school running at basement (office), stilt (reception), ground floor, first & second floor only and third floor is vacant.

Keeping in view of the above compliance of the minimum standards of fire prevention and fire safety measures under Rule 35 of the Delhi Fire Service Rules 2010, it's recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer 2004

Name- R.K. Yadav Designation- ADO (JKP)

DO (South West)

Director My 100

Maker