GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No.F6/DFS/MS/GH/NDZ/2024/81

Dated: 05/ 04/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Prince Hotel situated at 751, Church Mission Road, Fatehpuri, Delhi - 06, comprised of ground + 04 upper floors, ground floor – (commercial use), 1st floor- (store room and reception), 2st floor & 3^{rt} floor - (11 guest rooms at each floor) & 4th floor - (02 store room & 01 toilet (sealed), total 22 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/NDZ/2020/GH/15 dated 08.01.2021. The premises was re-inspected by the officer concerned of this department on 27.03.2024 in presence of Mr. Mukesh Kumar Gupta (Owner) and found that the building is comprised of ground + 04 upper floors and now the floor wise occupancy is ground floor – (commercial use), 1st floor – (store room + reception), 2st floor- (11 guest rooms), 3rd floor - (11 guest room) & 4th floor – (not in use as per affidavit dated 26.03.2024). The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of class "Residential" Group-A-1)", 2th floor & 3rd floor - (11 guest rooms at each floor) for total 22 guest rooms upto 3rd floor only, with effect from ... 55... 2.4.1.20.2.4.1. for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on .0.5 04 20.24 at New Delhi by

Director Deini Fire Service

Tel: 011-23414000

Copy to:-

- 1. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above & deviation, if any.
- The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2024031402982 dated 14.03.2024.
- 3. The Licensee, M/s Prince Hotel at 751, Church Mission Road, Fatehpuri, Delhi 06.

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 9. The occupancy of above 3rd floor not allowed as per clause 7.31 in UBBL-2016.

N/47-

ī	Name & address of the building		M/s Prince Hotel situated at 751, Church Mission Road, Fatehpuri, Delhi.			
	Building is comprised of		Ground + 04 upper floors			
2	Building is comprised of	Ground floor - (co				
		1 st floor – (store room + reception)				
	*	2nd & 3rd floor - (1)	guest rooms at each	n floor)		
	1	4th floor - (not	2 nd & 3 rd floor - (11 guest rooms at each floor) 4 th floor - (not in use as per affidavit date			
		W STANDARD C				
	-4	26.03.2024)				
3	Type of Occupancy	Residential Group A-1				
4	Type of Case	Renewal F6/DFS/MS/NDZ/2020/GH/15 dated 08.01.2021				
5	Details of Previous FSC	F6/DFS/MS/NDZ/2	020/GH/13 dated 08	.01.2021		
6	Fire Safety direction letter No	Nil				
7	Date of Inspection	27.03.2024				
8	Name of the Inspecting Officers	Sumit Kumar, ADO	(SPM)			
9	Name of the designation of Officer	TAXLES CONTRACTOR CONT	Mr. Mukesh Kumar Gupta (Owner)			
	from the building side					
10	Year of Construction	1980				
	Applicant's letter No	Online application	I.D No. 202403140	2982 dated		
11	Applicant's letter No	14.03.2024				
CN	Minimum Standards on fire		Provided at Site	Remark		
S.No	Mannana Stanton -	Service and territories remains a constant designation	- 1 - 1 - 1	S		
	A LUTUM HILL	arrangements		MR/NM		
	requirements U/R 33	arrangements		R		
1	Access to building	6 m	30 m	MR-		
	Road width	, terrorista.	NA	NA		
	Gate width	NA NA	NA	NA		
_	Width of internal road Number, Width, Type and Arran	(CONTROLL)	IW	1		
2	A. Number of Staircases	gement of Exits				
		01 no.	01 no.	MR		
	Upper Floor Basement	NA	NA NA	NA		
	505-36-5-46-5-46-5-5-5-5-5-5-5-5-5-5-5-5-5-5-	INA	14/1			
	B. Width of Staircases Upper Floor	80 cms	82 to 120 cms	MR		
	Basement	NA	NA NA	NA		
	C. Protection of exits	1111				
	Fire check door	Required	Provided	MR		
	Pressurization	NA	NA	NA		
	Pressurization	11/1		NIA		
	D. No. of continuous staircases to	NA	NA	NA		
	D. No. of continuous staircases to terrace	NA _				
	D. No. of continuous staircases to terrace E. Width of Corridor		NA NA	NA NA		
	D. No. of continuous staircases to terrace E. Width of Corridor G. Door size	NA _				
3	D. No. of continuous staircases to terrace E. Width of Corridor G. Door size Compartmentation	NA NA	NA	NA		
3	D. No. of continuous staircases to terrace E. Width of Corridor G. Door size Compartmentation Fire check door	NA NA 1.0 m	NA 1.0 m	NA MR		
3	D. No. of continuous staircases to terrace E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts	NA 1.0 m NA NA	NA 1.0 m	NA MR		
3	D. No. of continuous staircases to terrace E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts Fire rating of shaft door	NA 1.0 m NA NA NA NA	NA 1.0 m NA NA NA	NA MR		
3	D. No. of continuous staircases to terrace E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain	NA 1.0 m NA NA NA NA NA NA	NA 1.0 m NA NA NA NA	NA MR		
	D. No. of continuous staircases to terrace E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain Fire Dampers	NA 1.0 m NA NA NA NA	NA 1.0 m NA NA NA	NA MR NA NA		
3	D. No. of continuous staircases to terrace E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain Fire Dampers Smoke Management System.	NA NA 1.0 m NA NA NA NA NA NA NA	NA 1.0 m NA NA NA NA NA NA NA	NA MR NA NA NA NA NA		
	D. No. of continuous staircases to terrace E. Width of Corridor G. Door size Compartmentation Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain Fire Dampers	NA 1.0 m NA NA NA NA NA NA	NA 1.0 m NA NA NA NA	NA MR NA NA NA		

- N/48-

5.	Fire Extinguisher			
	Total numbers	05 nos.	08 nos.	M
	types	CO ₂ & ABC	CO ₂ & ABC	MI
	IS marking	Required	Provided	
6	First-aid-Hose Reels.			MI
0	Total numbers of each floor	01 no.	01 no.	MI
	Secretary of Security Co. Sec. Sec. Sec. Sec. Sec. Sec. Sec. Sec	30 m	30 m	MI
	Length of hose reel hose	5 mm	5 mm	
	Nozzie diameter			MR
7	Automatic fire detection and a	Dequired	Provided	MR
	Type of detectors (CO type)	Required	Provided	NA NA
	Location of main panel	Required NA	NA	MR
	Location of repeater panel	Required	Provided	MR
	Alternate source of power	Required	Provided	NA
	Hooters	NA NA	NA itad	MR
8	MOEFA	Required	Provided	
9	Public address System.	T.C.		NA
10	Automatic Sprinkler System.	NA	NA	NA
	Basement	NA NA	NA	NA NA
	Upper floor	NA NA	NA	INA
	Sprinkler above false ceiling	NA .		-1:54
11	Internal Hydrants	1	NA	NA
11	size of riser/down-comer	NA	NA	NA
	Number of hydrants per floor	NA	NA	NA
	Hose Box	NA		
12	Yard Hydrants.		NA	NA
14	Total number of hydrants	NA	NA	NA
	Hose Box	NA	INA	
	Pumping Arrangements.			
13	- Ground Level		NIA	NA
	> Discharge of main Pump	NA -	NA	NA
	➤ Head of Main Pump	NA ·	NA	NA
	> Number of main pumps	NA	NA	
	> Jockey pump out put	NA	NA	NA
	> Jockey pump head	NA	NA	NA
	> Standby pump out put	NA	NA	NA
	> Standby pump Head	NA	NA	NA
	> Auto Starting /Manual stopping	NA	NA	NA
	> Pump House Access	NA	NA	NA
	Terrace Level			
	➢ Discharge of pump	450 LPM	450 LPM	MR
-	➤ Head of the Pump	30 m	30 m	MR
	> Power supply	Required	Provided	MR
-	> Auto Starting of pump	Required	Provided	MR

CA

4

14	Captive Water Storage for Fire Fighting.				
	Underground tank capacity	NA	NA	NA	
	Draw-off connection	NA	NA	NA	
	Fire service inlet	NA	NA	NA	
	Access to tank	NA	NA	NA	
	TO SAISSANCE.	.5,000 ltrs	5,000 ltrs	MR	
	Overhead Tank capacity	Required	Provided	MR	
15	Exit Signage.				
16	Provision of Lifts.	Control of the contro	NA	NA	
	Pressurization of Lift Shaft	NA	NA NA	NA	
	Pressurization of Lift lobby	NA	NA NA	NA	
	Communication in lift car	NA NA	NA	NA	
	Firemen's grounding switch	NA .		NA	
	Lift Signage	NA	NA .	MR	
17	Standby power supply	Required	Provided	IVII	
18	Refuge Area.			NA	
10	Total area	NA	NA	THE CONTRACTOR	
		NA	NA	NA	
	Location				
19	Fire Control Room	NA	NA	• NA	
	Detector system panel	NA NA	NA	NA	
	Flow switch panel	NA NA	NA	NA	
	PA system panel	NA NA	NA	NA	
	Batter backup	NA NA	NA	NA	
	Building Floor Plans		NA	NA	
20	Special Fire Protection systems special Risks, if any:	ior protection or			

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/NDZ/2020/GH/15 dated 08.01.2021 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Sumit Kumar Designation ADO (SPM)

DO(C)

Dyes (202)

on MR

Director My NA

Arryspm