

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/107

Dated...10/04/2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of **M/s Diva Restaurant** located at **Ground & First Floor, M-8**, Greater Kailash-II, M-Block Market, New Delhi 110048 in the building comprised of Basement, Ground plus Three Upper Floors owned/occupied by A Unit of RIGA Foods LLP was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH/SZ/2021/117 dated 24/06/2021. The restaurant premise was re-inspected by the officer concerned of this department on 02/04/2024 in the presence of Mr. Ramesh Panday (Manager) of the restaurant and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building"** Restaurant and **validity upto 31/03/2027** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10/04/2024 at New Delhi by


(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police, Lic Branch, 1st Floor PS Defence Colony, New Delhi 110049 (Ref. MHA Portal ID 2024021901819 dated 14/03/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

M/38

INSPECTION REPORT



1	Name & Address of the Building	M/s Diva Restaurant, (A Unit of RIGA Foods LLP) M-8, Greater Kailash-II, M-Block Market, New Delhi 110048		
2	Type of Occupancy	Group-D Assembly Building.		
3	Building Comprised of	Basement, Ground + Three upper floors		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/EH /SZ /2021/117 dated 24/06/2021		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	02/04/2024		
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Ramesh Panday (Manager)		
10	Year of construction	1990 Restt. at ground, 1 st floor of the bldg.		
11	Applicant letter No.	MHA Portal ID 2024021901819 dated 14/03/2024		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	Accessible (4-5m)	Provided	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	02 Nos	03 Nos	MR
	➤ Basement floor.	N/A	Not part of Restt.	N/A
	b) Width of Staircase			
	➤ Upper floors	Required	1.1m, 1.1m, 0.8m	MR (old case)
	➤ Basement floor	N/A	N/A	N/A
	c) Protection of exits			
	➤ Fire check door	N/A	N/A	N/A
	➤ Pressurization	N/A	N/A	N/A
	d) No. of continuous staircase to terrace	N/A	N/A	N/A
	e) Width of corridor	N/A	N/A	N/A
	f) Door size	2 exits	1.05 m & 0.95 m	MR (old case)
3	Compartmentation.			
	• Fire check door.	N/A	N/A	N/A
	• Sealing of electrical shafts.	N/A	N/A	N/A
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4	Smoke Management system.			
	• Basement	30 ACPH	N/A	N/A
	• Upper floors	12 ACPH	Exhaust Fans Provided	MR
5	Fire Extinguishers.			
	• Total numbers	08 Nos	08 Nos	MR
	• Types	ABC/CO ₂	ABC-06 & CO ₂ -02	MR
	• ISI Marking	ISI marked	Provided	MR
6	First Aid Hose Reels.			
	• Total numbers on each floor.	One at each	Provided	MR
	• Length of hose-reel hose.	30m	Provided	MR
	• Nozzle Diameter	5mm	Provided	MR
7	Automatic fire detection & alarming system.			
	• Type of detectors	N/A	N/A	N/A

2/39

	<ul style="list-style-type: none"> • Location of Main Panel • Location of Repeater Panel • Alternate source of power • Hooter's location 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	MR
8	MOEFA	Required	Provided	N/A
9	Public Address System	N/A	N/A	
10	Automatic Sprinkler System			N/A
	<ul style="list-style-type: none"> • Basement 	N/A	N/A	M/R
	<ul style="list-style-type: none"> • Ground floor & above floor 	Required	Provided	N/A
	<ul style="list-style-type: none"> • Sprinkler above false ceiling 	N/A	N/A	
11	Internal Hydrants.			N/A
	<ul style="list-style-type: none"> • Size of Riser/Down-comer 	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Number of Hydrant per floor 	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Hose box. 	N/A	N/A	
12	Yard Hydrants.			N/A
	<ul style="list-style-type: none"> • Total number of hydrants. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Hose box. 	N/A	N/A	
13	Pumping arrangements.			
	<ul style="list-style-type: none"> • Ground Level 			N/A
	<ul style="list-style-type: none"> ➤ Discharge of main pump. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Head of main pump. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Number of main pumps. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Jockey Pump output. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Jockey Pump head. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Standby Pump output. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Standby Pump head. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Auto Starting/Manual Stopping. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Pump house access. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Terrace Level 			MR
	<ul style="list-style-type: none"> ➤ Discharge of pump. 	450LPM	450 LPM	MR
	<ul style="list-style-type: none"> ➤ Head of pump. 	40 m	Provided	MR
	<ul style="list-style-type: none"> ➤ Power supply. 	Required	Provided	MR
	<ul style="list-style-type: none"> ➤ Auto starting of pump. 	NA	Provided	NA
14	Captive water storage for fire fighting.			
	<ul style="list-style-type: none"> • Underground tank capacity. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Draw-off connection. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Fire Service Inlet. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> ➤ Access to tank. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Overhead tank capacity. 	5,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> • Pressurization of lift shaft. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Pressurization of lift lobby. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Communication in lift car. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Fireman's switch. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Lift signage. 	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	<ul style="list-style-type: none"> • Total area 	N/A	N/A	N/A
	<ul style="list-style-type: none"> • Location 	N/A	N/A	N/A
19	Fire Control Room.			
	<ul style="list-style-type: none"> • Detector system panel. 	N/A	N/A	N/A

2/10



	• Flow switch panel.	N/A	N/A	N/A
	• PA system panel.	N/A	N/A	N/A
	• Battery backup.	N/A	N/A	N/A
	• Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/SZ/2021/117 dated 24/06/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Manoj
Signature of the Inspection Officer
Name: Sh. Manoj Kumar Sharma
Design: DO (South)

Sh. Rajesh Kumar
Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Design: ADO (BCP)

CFO (HQ)

Nugh
5/4/2024

Director
5/4/24

ADO/BCP

As apporoned, F-1 letter is for sub
for your signature P/

1/4
21/4/24

Director
10/04/24

MSL

Uploaded
12/4/24

[Signature]