

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/EH/2024/SZ/106

Dated..10/04/2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of **M/s Gola Sizzlers Pvt Ltd**, located at **T-318, 3rd Floor** Ambience Mall Vasant Kunj, New Delhi 110070 in the building comprised of 03 tier Basement, Ground plus Three upper floors owned/occupied by M/s Gola Sizzlers Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2014/SZ/682 dated 05/06/2014. The restaurant premise was re-inspected by the officer concerned of this department on 02/04/2024 in the presence of Mr. Manik Kapoor and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building"** (Restaurant at 3rd Floor only) and **validity upto 31/03/2027** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10/04/2024 at New Delhi by


ATUL GARG
DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-110016 (Ref. MHA Portal ID 2024031603107 dated 16/03/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The basement shall be used as per the provisions of BBL /NBC Part- IV.
5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

N/18

INSPECTION REPORT				
1	Name & Address of the Building	M/s Gola Sizzlers Pvt Ltd, located at T-318, 3 rd Floor, Ambience Mall Vasant Kunj, New Delhi 110070		
2	Type of Occupancy	Restaurant running at 3 rd Floor		
3	Building Comprised of	Three tier Basement, Ground + 03 upper floors		
4	Type of Case	Renewal / Name Change		
5	Details of Previous NOC	F6/DFS/MS/EH/2014/SZ/682 dated 05/06/2014 for the name of Striker Restaurant		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	02/04/2024		
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Manik Kapoor		
10	Year of construction	2001		
11	Applicant letter No.	MHA Portal ID 2024031603107 dated 16/03/2024		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR
1	Access to Building. FSC No.F.6/DFS/MS/Mall/2023/SZ/35 Dated 25/01/2023 of Ambience Mall			
	• Road width	9m	Provided *	MR
	• Gate width	5m	Provided *	MR
	• Width of internal road	6m	Provided *	MR
2	Number, width, type and arrangements of exits.			
	a. Number of Staircase	Provided & Maintained by Ambience Mall		
	• Upper floors	02 Nos	17 Provided *	MR
	• Basement floor	02 Nos	Provided *	MR
	b. Width of Staircase	Provided & Maintained by Ambience Mall		
	• Upper floors	1.50 mtr	Provided *	MR
	• Basement floor	Required	Provided *	MR
	c. Protection of exits	Provided & Maintained by Ambience Mall		
	• Fire check door	Required	Provided *	MR
	• Pressurization	Required	Provided *	MR
	d. No. of continuous staircase to terrace	Required	Provided *	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	1.50 mtr each	1.50 mtr & 1.50 mtr	MR
3	Compartmentation.			
	• Fire check door.	Required	Provided *	MR
	• Sealing of electrical shafts.	Required	Provided *	MR
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4.	Smoke Management system.			
	• Basement	Required	Provided *	MR
	• Upper floors	Required	Exhaust fans provided	MR
5.	Fire Extinguishers.			
	• Total numbers	06 Nos	06 Nos.	MR
	• Types	ISI marked	ABC-04, W.CO ₂ -02	MR
	• ISI Marking	ISI marked	Provided	MR
6.	First Aid Hose Reels.			
	• Total numbers on each floor.	Hose Reel	05 Each floor	MR
	• Length of hose-reel hose.		30m	MR
	• Nozzle Diameter		5mm	MR
7	Automatic Fire Detection and Alarming system. (Provided & Maintained by Ambience Mall)			
	• Type of detectors	Required	Smoke & Heat	MR

	<ul style="list-style-type: none"> Location of Main Panel Location of Repeater Panel Alternate source of power Hooter's location 	Required	Provided *	MR
		N/A	N/A	N/A
		Required	Provided *	MR
		Required	Provided *	MR
8.	MOEFA	Required	Provided *	MR
9.	Public Address System	Required	Provided *	MR
10.	Automatic Sprinkler System	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> Basement 	Required	Provided *	MR
	<ul style="list-style-type: none"> Upper floors 	Required	Provided *	MR
	<ul style="list-style-type: none"> Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> Size of Riser/Down-comer 	Required	Provided *	MR
	<ul style="list-style-type: none"> Number of Hydrant per floor 	Required	Provided *	MR
	<ul style="list-style-type: none"> Hose box. 	Required	Provided *	MR
12.	Yard Hydrants.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> Total number of hydrants. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> 2. Hose box. 	N/A	N/A	N/A
13.	Pumping arrangements.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main pump. Head of main pump. Number of main pumps. Jockey Pump output. Jockey Pump head. Standby Pump output. Standby Pump head. Auto Starting / Manual Stopping. Access to pump house 	4500 LPM	Provided *	MR
		70 mtr	Provided *	MR
		Two	Provided *	MR
		450 LPM	Provided *	MR
		70 mtr	Provided *	MR
		4500 LPM	Provided *	MR
		70 mtr	Provided *	MR
		Required	Provided *	MR
		Required	Provided *	MR
	<ul style="list-style-type: none"> Terrace Level <ul style="list-style-type: none"> Discharge of pump. Head of pump. Power supply. Auto starting of pump. 	Provided & Maintained by Ambience Mall		
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
14.	Captive water storage for Fire Fighting.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> Underground tank capacity. <ul style="list-style-type: none"> Draw-off connection. Fire Service Inlet. Access to tank. 	5,00,000 Ltrs	Provided *	MR
		Required	Provided *	MR
		Required	Provided *	MR
		Required	Provided *	MR
		20,000 Ltrs	Provided *	MR
	<ul style="list-style-type: none"> Overhead tank capacity. 	Required	Provided *	MR
15.	Exit Signage.	Provided & Maintained by Ambience Mall		
16.	Provision of Lifts.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> Pressurization of lift shaft. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Pressurization of lift lobby. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Communication in lift car. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Fireman's switch. 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Lift signage. 	N/A	N/A	N/A
17.	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> Total area 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Location 	N/A	N/A	N/A
19.	Fire Control Room.	Provided & Maintained by Ambience Mall		
	<ul style="list-style-type: none"> Detector System Panel. 	N/A	As above	N/A
	<ul style="list-style-type: none"> Flow Switch Panel. 	N/A	As above	N/A

	• PA system Panel.	N/A	As above	N/A
	• Battery backup	N/A	As above	N/A
	• Building floor plan	N/A	As above	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	As above	N/A

Note- Fire safety arrangement provided and maintained by Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 677 dated 19/12/2023.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2014/SZ/682 dated 05/06/2014 for the name of Striker Restaurant, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended for the name of M/s Gola Sizzlers Pvt Ltd.

Accordingly, DFA is put up for approval and signature please.

Manoj Kumar Sharma
Signature of the Inspection Officer
Name: Sh. Manoj Kumar Sharma
Design: DO (South)

Rajesh Kumar
Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Design: ADO (BCP)

CFO (HQ) *online MHA portal case.*

Director
5/11/2024
5/14/24
17/11/24

As approved, F.T. letter is put up for your signature pl.

1/14
9/14/2024

Director
10/14/24

Mus

Uploaded
12/14/24

[Signature]