CIST

FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE [Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/DFS/MS/2022/SZ/ 573

Dated: 1/ //2/2022

FIRE SAFETY CERTIFICATE

Certified that the building of Bensups Hospital (B R Dhawan Memorial Charitable Trust), Located at Dwarka Sector - 12, New Delhi - 110078 running at Ground + 02 Upper Floors in a building comprised of Basement + Ground + 04 Upper Floors owned/occupied by B.R Dhawan which was Charitable issued Fire Safety Certificate F6/DFS/MS/Hospital/2019/SZ/1390, dated 05/07/2019. The premises was re inspected by the team of officers concerned of this department on 30/11/2022 in the presence of Mr. Uday (Owner) and found that the said building at Ground + 02 floors have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class " Institutional" Group C (Ground + 02 Upper Floors) with effect from 16/12/2022 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 16 12 2027 at New Delhi by.

(Director)

Copy to: -

- Directorate General of Health Service F-17, Arjun Gali Karkardooma-Anand Vihar, New Delhi-110032.
- The Bensups Hospital (B R Dhawan Memorial Charitable Trust), Dwarka Sector 12, New Delhi – 110078.

Following fire safety directives must be adhered to:-

- The FSC shall be Null & Void if basement, 3rd & 4th floors are used for any purpose.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- The trained staff should be available round the clock.
- Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- Basement shall be used as per building bye laws.
- The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expired.

INSPECTION REPORT

 Name & address of the building: Bensups Hospital (B R Dhawan Memorial Charitable Trust), Dwarka Sector – 12, New Delhi – 110078.

Type of Occupancy : Institutional (Hospital) running at Ground + 02
 Upper Floors in a building comprised of B+G+ 04 UF

3. Type of Case

: Renewal

 Details of previous NOC : F6/DFS/MS/Hospital/2019/SZ/1390, dated05/07/2019

 Fire Safety directives L. No.:F6/DFS/MS /BP/2002/hospital/52 dated 21/01/02

6. Date of inspection

: 30/11/2022

7. Name of the Inspecting Officer: DO/SW & ADO (DWK)

8. Name and designation of Officer:

from the building side Mr Uday (Owner)

9. Year of Construction

:2006

10. Applicant's letter No.

: Email dated - 18/12/2022

No	Minimum standards on fire prevention and fire safety U/R	33	As per N N/21 & 1		Prov site	ided at	Ren	arks M	R/NMR	
~	Access of building									
	Road width	09 m		1.5	Provided		MR			
	 Gate width 	4.5	4.5 m		Provided		MR			
	road		6 m		Provided		MR			
2.	Number, width, Type & Arran	geme	nts of exi	ts						
	a. Number of staircases									
	Upper floors Basements		03 Nos.& Ramp			Provided M		IR .		
			04 Nos & Ramp			Provided MR		l l		
	 Width of staircases 									
	Basements						MR being old case			
							MR	being old case		
	c. Protection of exits									
	Pressurization No of continuous staircase to terrace Width Of Corridor Door Size	Required Pro			rovided	vided at G, 1 st & 2 nd F MR				
		Required				Provided			MR	
		03		Provided			MR			
		2 m		Provided		MR				
-		2 m Provi			1	being old case				
3.						17711		iu case		
	Fire check door		Required		Prov	Provided at G, 1st &		2 nd F	MR	
	Sealing of electrical shafts Fire Rating of shaft door Water Curtain	Required			Provided		MR			
		Re	Required		Provided		MR			
		NA		NA	NA		NA			
	Fire Dampers		Required		Prov	Provided		MR		

N/30

4.	Smoke managements System			_				
	Basements Upper floors	NA	*		Basement r	ot in	NA	
	En Part 1.1	12a	c per hour		Provided		MR	
5.	Types IS marking		10 nos. ABC &CO2, ISI marked		Provided Provided ISI marked		MR MR MR	
6.	First – Aid Hose Reels Total numbers on each floor Length of hose reel hose Nozzle diameter Automatic fire detection and alarmi		101		D 11.1		1 m	
			se 30 m 5 mm		Provided Provided Provided		MR MR MR	
-								
7.				TN	IA		NA	
	Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power		Required Required		NA Provided		MR	
			Required		Provided		MR	
			ired	Provided			MR	
	Hooters' Location	Requ	equired Provided		d Strategic loca		MR	
8.	MOEFA	Requ	ired	Provided		_	MR	
).	Public Address System	Requ		P	rovided		MR	
0.	Automatic Sprinkler System		-					
	Basements	Requ		_	1011000		MR MR	
	Upper Floor Sprinkler above false ceiling		Required NA				NA .	
1.	Internal Hydrants:							
1.	Size of riser/down- comer Number of hydrants per floor Hose Box		****				MR MR	
			01		Provided M		\	
2,	Yard Hydrants		Required	Dr	ovided	MR		
Total number of hydrants Hose Box		ts	34 A. W. St. St. St. St. St. St. St. St. St. St				MR	
3.	Pumping Arrangements:	-		_		_		
	 Ground Level Discharge of main pump Head of main pump 		2850 lpm		Provided		MR	
			70 mtr		Provided			
	Contraction of the contraction	01	-12-20	Pro	ovided	MR		
	 Number of main pumps Jockey pump out put 	180	lpm		21100			
	> Jockey pump head	70 n			vided N			
	 Standby Pump out put Standby Pump Head Auto Staring/Manual stopping 		50 lpm Prov		P. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		IR	
1			70 mtr				MR	
			Required		1100.000		MR MR	
			Require		Tronden			
	 Discharge of pump 	NA		NA	NA NA			
	Head of the pump	NA		NA				
			NA NA		1 1 A			
	> Auto starting of pump	NA		NA	N/		1	

			IA				
14.	Captive water Storage for fire Under ground tank capacity Draw off connection Fire service inlet Access to tank Overhead Tank capacity	Requ Requ Requ 20,0	uired uired uired 00 Litres	Pro Pro Pro	vided vided vided vided vided	MR MR MR MR MR	
	Exit Signage	Req	uired	Pro	vided	MR	
15	Provision of Lifts Pressurization of Lift S Pressurization of lift lo Communication in lift Fireman's Grounding Switch Lift Signage	Car	Required NA Required Required Required	Pro Pro	wided wided wided wided	MR NA MR MR MR	
17.	Standby power supply	Req	uired	A.s.	110,000		
18.	Refuge Area	NA NA			NA		
-	> Total area	NA		NA NA		NA	
	> Location	NA !					
19.	Fire control room Detector system panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans		Requ NA		Provided NA	MR NA	
			Requ	ired	Provided	MR	
			Required		Provided	MR	
			Requ		Provided	MR	
20.	Special Fire Protection Systems for Protection of special Risks, if any;			ired	CO2 fire ext provided near elect	inguisher MR ric panel	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter No. F6/DFS/MS/Hospital/2019/SZ/1390. dated 05/07/2019 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note: - The FSC shall be Nulle Void if basement, 3rd & 4th floors are used for any purpose. The management has submitted in weiter (C-15) that basement, 3rd and 4th floor one not in like

Signature of the Inspecting Officer
Name Sh. Ved Pd

Designation

Signature of the Inspecting Officer Name Uola

Designation