

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001**



No F 6 / DFS / MS / 2024 /School/WZ/ 308

Dated 12/04/2024

FIRE SAFETY CERTIFICATE

Certified that the Satyawati Shiksha Niketan located at Tigipur Road, Bakhtawar Pur, Delhi-110036 comprised of Ground plus First floor was issued FSC by this department vide letter No F6 /DFS/MS/2018/School/WZ/979 dated 09.05.2018. The premises was re-inspected by the officer concerned of this department on 01.04.2024 in the presence of Sh. Kuldeep Sharma (Manager), and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 262-362 dated 17.01.2005 and the building/ premise is fit for occupancy Group B Educational with effect from12.04.12a24.. for a period of three years, subject to compliance of the conditions mentioned

Issued on .. 12 04 2024 .. at New Delhi by

Ph. 011-23414000

our

Copy to:-

1. The Director, Education, Government of NCT of Delhi. Old Sect. Delhi-110054

2. The Principal, Satyawati Shiksha Niketan, Tigipur Road, Bakhtawar Pur, Delhi-110036.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the

occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT

1. Name & address of the building: Satyawati Shiksha Niketan, located at Tigipur Road, Bakhtawarpur,

Delhi- 110036.

: Educational 2. Type of Occupandy

Ground + First Floor. **Building Comprised of** 3.

Renewal 4. Type of Case

F6/DFS/MS/2018/School/WZ/979 dated 09/05/2018 5. Details of Previous NOC DOE circular dated 17/01/2005 & as per N-1

6. Fire Safety directives letter No 01/04/2024 Date of inspection

R.K.Sinha, ADO (BW) 8. Name of Inspecting Officer

9. Name and designation of officers

Sh. Kuldeep Sharma (Manager) From the building side

2002 as per N-9 10. Year of Construction

S. No.	11. Applicant's letter No. Minimum Standards on fire prevention and fire safety U/R 3	: Outdoor Diary No. 1418 DOE/ Requirement letter dated 30/11/2006	Provided at site	Remarks MR/NMR			
1.	Access to building	55 letter dated 50/11/2000		1,2241,11,221			
1.	Road width	6 m	6 m	MR			
	Gate width	4.5 m	3.5 m	MR(old case)			
	Width of internal road	NA	NA	NA			
2.	Number, Width, Type & Arran	gement of Exits					
	a. Number of staircases						
	Upper Floors	01	02	MR(old case)			
	Basements	NA	NA	NA			
	b. Width of staircases						
	Upper Floor	1.50 m	1.5 m & 1.30 m	MR			
	Basements	NA	NA	NA			
	c. Protection of exits						
	Fire check door	NA	NA	NA			
	Pressurization	NA	NA	NA			
	d. No. of continuous staircases to terrace	o NA	NA	NA			
	e. Width of Corridor	NA	NA	NA			
	f. Door Size	1 m	Provided	MR			
3.	Compartmentation			-			
4.	Fire check door	NA	NA	NA			
			NA	NA			
	Sealing of electrical shafts Fire Rating of shaft door	NA NA	NA	NA			
		NA NA	NA NA	NA NA			
	Water Curtain Fire Dampers	NA NA	NA NA	NA NA			
	Smoke Management System	1111					
		NA NA	NA	NA			
		5 6 5 4 5 6	99,000	- APPARAGE			
	Upper floors	Required	Naturally Ventilated	MR			
i.	Fire Extinguishers						
	Total numbers	04	06	MR			
	• Types	ABC Type	Provided	MR			
	IS marking	Required	Provided	MR			
	First-Aid Hose Reels						
	 Total numbers on each flo 	or 01	Provided	MR			
	 Length of hose reel hose 	30 m	Provided	MR			
	Nozzle diameter	5 mm	Provided	MR			
'. 	Automatic fire detection and alarming system						
	Type of detectors	NA	NA	NA			
	Location of Main Panel	NA	NA	NA			
	Location of Repeater Pane	22/08/22	NA	NA NA			
	Alternate source of power		NA NA	NA NA			
			2.32.2	- 34.4			
	Hooters' Location	NA	NA	NA			



8.	MOEFA	NA	NA			
9.	Public Address System	NA	NA			
10	O. Automatic Sprinkler System					
	Basement	NA	NA			
	Ground Floor	NA	NA			
	Sprinkler above false ceiling	NA	NA	1		
11.						
	Size of riser/down-comer	NA	NA	l N		
	Number of hydrants per floor	NA	NA	N		
	Hose Box	NA	NA	N		
12.	2000					
	Total number of hydrants	NA	NA	N.		
	Hose Box	NA	NA	N/		
13.						
	Ground Level					
	Discharge of main Pump	NA	NA	NA.		
	➤ Head of Main pump	NA	NA	NA		
	> Number of main pumps	NA	NA	NA NA		
	Jockey Pump out put	NA	NA NA	NA		
	Jockey pump head	NA	NA	NA		
	> Standby Pump out put	NA	NA	· NA		
	> Standby Pump Head	NA	NA	NA		
	➤ Auto Starting/Manual Stopping	NA	NA	NA		
	> Pump House Access	NA	NA	NA		
	Terrace level					
	➢ Discharge of pump	220 lpm	Provided	MR		
	➤ Head of the pump		g ==			
	➤ Power Supply	NA	NA	NA		
	➤ Auto Starting of pump	NA	NA	NA		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	NA	NA	NA		
	> Draw-off connection	NA	NA	NA		
	> Fire service inlet	NA	NA	, NA		
	> Access to tank	NA	NA	NA		
15.	Overhead Tank capacity Exit Signage.	2500 ltrs Required	Provided Provided	MR MR		
16.	Provision of Lifts.					
ni 938)			377			
	Pressurization of Lift Shaft	NA NA	NA	NA		
	Pressurization of Lift lobby Communication In lift Car	NA NA	NA NA	NA NA		
		NA NA	NA NA	NA NA		
	Fireman's Grounding Switch Lia Simons	NA NA	NA NA	NA NA		
7.	Lift Signage Standby power supply	NA NA	NA NA	NA NA		
8.	Refuge Area.					
0.						
	> Total Area	NA NA	NA NA	NA		
- 1	> Location Fire Control Room	NA	NA	NA		

L

tor System Panel	NA	NA	NA
Switch Panel	, NA	NA	NA
ystem Panel	NA	NA	NA
ry backup	NA	NA	NA
ing Floor Plans	NA	NA	NA
Protection System for special Risks, if any:	NA	NA	NA
	Switch Panel /stem Panel ry backup ing Floor Plans Protection System for	Switch Panel NA /stem Panel NA /y backup NA ing Floor Plans NA Protection System for NA	Switch Panel NA NA /stem Panel NA NA /y backup NA NA ing Floor Plans NA NA Protection System for NA NA

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The school management had rectified the shortcomings issued vide letter number F6/DFS/MS/School/2023/WZ/214 dated 02/05/2023.

Note: Electric meter and electrical panel are not under the staircase.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under DOE circular dated 17/01/2005, it is recommended to renew the Fire Safety Certificate issued vide letter number F6/DFS/MS/2018/School/WZ/979 dated 09/05/2018.

4(f)(az) file is pending.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

Deted 03/04/bran

Etters

ADO (Barrama) for, No freezes the infedry

with me

A 50 (817)27

Dicholog

314

Deneutar My

Add on for lett in purpose for

Director