

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



No. F6/DFS/MS/2024/School/309

Dated: 15/04/2024

## FIRE SAFETY CERTIFICATE

Certified that the Birla Arya Girls Sr. Sec. School (School I'd No- 1207135) located at Birla Lane, Kamla Nagar, Delhi -110007 comprised of Ground & 02 upper floors Only owned/ occupied by the Birla Arya Girls Sr. Sec. School (School I'd No- 1207135) have complied with the fire prevention and safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 03.03.2024 in the presence of Mrs. Nidhi (Principal) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class 'Group B Educational' with effect from ... 15.104.12014.. for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... 1.5.1.04.120.2.4.. at New Delhi

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

2. The Principal, Birla Arya Girls Sr. Sec. School (School I'd No- 1207135) located at Birla Lane, Kamla Nagar, Delhi -110007.

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition

3. Any loss of life or property due to non-functional fire safety measures shall be at the

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first Service http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms. Fire Delhi 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

## INSPECTION REPORT

1. Name & address of the building

: Birla Arya Girls Sr. Sec. School at Birla Lane, Kamla Nagar, Delhi.

2. Type of Occupancy

: Educational

3. Composition of building

: Ground & 02 upper floors only

Type of Case

: New Case

5. Details of previous NOC

: Nil

6. Fire Safety directives letter No

: Nil

7. Date of inspection

: 03.04.2024

8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side

: Mrs. Nidhi (Principal)

10. Year of Construction

: 1947

11. Applicant's letter No.

: Letter No. DL/BAG/23-24/181 Dated 23.03.2024

	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per Rule 35 (6)/ inspection dated 07.08.2013	Provided at site	Remarks MR/NMR		
	Access to building					
	Road width	4.50m	3.50m	MR (old case		
	Gate width	Old case	2.60m	MR		
	Width of internal road	NA	NA	NA		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases		Jaka Tughtiga	ata T		
	Upper Floors	02	02	MR		
	Basements	NA	NA	NA		
	Upper Floors	1.50m or less and 75cm	1.17m & 90cm (iron)	MR		
	Basements	NA	NA	NA		
	c. Protection of exits					
	Fire check door	NA	NA	NA		
	Pressurization	NA	NA	NA		
	d. No. of continuous staircases to terrace	NA	NA	NA		
	e. Width of Corridor	NA	NA	NA		
	f. Door Size	1.0m	1.0m	MR		
	Compartmentation.					
		NA	NA	NA		
	Fire check door     Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA -	NA	NA		
	Fre Dampers	NA.	NA	NA		
	Smoke Management System.					
4	Basements	NA	NA	NA		
	Upper floors	Required	Natural Ventilation	MR		
		Ge				

5	Fire Extinguishers						
	Total numbers	06nos	06nos	MR			
	• Types	ABC/Co2	ABC6	MR			
	ISI marking	Yes	Yes	- MR			
5	First-Aid Hose Reels.						
	Total numbers on each floor	01	Provided	MR			
	Length of hose reel hose	30m	Provided	MR			
	Nozzle diameter						
	TO CONTRACTOR VOLUMBER DOCUMENTS	5mm	Provided	MR			
7	Automatic fire detection and alarming system	NA NA	NA I	NA			
	Type of detectors     Location of Main Panel	NA	NA	NA			
	Location of Main Panel     Location of Repeater Panel	NA	NA	NA			
		NA	NA	NA			
	Hooters' Location	SANS		- 50 ESS			
		NA NA	NA NA	NA NA			
9	MOEFA Public Address System.	NA NA	NA NA	NA NA			
10	Automatic Sprinkler System.	All shall		200.2			
	Basement	NA	NA	NA			
	Upper Floor	NA	NA	NA			
	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants						
~	Size of riser/down-comer	NA	NA	NA			
	Number of hydrants per floor	NA	NA	NA			
	Hose Box	NA	NA	NA			
12	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA NA	NA			
13	Pumping Arrangements.						
	Ground Level						
	<ul> <li>Discharge of main Pump</li> </ul>	N/A	N/A	N/A			
	➤ Head of Main pump	N/A	N/A	N/A			
	Number of main pumps			N/A			
	Jockey Pump out put	N/A	N/A				
	> Jockey pump head	N/A	N/A	N/A			
	> Standby Pump out put	N/A	N/A	N/A			
	➤ Standby Pump Head	N/A	N/A	N/A			
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	N/A	N/A	N/A			
	Terrace level	N/A	N/A	N/A			
	> Discharge of pump	450 LPM	Provided	MR			
	➤ Head of the pump	40m	Provided	MR			
	➤ Power Supply	Required	Provided	MR			
	➤ Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for fire fighting.						
		NA	NA NA	NA			
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>						
	Diaw-oil connection	NA	NA	NA			
	Fire service inlet	NA	NA	NA			

T	> Access to tank	NA	NA .	NA
-	Overhead Tank capacity	5,000 LTR	Provided	MR
15 E	Exit Signage.	Required	Provided	MR
16 F	Provision of Lifts.			
10	Pressurization of Lift Shaft	N/A	N/A	N/A
· lav	Pressurization of Lift lobby	N/A	N/A	N/A
07	Communication In lift Car	N/A	N/A	N/A
(	Fireman's Grounding Switch	N/A	N/A	N/Å
	Lift Signage	N/A	N/A	N/A
17 5	Standby power supply	N/A	N/A	N/A
18 F	Refuge Area.	5	WILL	WW13
-	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19 F	Fire Control Room	4.	1	
_	Detector System Panel	N/A	N/A	N/A
	Detector System Panel     Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	<ul> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A
20 S	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/2023/School/455 dated 04.10.2023.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2011, it is recommended to grant Fire Safety Certificate

> Signature of the Inspecting Officer Name -C.L. Meena Designation:- Asst. Div. Officer (RN)

Dy. Chief Fire Officer (WZ)

There is not file fanding before recived this file.