

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/112

Dated: 18/04 /2024

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Mahabelly Restaurant located at MA-05 Block, Ground Floor, DLF Avenue Saket, New Delhi -110017 in the building comprised of 03 tiers Basement, Ground plus Seven Upper floors owned/occupied by A Unit of Fenn And Jacob Associates was issued FSC by this department vide letter F6/DFS/MS/EH/2021/SZ/94 dated 08/04/2021. The restaurant premise was re-inspected by the officers concerned of this department on 08/04/2024 in the presence of Mr. Vishal Kumar and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class- D "Assembly Building" and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 18/04/2024 at New Delhi by

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer (MCD), Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016 (Ref. MHA Portal ID 2024032503566 dated 30/03/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire-fighting system.

 The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."





12	Name & Address of the Building M/s Mahabelly Restaurant (Unit of Fenn And Associates) located at MA-05 Block, Ground F						
2	Tym		DI F Avenue Selse	ed at MA-05 Block, Gr	round Floor		
3	D	Type of Occupancy DLF Avenue Saket, New Delhi -110017 Restaurant is running at Ground floor only					
A	Build	ling Comprised of	03 tier Basements Crawel 1 07 II				
4	Type	of Case	03 tier Basements, Ground + 07 Upper Floors Renewal				
5	Deta	ils of Previous NOC	The state of the s				
6	Fire	Safety Directives Letter No	F6/DFS/MS/EH/2021/SZ/94 dated 08/04/2021 DLF Place Mall,- F.6/MS/DFS/BP/2005/2073 dated				
NOV.		5 - acourtes Letter 140					
7	Date	of Inspection	04/10/2005 & F.6/MS/DFS/BP/2019/135 dated 01/04/2019				
8	Nar	e of the Inspecting Officers	08/04/2024				
9	Name & Designation of Officers		DO (South) & ADO (BCP)				
	from the building side Mr. Vishal Kumar (Manager)						
10	Yes	r of construction	And Sir Lift 4 . p-				
11			2005 AUGMAN STATES SCHOOLS ELL				
S.		policant letter No. MHA Portal ID 2024032503566 dated 30					
No.	and	imum standards on Fire Prevention Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMI		
1	Ac	ess to Building. (DLF Ave	nue Mall - F.6/DFS/M	S/2022/Mall/SZ/266 Dt. 15	/06/2022)		
SU^{\prime}		Road width	12 m	Provided*	MR		
3017		Gate width	7m migs	Provided*	MR		
	-	Width of internal road	6m	Provided*	MR		
2	Nu	mber, width, type & arrangement of ex		defined to a series			
98.4	a)	Number of Staircase Lipper floors		faintained by DLF Avenu			
		 Upper floors. Basement floor. 	NA	16 Nos Provided*	NA		
	b)	Width of Staircase	N/A	N/A	N/A		
NV.	(U)	> Upper floors	NA Provided & N	faintained by DLF Avenu			
MIN		> Basement floor	N/A	9 x 1.50m & 7 x 2m N/A	NA N/A		
	c)	Protection of exits		Maintained by DLF Avenu			
any		> Fire check door	NA	Provided*	NA		
- 53	171	▶ Pressurization	N/A	Provided*	N/A		
1939	d)	No. of continuous staircase to terrace	NA NA	-NA-	NA		
Man	e)	Width of corridor	N/A mai	N/A	N/A		
- 14	ŋ	Door size	1.50 mtr each	2 m & 1.50 m	MR		
3	Co	mpartmentation.	Provided & Maintained by DLF Avenue Saket Restt within Mall Provided* MR				
51.57	4	• Fire check door.	Restt within Mall	Provided*	MR		
257	6	Sealing of electrical shafts. Fire seting of shaft door.	N/A	Provided* N/A	MR N/A		
	-	Fire rating of shaft door. Water curtain	N/A	N/A	N/A		
58 h		Fire dampers.	N/A	N/A	N/A		
4	Sr	oke Management system.		Maintained by DLF Aven			
THE		Basement	30 ACPH	N/A	N/A		
31		Upper floors	12 ACPH	Exhaust Fans Provided	MR		
5	Fi	re Extinguishers.		populati 4	- Annewer W		
90		Total numbers	Required	08 Nos	MR		
		Types	ABC/CO ₂	ABC & CO ₂	MR		
-		ISI Marking	Required	Provided	MR		
6	F	rst Aid Hose Reels.		Maintained by DLF Aven			
		Total numbers on each floor.	One near Restt 30m	Provided*	MR		
		 Length of hose-reel hose. Nozzle Diameter 	5mm	Provided* Provided*	MR MR		
	A	tomatic fire detection & alarming syste		faintained by DLF Avenu			
-			Required	Smoke & heat	MR		
7		Type of detectors	TOTALOG		IVIIV		
7			Required	Provided*	1 (D		
7		Location of Main Panel	Required	Provided*	MR		
7			Required Required Required	Provided* Provided* Provided*	MR MR MR		

Λ,

8	MOEFA			मृत मह		
_	Public Address System	Required	Provided	MR		
0	Automatic Sprinkler System	N/A	As above	MR		
	Basement	Provided & Maintained by DLF Avenue Sa				
		Required	Provided*	MR		
	Ground floor.	Required	Provided*	200		
11	Sprinkler above false ceiling	N/A	N/A	MR		
11	Internal Hydrants.	Provided & Ma	intained by DLF Ave	N/A		
	Size of Riser/Down-comer	Required		7		
	Number of Hydrant per floor	One near Restt	Provided*	MR		
	Hose box.	One near Restt	Provided*	MR		
12	Yard Hydrants.	12-27 22 22 23 24 25 25 25 25 25 25 25 25 25 25 25 25 25	Provided*	MR		
	Total number of hydrants.	N/A	intained by DLF Ave	nue Saket		
	Hose box.	6 25/4	As above	N/A		
13	Pumping arrangements.	N/A	As above	N/A		
1	Ground Level	Provided & Maintained by DLF Avenue Saket				
		Common pumping arrangements for entire bldg				
14 8	Be of main pump.	4500 LPM	4500 LPM	MR		
	-10da of main pulip.	70m	08 5 70m	MR		
(500)	realition of main pumps.	02 Nos.	02 Nos.	MR		
	Jockey Pump output.Jockey Pump head.	180 LPM	180 LPM	MR		
2014	Standby Pump output.	70m	70m	MR		
SHC	> Standby Pump head.	4500 LPM	2 X 4500 LPM	MR		
	Auto Starting/Manual Stopping.	70m	70m	MR		
1.40	Pump house access.	Required	Provided	MR		
AM.	NA TOTAL STORY	Required	Provided	MR		
No.	• Terrace Level					
	Discharge of pump.	450 LPM	Provided*	MR		
CS3 v	read of pump.	40 m	Provided*	MR		
te Au	Power supply.Auto starting of pump.	Required	Provided*	MR		
14	1877 F 1977	Required	Provided*	MR		
**	Captive water storage for fire fighting. Provided & Maintained by DLF Avenue					
AV.	Underground tank capacity.	Required	3,70,000 Ltrs	MR		
	Draw-off connection. Fire Service Inlet	Required	Provided	MR		
	Fire Service Inlet. Access to tank.	Required	Provided	MR		
		Required	Provided	MR		
15	Overhead tank capacity. Exit Signage.	20,000 ltr	30,000 Ltrs	MR		
16	Provision of Lifts.	Required	Provided	MR		
	Trovided & Maintained by DLF Avenue Saket					
	ressurization of int shart.	Required	Provided*	MR		
	 Pressurization of lift lobby. Communication in lift car. 	Required	Provided*	MR		
	• Fireman's switch.	Required	Provided*	MR		
	Lift signage.	Required	Provided*	MR		
17	Standby Power Supply	Required	Provided*	MR		
18	Refuge Area	Required	Provided	MR		
	Total area	N/A	177	202.000		
12	• Location	N/A N/A	N/A	N/A		
19	Fire Control Room.		N/A	N/A		
133.1	Detector system panel.	Provided & Maintained by DLF Averue Sak				
- 15	Flow switch panel.	N/A	Provided*	N/A		
1884	PA system panel	N/A	Provided*	N/A		
	Battery backup.	N/A	Provided*	N/A		
	Building floor plan	N/A	Provided*	N/A		
20	Special Fire Protection System for the	N/A	Provided*	N/A		
	Protection of special Risk, if any.	IVA		N/A		



N/10

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2021/SZ/94 dated 08/04/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Adcordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Orlère/sortal care. Denecter

approved, F.T. Letter is
your synatype Pl