GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001 No.F6/DFS/MS/2024/ School/ 338 Dated: 26/.9.9./2024

FIRE SAFETY CERTIFICATE

Certified that the Anglo Arabic Model School located at Ajmeri Gate, Delhi comprises of Ground + 01 Upper floor only was earlier granted FSC by this department vide letter no. F6/DFS/MS/2020/School/563 dated 17/12/2020. Now, the premises was reinspected by the officer concerned of this department on 16-04-2024 in the presence of Fraha Sazida, Principle and found that school have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 issued by Director of Education and the building premises is fit for occupancy of class Group B "Educational Building" Sub-Div. B-I with effect from ... 26.1.0.4.....2024 for a period of three years subject to compliance of the conditions mentioned below;

DIRECTOR Delhi Fire Service

Copy to:-

- 1. The Commissioner, MCD, Civic Centre, New Delhi.
- 2. Director of Education, old Secretariat, Delhi.
- 3. The Principal, Anglo Arabic Model School at Ajmeri Gate, Delhi.

Conditions for the validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT 1. Name & address of the building:- Anglo Arabic Model School at Ajmeri Gate, Delhi 2. Type of occupancy:-Educational Group B-I, Gr.+01 Upper Floor Type of case:-4. Details of previous FSC: -No. F6/DFS/MS/2020/School/563 dated 17/12/2020. 5. Fire safety directives No.-N/A Date of inspection:-16/04/2024 7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC) 8. Name & designation of officer From the building side:-Fraha Sazida , Principle 9. Year of construction:-1996 10. Applicant's letter No:letter no. AAMS/67/letter/2057 dated 02.04.2024 Old Case S.No. Minimum Standards on fire Requirement/ Provided Remarks Prevention and fire safety Existing fire safety at site MR/NMR U/R 33 arrangements as per cir. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 1. Access to Building 1) Road width 06 mtr. 06 mtr. MR 2) Gate width NA NA NA 3) Width of internal road NA NA NA 2. Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors 01 Nos. 02 Nos. MR 2. Basements N/A N/A N/A B. Width of staircase 1. Upper floors 1.5 mtr. 1.0 & 1.10 MR mtr. 2. Basements N/A N/A N/A C. Protection of exits 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous 01 01 MR staircase to terrace E. Width of corridor 1.5 mtr. 1.5 mtr. N/A F. Door size 1 mtr. 1 mtr. MR 3. Compartmentation 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers N/A N/A

N/A

N/A

N/A

MR

MR

N/A

N/A

N/A

N/A

10 Nos.

ABC & CO2



N/A

N/A

N/A

04 Nos.

ABC & CO2

Smoke Management System

1) Basements

2) Types

2) Upper floors

Fire Extinguishers

1) Total numbers

3) ISI marking

4.

5.

6.	First-Aid Hose Reel	N/A	Provided	N/A as per
•	1)Total number at each floor	N/A	Tiovided	cir. dt. 01.03.11
	2) Length of hose reel hose	N/A	N/A	N/A
	3) Nozzle diameter	N/A	N/A	N/A
7.	Automatic Fire Detection & A	LAMA		
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	Location of repeater panel	N/A	N/A	N/A
1	4) Alternate source of power	N/A	N/A	N/A
•	5) Hooter's Location	N/A	N/A	N/A
	MOEFA	N/A	Provided	N/A
8.	Public Address System	N/A	N/A	N/A
9	Automatic Sprinkler System			
10.		N/A	N/A	N/A
	1) Basement	N/A	N/A	N/A
	Upper floors Sprinkler above false ceiling	N/A	N/A	N/A
	Internal Hydrants		2.02	N/A
11.	Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
•	floor	N/A	N/A	N/A
	3) Hose box	14/14		T > 2/4
12.	Yard Hydrants	N/A	N/A	N/A
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	14/71		
13.	Pumping Arrangement	NIA	N/A	N/A
**	1) Ground level	N/A N/A	N/A	N/A
	a) Discharge of main	N/A		
	กแพก	N1/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main	N/A	•	//
	nump	37/4	N/A	N/A
	d) lockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
1 10	f) Stand by pump	N/A	1442	
	outnut		N/A	N/A
	Stand by pump head	N/A	N/A	N/A
	t- ting/Manual	N/A	13/22	
	h) Auto starting/Wandars			
	2) Terrace level		220 LPM	N/A as per
	a) Discharge of pump	N/A	220 2	cir. Dt
	a) Discusses		1 1	01.03.2011
			N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	www.V	N/A	N/A	N/A
	d) Auto starting of	N/A		
	a) Auto sairing			13773
	pump Captive Water Storage for Fire	e Fighting	N/A	N/A
14.	1) Under ground tank	N/A	-300	
	I Ulluvi Brown			

N/17

	a) Draw-off connection	N/A	N/A	N/A
	 b) Fire service inlet 	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	N/A	2500 Ltr.	N/A
5.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		Tiovided	IVIIX
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			· N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no F6/DFS/MS/2020/School/563 dated 17/12/2020, under rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Singh

Designation: - ADO (CC)

22/4/24

Sychology

23 41 20m

Denuta My

Aogle