

# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/School/SZ/2024/ 351

Dated: 26/04/2024

### **FIRE SAFETY CERTIFICATE**

Certified that the **B.D. Public School** located at RZ/B-1, Jeevan Park, Uttam Nagar, New Delhi-59. The school building comprised of ground plus three upper floors, but school running at ground and first floor only and second & third floor is closed, owned/occupied B.D. Public School. The school building was inspected by the officer concerned of this department on 02.04.2024 in the presence of Sh. B.K. Kashyap (Manager) and found that School building have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/premises is fit for occupancy class "**Education**" (for ground and first floor only) w.e.f. the date of issue the certificate for the period of three years, subject to compliance of the conditions printed as below.

Issued on 26/04/2024 at New Delhi by.

Delhi Fire Service

## Copy to:-

- 1. The Manager, B.D. Public School located at RZ/B-1, Jeevan Park, Uttam Nagar, New Delhi- 110059.
- 2. Director of Education, GNCT of NCT of Delhi, Old Secretariat, New Delhi.

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

NB

# **INSPECTION REPORT**

1. Name & address of the building: B.D. Public School, RZ/B-1, Jeevan park, Uttam Nagar, New Delhi-59.

2. Building comprised of : Ground plus three upper floors, but school running at ground and first

floor only, second and third floor are closed.

3. Type of Occupancy : Educational

4. Type of Case : New
5. Details of Previous NOC : N/A
6. Fire Safety directives letter No : N/A

7. Date of inspection : 02.04.2024

8. Name of Inspecting Officer : R.K. Yadav, ADO (JKP)

9. Name and designation of officers

From the building side : Sh. B.K. Kashyap (Manager)

10. Year of Construction : 2004

11. Applicant's letter No. : Nil dated 29.02.2024

	Numbe	Road width Gate width Width of internal road r, Width, Type & Arrangement of Exits ber of staircases Upper Floors Basements	Accessible N/A N/A  02 No.'s	06 mtrs N/A N/A	M/R N/A N/A
	a. Num	Gate width Width of internal road  r, Width, Type & Arrangement of Exits ber of staircases Upper Floors	N/A N/A	N/A N/A	N/A
	a. Num	Gate width Width of internal road  r, Width, Type & Arrangement of Exits ber of staircases Upper Floors	N/A	N/A	
	a. Num	Width of internal road  r, Width, Type & Arrangement of Exits  ber of staircases  Upper Floors	N/A		N/A
	a. Num	er, Width, Type & Arrangement of Exits ber of staircases Upper Floors		02 No 20	
	Com Service	Upper Floors	02 No.'s	02 No 's	
	•	76.7	02 No.'s	02 No 20	
	•	Basements	Market M.	02 NO. S	MR
			N/A	N/A	N/A
			THE VILL		
1	1 117:11	A of stainsans	150 cms & 75	90 & 130 cms	MR
		th of staircases	cms	11121	7.6500 P.
_		Upper Floor Basements	N/A	N/A	N/A
	-	Dascinents		- 9-X	
	c. Prote	ection of exits	N/A	N/A	N/A
- 1	. •	Fire check door	N/A	N/A	N/A
1	•	Pressurization	1 Ming M. C. Committee	100 VIIVE 1344	
	d. No. of continuous staircases to		Required	One	MR
	terrace e. Width of Corridor		150 cms.	180 cms.	
	f. Door Size		22/2 (22/2)		MR
.0	1. DO	51 5120	100 cms	100 cms	MR
	Compa	rtmentation	170		
		Fire check door	N/A	N/A	N/A
	•	Sealing of electrical shafts	N/A	N/A	N/A
	•	Fire Rating of shaft door	N/A	N/A	N/A
	•	Water Curtain	N/A	N/A	N/A
	•	Fire Dampers	N/A	N/A	N/A
4.	Smoke	Management System		IVA	IVA
	•	Basements	N/A	N/A	N/A
	•	Upper floors	Required	Natural Ventilation	
_				The Chillian	, IVI/R
5.	Fire Extinguishers				
	•	Total numbers	06 no's	Provided	M/R
	•	Types	ABC/CO <sub>2</sub> type	Provided	M/R
I	IS marking		ISI marked	Provided	M/R

1	)
	~
	10
$\sim$	

	Total numbers on each floor	01 no/floor	Provided	M/R	
1	<ul> <li>Length of hose reel hose</li> </ul>	30 mtrs	Provided	M/R	
-	Nozzle diameter	5 mm	Provided	M/R	
7.	Automatic fire detection and alarming system				
	Type of detectors	N/A	N/A	N/A	
1	<ul> <li>Location of Main Panel</li> </ul>	N/A		A CONTRACTOR	
	Location of Repeater Panel     Alternation	N/A	N/A	N/A	
	Alternate source of power     Hooters' Location	N/A	N/A N/A	N/A	
8.		N/A	N/A	N/A N/A	
3.42	MOEFA	N/A	N/A	N/A	
9.	Public Address System	N/A	N/A	N/A	
10.	Automatic Sprinkler System				
	Basement	1			
	Ground Floor	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants	N/A	N/A	N/A	
	Size of riser/down-comer	N/A	377		
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A N/A	N/A	N/A	
•	Hose Box	N/A	N/A	N/A	
2.	Yard Hydrants	IVA	N/A	N/A	
	Total number of hydrants	N/A	NI/A		
3.	Hose Box	N/A	N/A N/A	N/A	
J.	Pumping Arrangements		IVA	N/A	
	Ground Level				
	Discharge of main Pump	N/A	N/A	-	
	Head of Main pump	N/A		N/A	
	Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put		N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	> Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A	
		N/A	N/A		
	<ul> <li>Pump House Access</li> <li>Terrace level</li> </ul>	N/A	N/A	N/A	
	The state of the s		IVA	N/A	
	- isonarge of pump	450 LPM	450 I D. 4		
	<ul><li>➢ Head of the pump</li><li>➢ Power Supply</li></ul>	40 mtrs	450 LPM 40 mtrs	M/R	
	Auto Starting of pump	Required	40 mtrs Provided	M/R	
		Required	Provided	M/R	
1.	Captive Water Storage for fire fighting	- 3		M/R	
	Underground tank canacity.	N/A			
	> Draw-off connection > Fire service inlet	N/A N/A	N/A	N/A	
	Access to tank		N/A	N/A	
	Overhead Tank capacity	N/A	N/A	N/A	
5.	Exit Signage.	N/A	N/A	N/A	
	Signage.	10000 ltrs Required	10000 ltrs	M/R	
6.	Provision of Lifts.	reduited	Provided	M/R	
	Pressurization of Lift Shaft			(No Lift)	
	riessurization of Life lake	N/A	N/A		
	Communication In life Ca	N/A	N/A	N/A	
	Fireman's Grounding Switch     Lift Signage	N/A	N/A	N/A	
7		N/A	N/A	N/A	
7.	Standby power supply	N/A	N/A	N/A	
0	1	N/A	N/A	NA	
			11//	N/A	

18.	Keiug	ge Area.			
	×	Total Area Location	N/A	N/A	N/A
	1		N/A	N/A	N/A
19.	Fire C	Control Room			
	•	Detector System Panel	N/A	N/A	N/A
	•	Flow Switch Panel	N/A	N/A	N/A
		PA System Panel Battery backup	N/A	N/A	N/A
		Building Floor Plans	N/A	N/A	N/A
	1		N/A	N/A	N/A
0.	Special special	l Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Note: As per undertaking (placed at C-14) school building comprised of ground plus three upper floors, but school running at ground and first floor only and second & third floor is closed. Closed gate photograph enclosed with undertaking

Keeping in view of the above compliance of the minimum standards of fire prevention and fire safety measures under the circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011, issued by the Director of Education, it's recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer

Name- R.K. Yadav Designation- ADO (JKP)

DO (South West)

ADO Johnson)

The Papplicant has submitted an underthing that ballook to recovering at ground and for the celabet only. Photographic is about placed on the file relative only. Photographic is about placed on the file relative only. Photographic is about placed under circular So, the school may be considered under circular of 1/2/2011. and exempted as percincular may be extended place of 1/2/2011. and exempted as percincular may be extended place.