



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F.6/DFS/MS/G/2024/SZ/ 262

Dated .26./.04/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Midland Fruit & Vegetable Products (India) Pvt. Ltd, Situated at 15, Ishwar Nagar, Dr. Jha Marg, Okhla Industrial Area, Phase-III, New Delhi -110020 comprised of Basement + Ground + two upper floors was issued FSC by this department vide letter no F6/DFS/MS/G/SZ/2021/333 Dated 16/07/2021. The Premise was re- inspected by the officer concerned of this department on 19/04/2024 in the presence of Mr. KA Lal and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and found that the said building / premises is fit for occupancy class Group G "Industrial Building" with effect from 26/0/2024 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on $\frac{26}{10}$ $\frac{04}{100}$ $\frac{1}{100}$ 2024 at New Delhi by

(ATUL GARG)
DIRECTOR
IRE SERVICE

DELHI FIRE SERVICE

Copy to:

 The Midland Fruit & Vegetable Products (India) Pvt. Ltd, Situated at 15, Ishwar Nagar, Dr. Jha Marg, Okhla Industrial Area, Phase-III, New Delhi -110020.

2. The Executive Engineer (Building), MCD, Jal Vihar, Lajpat Nagar, New Delhi 110024.

Conditions for the validity of the safety certificate:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

4. Basement shall be used strictly as per Building Bye Laws.

 The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

The owner/occupier shall submit a declaration every year in the form 'K'
provided in the first schedule of Delhi Fire Service Rules 2010, form is available
on www.dfs.delhigovt.nic.in.

		NH	L			
	Thich com					
1	Name & Address of the Building	INSPECTION REPORT				
	a doc or the building	The Midland Fruit & Vegetable Products (India) Pvt				
		Ltd, 15, Ishwar N	lagar, Dr. Jha Marg, Okh	la Industrial		
2	Type of Occupancy	Area, phase -III, New Delhi 110020				
		Industrial Building G				
	Building Comprised of	Building is comprised of two portions (i.e. Big & Small) and each portion comprised of Basement				
	Alex 1					
		Ground + Two Upper Floors				
4	Type of Case	Renewal				
5	Details of Previous NOC	F6/DFS/MS/G/SZ/2021/333 Dated 16/07/2021				
6	Fire Safety Directives Letter No	Nil				
7	Date of Inspection	10/04/2024				
8	Name of the Inspecting Officers	DO (South) & ADO (DCD)				
9	Name & Designation of Officers from the	May VAT-1				
V	building side	At whose it to	or released w			
10	Year of construction	1983	more a literature of			
11	Applicant letter No.	Email Dated 13/	04/2024			
S. No	Minimum standards on Fire Prevention	BBL-1967	Provided at Site	D		
1	and Fire Safety U/R 33 Access to Building.	requirement	and the state of t	Remarks MR/NMR		
erk -	Road width	Accessible	6 mtr	111		
	Gate width	NA	4 x 2 Nos	MR		
	Width of internal road	N/A	N/A	NA		
2	Number, width, type & arrangement of exits		Pampile AVI angent on	N/A		
	a. Number of Staircase	gmacrail	Distance of the			
TO -	1. Upper floors	Required	Big Portion : Two	9000		
	N.Y	required	Small Portion one	MR		
	2. Basement floor	Required	Big Portion : 01 ± 02 ramp Small Portion one	MR		
12	b. Width of Staircase	-15	si quan'i ganan 🧸			
12	1. Upper floors	4 feet	Big Portion : Provided	-		
N/A	2. Basement floor	MUNICOLE TELEDICA	Small Portion Provided	MR		
AUT	AV TAKE	4 feet	Big Portion : Provided Small Portion Provided	MR		
	c. Protection of exits		Terrare Level			
TIN .	1. Fire check door	N/A Ign	N/A	N/A		
10%	2. Pressurization	N/A	(Cample N/A)	N/A		
	d. No. of continuous staircase to terrace	NA	One provided (not continuous)	NA		
-	e. Width of corridor	N/A	N/A	N/A		
	f. Door size	2 feet8 inch	Provided	MR		
3	Compartmentation.	(North	da des la companya de	IVIK		
	 Fire check door. 	N/A	N/A	N/A		
100	Sealing of electrical shafts.	N/A	N/A	N/A N/A		
10	Fire rating of shaft door.	N/A	N/A	N/A		
100	Water curtain	N/A	N/A	N/A		
4.	Fire dampers. Smoke Management system.	N/A	N/A	N/A		
Y	Basement	NUA	Series III Bridging 17	, tel		
- 1	Upper floors	N/A N/A	N/A	N/A		
5.	The second secon	IVA	N/A	N/A		
	Total numbers	12 Nos	Provided	100		
	• Types	ABC / Co2	Provided	MR		
100	ISI Marking	ISI Marked	Provided	MR		
6.	. First Aid Hose Reels.	Aramanou	1 TOVIDED	MR		

	Total numbers on each floor.	N/A	01 Nos	N/A
T KE MA	Length of hose-reel hose.	N/A	iti sell foræs 30 m a sour	N/A
	Nozzle Diameter	N/A	5 mm	N/A
7	Automatic Fire Detection & Alarming	System.		
	Type of detectors	N/A	N/A	N/A
21 -0:I1	Location of Main Panel	N/A	N/A	N/A
mount	Location of Repeater Faner	N/A	N/A	N/A
-	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A 10 ang 1	N/A
8.	MOEFA	N/A	Provided	N/A
9.	Public Address System	N/A	N/A N/A	N/A
10.	Automatic Sprinkler System		Mother graft for Smith	
	Basement	N/A	Provided	N/A
	• Upper floors (on 2 nd floor)	N/A	Partially Provided	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.		HORS(WEIGO IN BUY)	
	Size of Riser / Down-comer	N/A	100 mm	N/A
	Number of Hydrant per floor	odro N/A sul	no elember 03 mersin M	N/A
VIEW	Hose box.	N/A	03	N/A
12.	Yard Hydrants.		GUARANTE DE CO-SE	
	Total number of hydrants.	N/A	5 Nos	N/A
	Hose box.	N/A	5 Nos	N/A
13.	Pumping arrangements.	Miles I	BALLED SIN COST OF T	
	Ground Level	er wie gewanne grant	Number, width, 120e & ne	N/A
	Discharge of main pump.	N/A	E Sum A/A Smire	N/A N/A
	> Head of main pump.	N/A N/A	N/A N/A	N/A
	Number of main pumps.	N/A N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	 Jockey Pump head. Standby Pump output. 	N/A	N/A	N/A
	> Standby Pump head.	N/A	N/A	N/A
	> Auto Starting / Manual Stopping.	N/A	N/A	N/A
× .	> Pump House Access	N/A	N/A	N/A
	Terrace Level		er a tradesman of early	
7 1	Discharge of pump.	N/A	900 LPM	N/A
	> Head of pump.	N/A	40 m	N/A
	> Power supply.	N/A	Provided 1/10	N/A
	Auto starting of pump.	N/A	Provided W	N/A
14.	Captive water storage for fire fighting.		L. Dong L.	27/4
-	Underground tank capacity.	N/A	N/A	N/A N/A
0.7	> Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	Provided Provided	N/A
4	Access to tank.	N/A	50,000 ltr	N/A
	Overhead tank capacity.	N/A		N/A
1-1		N/A	Provided	N/A
15.	Exit Signage.			
15. 16.	Provision of Lifts.		American Manager	NA.
	Provision of Lifts. • Pressurization of lift shaft.	NA	NA NA	NA NA
	Provision of Lifts. • Pressurization of lift shaft. • Pressurization of lift lobby.	NA NA	NA -	NA
	Provision of Lifts. Pressurization of lift shaft. Pressurization of lift lobby. Communication in lift car.	NA NA NA	NA NA	240007251
	Provision of Lifts. Pressurization of lift shaft. Pressurization of lift lobby. Communication in lift car. Fireman's switch.	NA NA NA NA	NA NA NA	NA NA
16.	Provision of Lifts. Pressurization of lift shaft. Pressurization of lift lobby. Communication in lift car.	NA NA NA	NA NA	NA NA NA

Battery backup Building floor plan Special Fire Protection System for the	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A
 Battery backup 	N/A		34, 37, 23, 14
		N/A	N/A
Flow Switch Panel. PA system Panel.	SARAMETER S	N/A	N/A
	0.0000000000000000000000000000000000000	N/A	N/A
Detector System Panel			
Fire Control Room.	NA	NA	NA
	5,500,7,50	NA	NA
	N/A		
	Fire Control Room. Detector System Panel. Flow Switch Panel.	Location N/A NA Fire Control Room. Detector System Panel. Flow Switch Panel. N/A N/A	Location N/A NA NA Fire Control Room. Detector System Panel. Flow Switch Panel. N/A N/A N/A N/A N/A N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/G/SZ/2021/333 Dated 16/07/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Any OCP

Note Any OCP

Note of Johnson of Jo

g5/m/m