

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/WZ/Mercantile/2024/ 954

Dated: 25/04/2024

FIRE SAFETY CERTIFICATE

Certified that the building of M/s. Pacific Development Corporation Ltd., lessee of DMRC Ltd. located above Netaji Subhash Place underground Metro Station, Line- 7, Phase-III Corridor, New Delhi owned/occupied by M/s. Pacific Development Corporation Ltd., lessee of DMRC Ltd. comprised of two tier basements, lower ground/concourse, ground plus 02 upper floors & part 3rd floor without multiplex was issued fire safety certificate by this department vide letter No. F.6/DFS/MS/Mercantile/2021/WZ/368 dated 02.08.2021 and MLCP Block comprised of ground plus seven upper floors was issued fire safety certificate vide letter No. F6/DFS/MS/Mercantile/2021/WZ/218 dated 09.04.2021. The building complex was re-inspected by the officers concerned of this department on 01.04.2024 in the presence of Sh. I.K. Thakur, Director (Commercial) and found that the management of M/s. Pacific Development Corporation Ltd. have added 5th floor (restaurants) and now the building is comprised of two tier basements, lower ground / concourse, ground plus five upper floors have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service, 2010 and that the premises/building complex is fit for occupancy Mixed class "Mercantile & Assembly" for two tier basements, lower ground / concourse, ground plus five upper floors and MLCP Block comprised of Ground plus 07 upper floors with effect from 2504204 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service, 2010, printed overleaf.

Issued on 25/04/2024 at New Delhi by.

Copy to: -

1. The Executive Director (PD), DMRC Ltd., 25, Ashoka Road, New Delhi- 110001.

2. Sh. I.K. Thakur, Director Commercial, G-42, Pacific Mall, Tagore Garden, Najafgarh Road, New Delhi- 110018.

INSPECTION REPORT

Name & address of the building: M/s. Pacific Development Corporation Ltd. lessee of

DMRC Ltd. (Commercial cum Multiplex with MLCP), NSP Metro Station, Line-7, Delhi.

Type of Occupancy

: Mixed (Mercantile & Assembly)

Type of Case 3.

: Renewal/ addition of 5th floor

Details of previous No.: F6/DFS/MS/Mercantile/2021/WZ/218 dated 09.04.2021 for MLCP block, & F6/MS/DFS/MS/Mercantile/2021/WZ/368 dated 02.08.2021- for commercial complex

Fire Safety directives no.: F6/DFS/MS/95/2017/292 dated 27-09-2017, F.6/DFS/MS/BP/2021/419 dated 22.09.2021- for addition of 5th floor

Date of inspection

: 01.04.2024

Name of the Inspecting Officer: M.K. Chattopadhyay, DCFO (WZ), R.K. Sinha, ADO (Bawana)

Name and designation of Officer

from the building side

: Sh. I.K. Thakur, Director (Commercial)

Year of Construction

: 2001

licant's File No.

: Form 'J' dated nil

S No	10. Applicant's File No. Minimum standards on fire prevention and fire safety U/R 33	Requirements as per NBC UBBL- 2016 / directives of 16.04.2019 & 22.09.2021	Provided at site	Remarks MR/NMF
1.	Access of building	12	Provided	MR
1.	Road width	12 m	Provided	MR
	Gate width	06 m	Provided	MR
	road road	06 m	Flovided	IVIK
-	When width, Type & Arranger	nents of exits		
2.	a. Number of smircases Upper floors	09 (commercial) + 03 M + 02 ramps in MLC	ALCP Provided	MR
- 1		02 Nos. +Ramps Provided		MR
	 Basements 	021,65		
	b. Width of staircases Upper floors	2.0 mts each (commerci	P	MR
		1.5 mts each	Provided	MR
- #	Basements		151 1-17	
	c. Protection of exits	Required	Provided	MR
	• Fire check door	Required	Provided	MR
	Pressurization No of continuous staircase	04 Nos	Provided	MR
	to terrace	2.0 mts (Commercial) / 1.5 mts (MLCP)	Provided	MR
		2.0 & 1.5 mts	Provided	MR
	f. Door Size	2.0 & 1.5 1115		
C	Compartmentation	D- swined	Provided	MR
1	Fire check door	Required	Provided	MR
	 Sealing of electrical shafts 	Required	Provided	MR
	Fire Rating of shaft door	02 Hours	Provided in basement	MR
	Water Curtain	Required	Provided	MR
	• Fire Damper	Required	Tiovided	
Sn	oke Management System			MR
1511		Required	Provided	MR
	Basements Unner Google	Required	Provided	-
E:	• Upper floor		1 Y 10 17 1 1 N	MR
rir	re Extinguishers	125 nos.	Provided	MR
	Total numbers	CO ₂ & ABC	Provided	
	• Types	ISI marked	Provided	MR
	IS marking	151 marked	200 Mar (200)	



1	First – Aid Hose Reels					
1				MR		
	 Total numbers on each floor 	10 Nos.	Provided	MR		
	 Length of hose reel hose 	30 mts	Provided	MR		
	Nozzle diameter					
	Automatic fire detection and alarming system					
+	Type of detectors	Smoke & Heat	Provided	MR		
	 Type of detectors Location of Main Panel 	Ground floor	Provided	MR		
	Control of the Contro	Required	Provided	MR		
	Location of Repeater Panel	Required	Provided	MR		
	Alternate source of powerHooters' Location			MR		
		Appropriate place	Provided	MR		
	MOEFA	Required	Provided	MR		
	Public Address System	Required	Provided			
	Automatic Sprinkler System					
	Basements	Required	Provided	MR MR		
	Upper Floor	Required	Provided	· MR		
	Sprinkler above false ceiling	Required	Provided	1		
	Internal Hydrants			MR		
•	Size of riser/down- comer	150 mm	Provided	MR		
	N. I Charlesonte por floor	10	Provided	MR		
	Number of hydrants per floor Hose Box	Required	Provided	TVAX.		
	Yard Hydrants			MR		
2.	Total number of hydrants	Required	Provided	MR		
	Hose Box	Required	Provided	IVAL		
2	Pumping Arrangements					
3.				MR		
	Ground Level Discharge of main pump	2280 lpm	Provided	MR		
	Discharge of main pump Head of main pump	88 mts	Provided	MR		
		02	Provided	MR		
	 Number of main pumps Jockey pump out put 	2 x 180 lpm	Provided	MR		
	> Jockey pump head	88 m	Provided	MR		
	Standby Pump out put	2280 lpm	Provided	MR		
	Standby Pump Head	88 mts	Provided	MR		
	Auto Staring/Manual stopping	Required	Provided			
	Pump House Access	Required	Provided	MR		
	Terrace level	200 1 70 (Descrided	MR		
	Discharge of pump	900 LPM	Provided			
	> Head of the pump	40 mts	Provided Provided	MR MR		
	> Power supply	Required Required	Provided	MR		
	> Auto starting of pump	Required	Tiovided	IVIIC		
14.	Captive water Storage for fire fighting	2 00 000 Itm	Drovidad	MD		
	Underground tank capacity	2,00,000 ltrs. Required	Provided Provided	MR		
	Draw of connection	Required	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	 Access to tank Overhead Tank capacity 	20,000 litres	Provided	MR		
200		Required	Provided	MR MD		
15	OT 'A-	1		MR		
16.	Provision of Lifts	Required	Described			
	> Pressurization of Lift Shaft > Pressurization of lift lobby	Required	Provided	MR		
	Communication in lift Car	Required	Provided Provided	MR		
	- 'a Grounding Switch	Required	Provided	MR		
	 ➤ Fireman's Glounding ➤ Lift Signage 	Required	Provided	MR		
	Standby power supply	Required	DG set Provided	MR		
	THE PART OF CHILDINA	1 ANGGUIEU	THE T VISIT LINES. 1 .			

		Total area	Require	d Provided	MR
19.	Fire	> Location ire control room	4 th floor		MR
_		Detector system panel	Required	Provided	MR
		 Flow Switch Panel PA System Panel Battery backup 	Required	Provided	MR
			Required	Provided	MR
			Required	Provided	MR
		> Building Floor Plans	Required	Provided	MR
0.		cial Fire Protection Systems for ection of special Risks, if any;	Required	NOVEC fire fighting system provided	MR

The fire protection systems provided in the building were randomly test checked and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act- 2007 & Rules- 2010. DFA is put up for approval & signature please.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer

Name: M. K. Chattopadhyay Designation: DCFO (WZ)

Signature of the Inspecting Officer

Name: R.K. Sinha

Designation: ADO (Bawana)

F. T. littes is put up for Sign. please.

Director