आज़ादी ना अमृत महोत्सव 14

DFS/MS/School/NDZ/2024/367

Dated: 29/04/2024

FIRE SAFETY CERTIFICATE

Certified that the Central Public School located at A-13A, Shanti Marg, Mandawali, Delhi110092, comprised Ground plus three upper floors Only owned / occupied by Central Public
School, was issued FSC vide letter No. F6/DFS/MS/School/2020/NDZ/133 dated 20/03/2020. The
School building was re-inspected by the officer concerned of this department on 18/04/2024 in
presence of Mrs.Niru Sharma (Principal) of the school and found that school building have deemed
complied with the fire prevention and fire safety requirements in accordance with Circular Letter No.
262-362 dated 17/01/2005 issued by Director of Education and the school building is fit for occupancy
class "Educational Building" (Group-B) for ground plus three upper floors with effect from
29/04/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or
sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS
rule 2010.

Issued on 29/04/2024 at New Delhi by.

DIRECTOR

CDELHI FIRE SERVICE

Copy to:-

1. The Principal, Central Public School located at A-13A, Shanti Marg, Mandawali, Delhi-110092.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

NIS

			INSPE	CTION REPORT					
	Name & address of the building			Central Public School located at A-13A, Shanti Marg, Mandawali, Delhi-110092.					
2.	Buil	din	g is comprised of	Ground plus three upper floors Only					
3.	Type	e o	foccupancy	Educational					
14.			f case	Renewal					
)5.	Details of previous FSC			F6/DFS/MS/School/2020/NDZ/133 dated					
	20			20/03/2020					
06.	Fire safety directives letter no.			Circular No.262-362 dated 17/01/2005					
07.	Date of inspection 18/04/2024				10				
08.	Nan	ne (of the inspecting officers	Yashwant Singh Meena ADO (L.N)					
09.			of the designation of officer ne building side	Mrs. Niru Sharma (Principal)					
10.	Year of construction 2000								
11.	_		ant's letter no.	Outdoor dairay no.390 dated 09/04/2024					
S.No		Minimum standard of fire prevention and fire safety U/R 33		Circular Requirement	Provided at site	Remarks MR/NMR			
01.	Ac		s to Building:						
	A	R	oad width	6.0 mtrs.	6.0 mtrs.	- M	R		
	В			N/A	N/A				
-	C Width of internal road			N/A	N/A N/A		'A		
02.		Number, Width, Type and Arrangement of Exits:							
1	A	N	lumber of staircases	75 98 15-9			- 4		
		a	Upper floor	02 nos.	02 nos.		MR		
	D	b	Basement	N/A	N/A		N/A		
	В		Vidth of staircases						
1 10		a	Upper floor	1.50 mtrs	1.20 mtrs & 0.80 r (old accepted)		MR		
		b	Basement	N/A	N/A		N/A		
	C	Pı	rotection of exits						
		a	Fire check door	N/A	N/A		N/A		
		b	Pressurization	N/A	N/A		N/A		
	D		No. of continuous taircases to terrace	01 no	01 no		MR		
	E		Width of corridor	1.50 mtrs	01 mtr (old acc	epted)	MR		
	F	_	Door size	1.0 mtr	1.0 mtr		MR		
03.	Co	_	partmentation:						
	A	-	Fire check door	N/A	N/A	N	I/A		
	В		Sealing of electrical shafts	N/A	N/A	N	I/A		
	C	_	Fire rating of shaft door	N/A	N/A		I/A		
	D	\	Water curtain	N/A	N/A		I/A		
	E Fire dampers			N/A	N/A	N/A			
04.			ke Management System:				000 J. D.		
	A Basement		Basement	N/A	N/A	/A N/A			
	В	1	Upper floor	N/A	N/A		J/A		
			P I II V		1 11.2 %	1 1	1/21		

W

Central Public School located at A-13A, Shanti Marg, Mandawall, Delhi-110092.

04	. Fire	Extinguisher:							
	A	Total numbers	06 nos.	06 nos.	MR				
	В	Types	ABC/CO ₂	ABC/CO ₂	MR				
	C	ISI marking	ISI Marked	ISI Marked	MR				
06	. First-	-Aid-Hose Reel:							
	A	Total numbers of each floor	01 no.	01 no. /	MF				
	В	Length of hose reel hose	30 mtrs.	30 mtrs.	MF				
	C	Nozzle diameter	05 mm	05 mm	MF				
07.	Auton	natic Fire Detection and A	larming System:	= -(
	A	Type of detectors	N/A	N/A	N/A				
	В	Location of main panel	N/A	N/A	N/A				
	C	Location of repeater	N/A	N/A	N/A				
	D	Alternate source of power	N/A	N/A	N/A				
	E	Hooters	N/A	N/A	N/A				
18.	MOEF		N/A	N/A	N/A				
9	July Market States	Address System:	N/A	N/A	N/A				
0.		atic Sprinkler System:			100				
٠.	A	Basement	N/A	N/A	N/A				
	В	Upper floor	N/A	N/A	N/A				
	C	Sprinkler above false	N/A	N/A	N/A				
1.	Interne	Internal Hydrants:							
	A	Size of riser/down-	100 mm	100 mm	MR				
	A	comer							
	В	Number of hydrants per floor	01 no	01 no /	MR				
1	<u>C</u>	Hose box	01 no	01 no /	MR				
2.		ydrants:							
	A	Total number of hydrants	N/A	N/A	N/A				
ŀ	В	Hose box	N/A	N/A	N/A				
3.	-	g Arrangements:							
,.		id level	7						
	A	Discharge of main	N/A	N/A	N/A				
+	В	Pump Head of main pump	N/A	N/A	N/A				
	C	Number of main	N/A	N/A	N/A				
	D	Jockey pump out put	N/A	N/A	N/A				
1	E	Jockey pump head	N/A	N/A	N/A				
	F	Standby pump out put	N/A	N/A	N/A				
	G	Standby pump head	N/A	N/A	N/A				
	H	Auto starting /manual stopping	N/A	N/A	N/A				
	1	Pump house access	N/A	N/A	N/A				
	Terrace Level								
	Α	Discharge of pump	450 LPM	450 LPM	MR				
	B	Head of the pump	40 m	40 m	MR				
	C	Power supply	Required	Provided	MR				
	D	Auto starting of pump	Required	Provided	MR				
					and the same of th				

50/

14.	Caj	Captive Water Storage for Fire Fighting:						
ur.	A	Underground tank capacity	N/A	N/A	N/A N/A			
	В	Draw-off connection	N/A	N/A				
	C	Fire service inlet	N/A	N/A	N/A			
	D	Access to tank	N/A	N/A	N/A MR			
	E	Overhead tank capacity	5,000 liters.	5,000 liters.				
15.	Exit Signage:		Required	Provided	MR			
16.	Description of Lifera							
	A	Pressurization of lift shaft	N/A	N/A	N/A			
	B	Pressurization of lift lobby	N/A	N/A	N/A			
	C	Communication in lift car	N/A	N/A	N/A			
			N/A	N/A	N/A			
	D	Firemen's grounding switch	N/A	N/A	N/A			
	E	Lift signage	NA	N/A	N/A			
17.		Standby Power Supply:						
18.	-	fuge Area:	N/A	N/A	N/A			
	A	Total area	N/A		N/A			
	В	Location	1,1,3.2					
19.	+-	re Control Room:	N/A	N/A	N/A			
	A	Detector system panel	N/A		N/A			
	В	Flow switch panel	N/A		N/A			
	C	PA system panel	N/A	2.270	N/A			
	D	Battery backup	N/A		N/A			
	E	Building floor plans		N/A	N/A			
20.	Sp	ecial Fire Protection systems for otection of special Risks, if any		A 100 May 100				

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules of Directorate of Education the FSC issued vide letter no. F6/DFS/MS/School/2020/NDZ/133 dated 20/03/2020, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended to be renewed.

No file is pending with me before disposal of this case.

22/4/2024 Signature of the Inspecting Officer

Name: - Yashwant Singh Meena

Designation: -

ADO (L.N)

DY. CFO NDZ

23 41 200

Director May 175

Anylon