FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No. F6/DFS/MS/2024/GH | 102

Dated: 26/04/2024

Direct Of Delhi Fire Serving

FIRE SAFETY CERTIFICATE

Certified that the building of M/s Hotel C Park, Located at 6/13, WEA, Karol Bagh, New Delhi110005, running at G + 03 Upper Floors in a building comprised of B + G + 04 Upper Floors using
Basement (storage), Ground floor (reception & office), 1st,2nd & 3rd floor (08 guest rooms each floor)
(Total=24 Rooms) and a kitchen with two staff rooms (now closed) on terrace was issued Fire Safety
Certificate by this department vide Letter No. F6/DFS/MS/GH/SZ/2021/133, dated 11/03/2021. The
premises was re inspected by the officer concerned of this department on 13/04/2024 in the presence of Sh.
Rakesh Chadha (Owner) and observed that all the fire prevention and fire safety arrangements provided in
the premises found in good working condition. The premises have therefore deemed complied with the fire
prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010
and that the premises is fit for occupancy class "Residential" (guest house at 1st,2nd &3rd floor (08 guest
rooms each floor) (Total=24 Rooms) with effect from 26/04/2024 for a period of three years in
accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to
compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .26/04/2024... at New Delhi by.

Copy to:

 The Joint. Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi.

2. The Manager, M/s Hotel C Park, at 6/13, WEA, Karol Bagh, New Delhi-110005.

Following fire safety directives must be adhered to:-

1. The 4th floor i.e terrace floor shall not be used for any purpose as undertaking given by owner/occupier

2. All the fire safety arrangements provided therein shall be maintained in good working condition at

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. Basement strictly shall be kept vacant as seen during inspection.

8. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: M/s Hotel C Park, Located at 6/13, WEA, Karol Bagh, New Delhi-110005.

2. Type of Occupancy

:Lodging or rooming "A-1"

: Renewal (Running at G+3 UFs in a building comprised 3. Type of Case of Basement, Ground + 4 UFs)

4. Details of previous NOC: F6/DFS/MS/GH/SZ/2021/133, dated 11/03/2021

5. Fire Safety directives Letter No.: Nil

6. Date of inspection

:13/04/2024

7. Name of the Inspecting Officer: ADO (DWK)

8. Name and designation of Officer

from the building side .

: Sh. Rakesh Chadha (Owner)

9. Year of Construction

: 2005

10. Applicant's letter No.

: 2024032903763, dated 01/04/2024

<u>s · [</u>	0. Applicant's letter No. Minimum standards on fire	As per N/20,		Prov	110110		Remarks MR/NMR	
No	prevention and fire safety U/R 3	3 N/21 &	11/22		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		MR	
1.	Access of building • Road width	6 mtr Provide			11 from road		MR	
			Direct	Direct accessible from road			NA	
	Gate width Width of internal road	NA	INA					
2.	Number width, Type & Arrang	gements of	exits				47	
<u> </u>	 a. Number of staircases Upper floors Basements b. Width of staircases Upper floors Basements c. Protection of exits Fire check door Pressurization d. No of continuous staircase to terrace e. Width Of Corridor f. Door Size 		0	1	MR (Being old case)		ld case)	
		01 No.	01 No. MR (Being		Being o	g old case)		
*		01 No.	1 No.	TATE (With (Doing out 1)			
		Old case	Old case 1.30 m			MR (Being old case)		
		Old case	1.25n	1 m (D :			old case)	
		Old case	1.231				344	
		NA Having ≥ 10beds					NA	
		NA Having			NA N		NA	
		01	1 24		01		MR	
1		1 mtr	1.52m		MR (Being old cas		g old case)	
		Old case	200000000000000000000000000000000000000	(CARCASA)		R (Bein	R (Being old case)	
		Old Case	Se 0.87III		11			
3.	Compartmentation Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers	NA Having≥1			0beds	beds NA		
		NA .			NA ·		NA	
		NA .		I	NA		NA	
		NA			NA		NA	
		NA			NA		NA	
	82.				r	×:	0	

N/33

6.75

-	Basements	per hour Exhau		ust fan provided		MR				
- 1	Upper floors		e per h					MR		
	Fire Extinguishers	1		-						
-	Total numbers		16 No	19		Pro	vided	MR		
	Total numbers Types		ABC),	CO	& ABC	MR		
	IS marking		Requi			Dro	vided	MR		
_	First - Aid Hose Reels		Order to the second	ARCONO I		FIO	vided	1722		
5.			01	_		Pro	vided	MR		
	 Total numbers or each floor 		O1			110	Videa	A:		
		1	30 m	30 mtr		Pro	vided	MR		
	 Length of hose re hose 	ei .	30 III	u		110	71000			
	Nozzle diameter		5 MM		Pro	vided	MR			
7.	Automatic fire detection	and al	15 150.55		em	1				
<i>'</i> ·	Type of detector		Requ		CIII	Pro	vided	MR		
	Location of Main		Requ				vided	MR		
	Panel	•	rcqu	iii cu		110	7.1404			
	Location of Rep	eater	NA		NA			NA		
	Panel	catci		Q						
	Alternate source	of	NA		ŇA			NA		
	power	VI.						D/65-75		
	Hooters' Location	on	NA			NA		NA		
8.	MOEFA		Requ	uired	Provi	ided		MR		
9.	Public Address System	•		uired	Provi			MR		
10.		stem	12004		11011			1,120		
	Basements		Reg	uired	5.93		Provided	MR		
	Upper Floor		NA				NA	NA		
	Sprinkler above	false	NA:	3			NA	NA		
	ceiling	1000	INA INA					INA.		
11										
	Size of riser/do	wn- coi	mer	N	A -	T	NA	NA		
	Number of hydr	STATES AND STATES		50						
	Hose Box			I	A		NA .	NA		
12	* -	N.		NA .		NA	NA			
12		C11	20.000		NTA.		27.			
	Total number o Hose Box	i nyara	ints	•	NA		NA	NA		
13					NA		NA	NA		
13	Ground Level									
1		-i		NA	¥1		NA			
	> Head of main	Discharge of main pump Head of main numbers					NA	NA		
	Number of mo	 Head of main pump Number of main pumps 					NA	NA		
	> Jockey nump o	ΡŞ	NA NA			NA	NA			
	> Jockey pump b	Jockey pump out putJockey pump head					NA	NA		
1					NA		NA	NA		
	Standby Pump Head Auto Staring/Manual						NA	NA		
				NA			NA	· NA		
	stopping		NA			NA	NA			
	> Pump House Access			NA						
	Terrace level	NA ·			NA	NA				
	 Discharge of pump 			4501			D			
	 Head of the pump Power supply Auto starting of pump 			450 lpm 30 mtrs Required Required			Provided	MR		
							Provided	MR		
5.7							Provided	MR		
1							Provided	MR		

٠



4.1	0 4 1 0			37	-	-			
4.	Captive water Storage for fire fi	ghtin	g:						
	 Under ground tank NA 			NA NA					
- 1	capacity				TVA.	NA			
	Draw off connection	NA			NA	-			
- 1	➢ Fire service inlet	NA			Provided	NA			
- 1	Access to tank	NA			NA	NA.			
5.	Overhead Tank capacity		case		6,000 ltr	MR			
15	Exit Signage	Required			Provided	MR			
16.									
	Pressurization of Lift St	naft	NA		NA NA	NA			
	Pressurization of lift lob	NA		NA	NA				
	 Communication in lift (Requ	ired	Provided	MR				
	 Fireman's Grounding Switch 	Requ		Provided	MR				
~	➤ Lift Signage	Requ	ired	Provided	MR				
17.	Standby power supply		Required		Provided	MR			
18.	Refuge Area								
	> Total area	NA		NA	NA				
	> Location	NA		NA	NA				
19.	Fire control room								
	Detector system panel	NA			NA	NA			
	> PA System Panel N. > Battery backup N. > Building Floor Plans N.		NA		NA	NA			
200			NA NA		NA	NA			
1					NA	NA NA			
			NA		- NA	NA			
20	Systems for Protection of special Risks, if any,	NA		NA		NA			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the FSC issued vide letter No. F6/DFS/MS/GH/SZ/2021/133, dated 11/03/2021 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended. If approved FSC may be issued.

Signature of the Inspecting Officer

Name: Sh. Udaivir Singh

Designation: ADO (DWK)

Colcon W

Newstal AN

1 - Busered 47 oceph

3- Kitch ong Jann