



412

75  
आज़ादी का  
अमृत महोत्सव

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001**

No. F6/DFS/MS/WZ/2024/ 264

Dated: 29/04/2024

**FIRE SAFETY CERTIFICATE**

Certified that the M/s. Bindra Brothers, Located at C-38-39, Rajdhani Market, Raghbir Nagar, Tagore Garden Extn., New Delhi – 110027, in a building comprised of ground & 1<sup>st</sup> floor only, owned/occupied by M/s. Bindra Brothers, was issued Fire Safety Certificate vide Letter No. F6/DFS/MS/2020/WZ/391 dated 01/10/2020. The premises was re-inspected by officer concerned of this department on 01/04/2024 in the presence of Sh. Ajit Pal Singh and found that the said building/Premises have deemed complied with the fire prevention & fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rule 2010 & the building/ premises is fit for occupancy class Storage of rectified spirit and absolute Alcohol with effect from 29/04/2024 for a period of three year in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010 condition mentioned below.

Issued on 29/04/2024 .....at New Delhi by.

(Atul Garg)  
Director

Copy to:

1. The Owner/occupier M/s. A.P.S. Enterprises, Located at C-29-30, Rajdhani Market, Raghbir Nagar, Tagore Garden Extn., New Delhi – 110027.
2. Assistant Commissioner, (M & TP) Govt. of NCT of Delhi, O/o Commissioner of Excise, L & N Block, Vikas Bhawan, New Delhi – 110002.

**Following Fire safety directives must be adhered to:-**

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).
8. **The correct labelling of rectified spirit & Absolute Alcohol be followed.**
9. **Fire Safety Certificate is valid for Ground Floor only.**



~14  
**INSPECTION REPORT**

1. Name & address of the building		Bindra Brothers, Located at C-38-39, Rajdhani Market, Raghubir Nagar, Tagore Garden Extn., New Delhi – 110027.		
2. Type of Occupancy		Godown (Storage of rectified spirit and Absolute Alcohol)		
3. Type of Case		Renewal (Bldg. is Ground & 1 <sup>st</sup> Floor but storage is only on Ground Floor only)		
4. Details of previous NOC		F6/DFS/MS/2020/WZ/391 dated 01/10/2020		
5. Fire Safety directives letter No		Nil		
6. Date of inspection		01/04/2024		
7. Name of the Inspecting Officers		Sarabjeet Singh ADO (MN)		
8. Name and designation of officers from the building side		Sh. Ajit Pal Singh		
9. Year of Construction		-----		
10. Applicant's letter No.		Email dated 23/02/2024		
S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Required as per Rule 35(6) of DFS Rule 2010	Provided at site	Remarks MR/NMR
1	<b>Access to building</b>			
	• Road width	Accessible	Provided	MR
	• Gate width	Accessible	On Main Road	MR
	• Width of internal road	NA	NA	NA
2	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	a. Number of staircases			
	• Upper Floors	NA	NA	NA
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	NA	NA	NA
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NR	NR	NR
	• Pressurization	NA	NA	NA
	e. No. of continuous staircases to terrace	NA	NA	NA
	f. Width of Corridor	NR	NR	NR
	g. Door Size	1.00 mtr	1.50mtr Provided	MR
3	<b>Compartmentation.</b>			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	<b>Smoke Management System.</b>			
	• Basements	NA	NA	NA
	• Upper floors	NA	NA	NA
5	<b>Fire Extinguishers</b>			
	• Total numbers	06 Nos.	Provided	MR
	• Types	CO <sub>2</sub> , ABC type	Provided	MR
	• IS marking	ISI marked	Provided	MR

8/4

6	<b>First-Aid Hose Reels.</b>			
	• Total numbers on each floor	NA	NA	NA
	• Length of hose reel hose	NA	NA	NA
	• Nozzle diameter	NA	NA	NA
7	<b>Automatic fire detection and alarming system.</b>			
	• Type of detectors	NA	NA	NA
	• Location of Main Panel	NA	NA	NA
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	NA	NA	NA
	• Hooters' Location	NA	NA	NA
8	<b>MOEFA</b>			
		NA	NA	NA
9	<b>Public Address System.</b>			
		NA	NA	NA
10	<b>Automatic Sprinkler System.</b>			
	• Ground Floor	Required	Provided	MR
	• Upper Floor	NA	NA	NA
	• Sprinkler above false ceiling	NA	NA	NA
11	<b>Internal Hydrants</b>			
	• Size of riser/down-comer	NA	NA	NA
	• Number of hydrants per floor	NA	NA	NA
	• Hose Box	NA	NA	NA
12	<b>Yard Hydrants.</b>			
	• Total number of hydrants	NA	NA	NA
	• Hose Box	NA	NA	NA
13	<b>Pumping Arrangements.</b>			
	• Ground Level			
	➤ Discharge of main Pump	NA	NA	NA
	➤ Head of Main pump	NA	NA	NA
	➤ Number of main pumps	NA	NA	NA
	➤ Jockey Pump out put	NA	NA	NA
	➤ Jockey pump head	NA	NA	NA
	➤ Standby Pump out put	NA	NA	NA
	➤ Standby Pump Head	NA	NA	NA
	➤ Auto Starting/ Manual stopping	NA	NA	NA
	➤ Pump House Access	NA	NA	NA
	• Terrace level			
	➤ Discharge of pump	450 lpm	450lpm x 2 Provided	MR
	➤ Head of the pump	40 m	Provided	MR
	➤ Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14	<b>Captive Water Storage for fire fighting.</b>			
	• Underground tank capacity	NA	NA	NA
	➤ Draw-off connection	NA	NA	NA
	➤ Fire service inlet	NA	NA	NA
	➤ Access to tank	NA	NA	NA
	• Overhead Tank capacity	10,000 ltrs	Provided	MR
15	<b>Exit Signage.</b>			
		NA	NA	NA
16	<b>Provision of Lifts.</b>			
	• Pressurization of Lift Shaft	NA	NA	NA
	• Pressurization of Lift lobby	NA	NA	NA



n/6

	<ul style="list-style-type: none"> <li>• Communication In lift Car</li> <li>• Fireman's Grounding Switch</li> <li>• Lift Signage</li> </ul>	NA	NA	NA
17	Standby power supply	NA	NA	NA
18	Refuge Area.			
	➤ Total Area	NA	NA	NA
	➤ Location	NA	NA	NA
19	Fire Control Room			
	<ul style="list-style-type: none"> <li>• Detector System Panel</li> <li>• Flow Switch Panel</li> <li>• PA System Panel</li> <li>• Batter backup</li> <li>• Building Floor Plans</li> </ul>	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

**Note: Building comprised of Ground & 1<sup>st</sup> Floor only. Storage is done on Ground floor only. 1<sup>st</sup> floor is being used as rest room for the labours.**

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards of fire Prevention & fire safety required under the rules, the NOC Vide letter no. F6/DFS/MS/2020/WZ/230 dated 29/06/2020 recommended.

68/ADO/MN  
03/04/2024  
12/04/2024

~~ADO (MN)~~

~~ADO~~  
03/04/2024

Signature of the Inspecting Officer  
Name: Sarabjeet Singh  
Designation: ADO (MN)

Correct fsc letter & put up.

DCFO/199.....  
Date: 19/04/2024

~~ADO (MN)~~

~~ADO~~  
19/04/2024

Sir, correct R.S.C is put up for your personalty. pls.

Sir, no pending.

~~ADO (MN)~~

~~ADO~~  
12/4/2024

DCFO/199.....  
Date: 19.04.24.....

~~ADO (MN)~~  
19/4

Director  
19/4/2024

~~ADO~~  
19/4/2024