

C-139

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001**

No. F6/DFS/MS/GH/NDZ/2024/111

Dated: 02/05/2024

**FIRE SAFETY CERTIFICATE**

Certified that the M/s Hazi Hotel located at 914-18, Kabari Bazar, Jama Masjid, Delhi-06, comprised of Ground + 02 upper floors: Ground floor – (commercial use), 1<sup>st</sup> floor – (reception + 07 guest rooms), 2<sup>nd</sup> floor – (02 guest rooms), total 09 guest rooms was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2021/286 dated 04.08.2021. The building/premises was re-inspected by the officer concerned from this department on 25.04.2024 in presence of Mohd. Sadiq (Manager) and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of (Group A-1) “Residential”, (1<sup>st</sup> floor – (07 guest rooms) & 2<sup>nd</sup> floor - (02 guest rooms) for total 09 guest rooms only, with effect from ..02/05/2024.... for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on .....02/05/2024.....at New Delhi by

  
(Atul Garg)  
Director  
Delhi Fire Service 016  
Tel: 011-23414000

**Copy to:-**

1. The Joint Commissioner of Police (Licensing), 1<sup>st</sup> Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2024032303540 dated 14.04.2024.
2. The Licensee, M/s Hazi Hotel at 914-18, Kabari Bazar, Jama Masjid, Delhi-06.

**Conditions for the validity of fire safety certificate**

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry”.
8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

## INSPECTION REPORT

1	Name & address of the building	M/s Hazi Hotel located at 914-18, Kabari Bazar Jama Masjid, Delhi-06.		
2	Building is comprised of	(Ground + 02 upper floors) Ground floor - (commercial use) 1 <sup>st</sup> floor - (reception + 07 guest rooms) 2 <sup>nd</sup> floor - (02 guest rooms)		
3	Type of Occupancy	Residential Group A-1		
4	Type of Case	Renewal		
5	Details of Previous FSC	F6/DFS/MS/GH/NDZ/2021/286 dated 04.08.2021		
6	Fire Safety direction letter No	Nil		
7	Date of Inspection	25.04.2024		
8	Name of the Inspecting Officers	Sumit Kumar, ADO (SPM)		
9	Name of the designation of Officer from the building side	Mohd. Sadiq (Manager)		
10	Year of Construction	1938		
11	Applicant's letter No	Online I.D No. 2024032303540 dated 14.04.2024		
S.No	Minimum Standards on fire Prevention and fire safety requirements U/R 33	Requirement/ Existing fire safety arrangements	Provided at Site	Remarks MR/NMR
1	<b>Access to building</b>			
	Road width	NA	14 m ✓	NA
	Gate width	NA	NA	NA
	Width of internal road	NA	NA	NA
2	<b>Number, Width, Type and Arrangement of Exits</b>			
	<b>A. Number of Staircases</b>			
	Upper Floor	01 no.	02 nos. ✓	MR
	Basement	NA	NA	NA
	<b>B. Width of Staircases</b>			
	Upper Floor	80 cms	90 cms, & 95 cms	MR
	Basement	NA	NA	NA
	<b>C. Protection of exits</b>			
	Fire check door	NA	NA	NA
	Pressurization	NA	NA	NA
	<b>D. No. of continuous staircases to terrace</b>			
		01 no.	01 no. ✓	MR
	<b>E. Width of Corridor</b>			
		NA	NA	NA
	<b>G. Door size</b>			
		1.0 m	1.0 m ✓	MR
3	<b>Compartmentation</b>			
	Fire check door	NA	NA	NA
	Sealing of electrical shafts	NA	NA	NA
	Fire rating of shaft door	NA	NA	NA
	Water curtain	NA	NA	NA
	Fire Dampers	NA	NA	NA
4	<b>Smoke Management System.</b>			
	Basement	NA	NA	NA
	Upper floor	12 ACPH	Natural	MR

5.	<b>Fire Extinguisher</b>		08 nos.	MR
	Total numbers	05 nos.		MR
	types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR
	IS marking	Required	Provided	MR
6	<b>First-aid-Hose Reels.</b>		01 no. at 1 <sup>st</sup> floor	MR
	Total numbers of each floor	01 no.	only	MR
	Length of hose reel hose	30 m	30 m	MR
	Nozzle diameter	05 mm	05 mm	MR
7	<b>Automatic fire detection and alarming system.</b>			MR
	Type of detectors	Required	Provided	MR
	Location of main panel	Required	Provided at reception	MR
	Location of repeater panel	NA	NA	NA
	Alternate source of power	Required	Provided	MR
	Hooters	Required	Provided	MR
8	<b>MOEFA</b>	NA	NA	NA
9	<b>Public address System.</b>	Required	Provided	MR
10	<b>Automatic Sprinkler System.</b>			NA
	basement	NA	NA	NA
	upper floor	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11	<b>Internal Hydrants</b>			NA
	size of riser/down-comer	NA	NA	NA
	Number of hydrants per floor	NA	NA	NA
	Hose Box	NA	NA	NA
12	<b>Yard Hydrants.</b>			NA
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
13	<b>Pumping Arrangements.</b>			
	• Ground Level			
	➤ Discharge of main Pump	NA	NA	NA
	➤ Head of Main Pump	NA	NA	NA
	➤ Number of main pumps	NA	NA	NA
	➤ Jockey pump out put	NA	NA	NA
	➤ Jockey pump head	NA	NA	NA
	➤ Standby pump out put	NA	NA	NA
	➤ Standby pump Head	NA	NA	NA
	➤ Auto Starting /Manual stopping	NA	NA	NA
	➤ Pump House Access	NA	NA	NA
	• Terrace Level			
	➤ Discharge of pump	225 LPM	225 LPM	MR
	➤ Head of the Pump	40 m	40 m	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR

L.S.

- 17/96 -

<b>14</b>	<b>Captive Water Storage for Fire Fighting.</b>			
	Underground tank capacity	NA	NA	NA
	Draw-off connection	NA	NA	NA
	Fire service inlet	NA	NA	NA
	Access to tank	NA	NA	NA
	Overhead Tank capacity	2500 ltrs	2500 ltrs. ✓	MR
<b>15</b>	<b>Exit Signage.</b>	Required	Provided	MR
<b>16</b>	<b>Provision of Lifts.</b>			
	Pressurization of Lift Shaft	NA	NA	NA
	Pressurization of Lift lobby	NA	NA	NA
	Communication in lift car	NA	NA	NA
	Firemen's grounding switch	NA	NA	NA
	Lift Signage	NA	NA	NA
<b>17</b>	<b>Standby power supply</b>	Required	Provided ✓	MR
<b>18</b>	<b>Refuge Area.</b>			
	Total area	NA	NA	NA
	Location	NA	NA	NA
<b>19</b>	<b>Fire Control Room</b>			
	Detector system panel	NA	NA	NA
	Flow switch panel	NA	NA	NA
	PA system panel	NA	NA	NA
	Batter backup	NA	NA	NA
	Building Floor Plans	NA	NA	NA
<b>20</b>	<b>Special Fire Protection systems for protection of special Risks, if any:</b>		NA	NA

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2021/286 dated 04.08.2021 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Sumit Kumar  
26/04/2024

Signature of the Inspecting Officer  
Name Sumit Kumar  
Designation ADO (SPM)

DO (CD)

*[Signature]*  
26/4/24

*[Signature]*  
By C.F.O. (DOZ)

*[Signature]*  
29/04/24

C.F.O. *[Signature]*  
29/4/24

Director *[Signature]*  
30/04/24

*[Signature]*  
ADO/SPM