



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/School/ 373

Dated: 61 /0,5 /2024

## FIRE SAFETY CERTIFICATE

Certified that the M.C. Primary Co-ed School (School ID No-1253124) located at Mohan Park, Model Town Part-III, Delhi-110009 comprised of 02 blocks (01 block comprised of Ground floor & 01 block comprised of Ground plus first floor only) owned/occupied by M.C. Primary Co-ed School was granted FSC by this department vide letter no. F6/DFS/MS/School/2021/205 dated 10.03.2021. The premises was inspected by the officer concerned of this department on 24.04.2024 in presence of Smt. Suhita Khanna (Incharge) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class "Group B Educational" conditions mentioned below:

Issued on ...01 05 2024 ... at New Delhi by

Ph/-011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Incharge, M.C. Primary Co-ed School (School ID No-1253124) located at Mohan Park, Model Town Part-III, Delhi-110009

## Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures

All the staff members must know the correct method of operation of firefighting system.

4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit

5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

## INSPECTION REPORT

1. Name & address of the building : NDMC Primary Co-ed School, Mohan Park, Model Town-III, Delhi-09.

2. Type of Occupancy : Educational

3. Type of Case : Renewal

4. Composition of building : 02 blocks (01 block, Ground floor & 01 block. Ground + First floor only)

5. Details of previous NOC : No.F6/DFS/MS/School/2021/205 Dated 10.03.2021

5. Fire Salety directives letter No : Nil

7. Date of inspection : 24.04.2024
8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side : Smt. Suhita Khanna (Incharge)

10. Year of Construction : 1972/2002

11. Applicant's letter No. : Letter No. Nil & DFS Dairy no. 570 Dated: 12.04.2024

	Minin	um Standards on fire prevention and fire safety U/R 33	Director of Education	Provided at site	Remarks MR/NMR		
	Access to building						
	•	Road width	06m	09m	MR		
	- :	Gate width Width of internal road	4.5m	3.70m	MR(being old		
	None		NA	NA	case)		
	Number, Width, Type & Arrangement of Exits						
		Upper Floors	01	02	MD		
		Basements	NA	NA NA	MR NA		
	b. Widt	h of staircases			INA		
		Upper Floors	1.5m 1.90m & 85 cm( MP(-11)				
		Basements		1.90m & 85 cm( iron staircase)	MR(old case		
	c. Prote	ection of exits	NA	NA	NA -		
		Fire check door					
	-	Pressurization	NA	NA	NA		
	d. No.	of continuous staircases to terrace	NA	NA	NA		
		th of Corridor	NA	NA	NA		
	f. Door		NA	NA	NA		
3		artmentation.	01m for class rooms & 1.50m for Hall	1.10m 1.50m each for Hall	MR		
	•		. 1869	The sin eden for riall			
	•	Fire check door	NA	NA			
	•	Sealing of electrical shafts	NA	NA	NA		
	•	Fire Rating of shaft door	NA		NA		
	•	Water Curtain	WAS CO	NA	NA .		
	•	Fire Dampers	NA	NA	NA		
4	Smok	e Management System.	NΛ	NA	NA		
	•	Basements			INA		
	•	Upper floors	NA	NA	NA		
5	Fi	re Extinguishers	Required	Natural Ventilation	MR		
		Total numbers		The second second			
			07nos	08nos	100		
		Types	ABC/Co2	ABC-08	MR		
6	First	ISI marking	ISI Marked		MR		
	. 1131-	Aid Hose Reels.		Provided	MR		

		N/22					
	Total numbers on each floor	NA	NA				
	Length of hose reel hose	NA	NA	N			
	Nozzle diameter	NA	NA	NA NA			
	Automatic fire detection and alarming system.						
	Type of detectors	NA	NA	N/			
J	Location of Main Panel	NA	NA	N/			
	Location of Repeater Panel	NA	NA	N/			
	Alternate source of power	NA	NA	N/A			
	Hooters' Location	NA	NA	N/			
	as avertical processing in the event of the control	NA NA	NA	NA NA			
	MOEFA	NA .	1,1/1				
	Public Address System.		2 541				
	Automatic Sprinkler System.	214	NA	NA NA			
	Basement	NA NA	NA NA	NA NA			
	Upper Floor	NA NA	NA NA	NA			
	Sprinkler above false ceiling	NA	A CONTROL OF THE CONT	35%			
	Internal Hydrants		, F , E	April 1			
	Size of riser/down-comer	NA	NA	NA			
	Number of hydrants per floor	NA	NA	NA			
	Hose Box	NA	NA	NA			
8	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
	Pumping Arrangements.						
	Ground Level						
	> Discharge of main Pump	N/A	N/A	N/A			
	➤ Head of Main pump						
	➤ Number of main pumps	N/A	N/A	N/A			
	➤ Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	NA	NA	NA			
	> Standby Pump out put	NA	NA	NA NA			
	> Standby Pump Head	N/A	N/A	N/A			
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	N/A	N/A	N/A			
	Terrace level	N/A	N/A	N/A			
	Discharge of pump						
	Head of the pump	NA	NA NA	NA			
	➤ Power Supply	NA	NA .	NA			
	Auto Starting of pump	NA	NA .	NA			
		NA	NA	NA			
14	Captive Water Storage for fire fighting.						
	Underground tank capacity	NA	NA .	NA			
	➤ Draw-off connection	NA	NA NA	NA NA			
	➤ Fire service inlet	NA NA	NA NA	NA NA			
	> Access to tank	NA NA	NA NA	NA NA			
		<b>&amp;</b>					



T	Overhead Tank capacity	NA	NA NA	NΛ		
	Exit Signage.	NA	NA L	NA		
-	Provision of Lifts.					
1	n wingtion of Lift Shaft	N/A	N/A	N/A		
	<ul> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A	N/A		
	Communication In lift Car     Fireman's Grounding Switch	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Lift Signage	N/A	· N/A	N/A		
	Standby power supply	N/A	N/A	N/A		
-	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
ī	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	<ul> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education Circular, the FSC issued vide letter of even no.F6/DFS/MS/School/2021/205 dated 10.03.2021 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

Signature of the Inspecting Officer

Name :- C.L. Meena

Designation:- Asst. Div. Officer (RN)

Dy. Chief Fire Officer (WZ)

There is no pending Fide before recivad

24/04/24