GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001 No.F6/DFS/MS/GH/2024/106 Dated :0.L./0.5./2024

FIRE SAFETY CERTIFICATE

Certified that the M/S Neu Villa Guest House located at 1719, 1720, 1728 & 1729, Pratap Gali, Chuna Mandi, Pahar Ganj, New Delhi comprised of Basement + stilt, ground + 03 Upper floors, Basement (Storage), stilt parking - ground floor to 3rd floor (06 guest rooms at each floor), total 24 guest rooms, was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2021/179 dated 05/04/21 & No.03 dated 03.01.2022 and name changed vide letter no. 404 dated 14.08.2023. Now, the premises was re-inspected by the officer concerned of this department on 22/04/24 in the presence of Mr. Akhil and found that the said guest house building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Stilt - parking, ground floor to 3rd floor (06 guest rooms at each floor), total 24 guest rooms only, and valid up to 31.03.2027 from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 01/05/2024 at New Delhi by.

Delhi/Fire Service

Copy to:-

1. The Commissioner, MCD, Civic Centre, New Delhi: to kindly ensure the occupancy as detailed above and deviation in construction if any.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.

ID no. 2024041004676 dated 10/04/24.

3. The Manager, M/S Neu Villa Guest House at 1719, 1720, 1728 & 1729, Pratap Gali, Chuna Mandi, Pahar Ganj, New Delhi.

Conditions for the validity of Fire Safety Certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.

2. Any loss of life or property due to non functional fire safety measures shall be at the

responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

9. Any flammable material for interior decoration is prohibited.

M/S Neu Villa Guest House at 1719, 1720, 1728 & 1729, Pratap Gali, Chuna Mandi, Pahar Ganj, New Delhi 2. Type of occupancy:-Residential, Sub Division-A-1 B + stilt, Gr. + 03 Upper floors (total 24 Guest rooms) Basement -storage, ground floor to 3rd floor (06 guest rooms at each floor) 3. Type of case:-Renewal 4. Details of previous FSC:-No. F6/DFS/MS/GH/2021/179 dated 05/04/21. Fire safety directives No.-N/A 6. Date of inspection:-22/04/24 7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC) 8. Name & designation of officer From the building side:-Mr. Akhil 9. Year of construction:-2013 10. Applicant's letter No:-Id no. 2024041004676 dated 10/04/24. Old Case Requirement/ Minimum Standards on fire Provided at site Remarks S.No. **Existing fire** MR/NMR Prevention and fire safety safety U/R 33 arrangements Access to Building 1. N/A N/A 09 mtr. 1) Road width N/A N/A N/A 2) Gate width N/A N/A 3) Width of internal road N/A Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 01 01 1. Upper floors MR 02 Nos. 02 Nos. 2. Basements B. Width of staircase MR 1. Upper floors 1.6 mtr. 1.5 mtr. MR 1.5 & 1.2 mtr. 1.0 mtr. 2. Basements C. Protection of exits MR Provided Required 1. Fire check door N/A N/A N/A 2. Pressurization MR 01 01 D. No. of continuous staircase to terrace MR 01 mtr. 01 mtr. E. Width of corridor MR 01 mtr. 01 mtr. F. Door size Compartmentation 3. provided MR Required 1) Fire check door N/A 2) Sealing of electrical shafts N/A N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System 4. MR Mechanical 12 ACPH 1) Basements MR Natural 12 a/c per 2) Upper floors hour Fire Extinguishers 5. MR 12 Nos. 10 Nos. 1) Total numbers MR ABC & CO2 ABC & CO2 2) Types MR Provided Required 3) ISI marking

INSPECTION REPORT

1. Name & address of the building

N/21

	I			
6.	First-Aid Hose Reel	01	01	MR
	1) Total number of eachfloor	30 mtr.	30 mtr.	MR
	2) Length of hose reel hose	05 mm	05 mm	MR
	3) Nozzle diameter			
7.	Automatic Fire Detection &		Provided	MR
	1) Type of detectors CO type	Required	Provided	MR 💹
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	Required	Provided	MR
	4) Alternate source of power	at each floor	Provided	MR
	5) Hooter's Location		Provided	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	1
10.	Automatic Sprinkler System		Provided	N/A
	1) Basement less than 200 SQM	N/A	N/A	N/A
	2) Upper floors	N/A	Control of the contro	N/A
	3) Sprinkler above false ceiling	N/A	N/A	IVA
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	****		
12.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
13.	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	 f) Stand by pump output 	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fi			
	Under ground tank capacity	N/A	30,000 ltr.	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	Required	Provided	MR
	d) Over head tank	5,000 ltr.	10,000 ltr.	N/A

N/22

15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
44	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syst Risk, if any:	N/A		

The fire protection systems provided in the building were randomly tested, checked

and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter no. No. F6/DFS/MS/GH/2021/179 dated 05/04/21, under rule 35(6) of the Delhi Fire Service rules 2010 Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Sh. Ravinder Singh Designation: ADO (CC)

21/4/24

CGO (002)

, (

Dinecto

25/84/24

Anyh