

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/School/NDZ/2024/ 402

Dated: 08 / 05/2024

FIRE SAFETY CERTIFICATE

Certified that the Sahu International School School running at ground plus one floor located at E-1/1097/2, 4 1/2 Pusta, Sonia Vihar, Delhi-110090, comprised of ground plus two upper floors only owned / occupied by Sahu International School, was issued Fire Safety Certificate vide letter No. F6/DFS/MS/School/2021/NDZ/523 dated 23/07/2021. The School building was reinspected by the officer concerned of this department on 23/04/2024 in presence of Mr. Surendra Sahu (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the Fire Prevention and Fire Safety requirements in accordance with Circular No. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education and that the School building is fit for ground plus one floor occupancy class "Educational" (Group-B) with effect from 08/05/2024 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 08 05 2024 at New Delhi by.

Copy to:-

1. The Director of Education, MCD, Udyod Sadan, Plot no.419, FIE, Patparganj Industrial Area, Delhi-110092.

The Principal, Sahu International School located at E-1/1097/2, 4 1/2 Pusta, Sonia Vihar, Delhi-110090.

Conditions for the validity of Fire Safety Certificate

1. This FSC is being issued for ground plus one upper floor only.

2. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry

3. All the means of escape shall be kept free of all the type of obstruction all the time.

4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

6. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.

7. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

N108

1	N	INSPEC	CTION REPOR	T			
1	IN	me & address of the building	Sahu International School located at E-1/1097/2				
2	Bı	ilding is comprised of	4 ½ pusta, Sonia Vihar, Delhi-110090.				
		The state of	Ground plus two upper floors only. (School is				
3	Ty	pe of occupancy	running ground plus one upper floor only)				
4		pe of case	Educational Building Renewal				
5		tails of previous FSC	F6/DFS/MS/School/2021/NDZ/523 dated				
		, , , , , , , , , , , , , , , , , , , ,	23/07/2021.				
6	Fi	e safety directives letter no.	F16/Estate/CC/Fire Safety/2011/3298-3398				
		,	dated 23.07.2021.				
7	Da	te of inspection	23.04.2024				
8	-	me of the inspecting officers					
9		me of the designation of					
		icer from the building side	2015				
10		ar of construction					
11	Applicant's letter no. Email dated 20/04/2024			/04/2024			
S.No		Minimum standard of fire	Circular Provided at site Remarks				
	D	revention and fire safety U/R	requirement	1 Tovided at site	MR/NMI		
	P	33		ata a transfer	MICHINI		
1	Ac	cess to Building:		1040			
	A	Road width	6.0 mtrs.	9.0 mtrs. /	MR		
	В	Gate width	N/A	N/A	N/A		
	C	Width of internal road	N/A	N/A	N/A		
2	Nu	mber, Width, Type and Arran			1,1/11		
	A	Number of staircases					
		a Upper floor	01 nos.	01 nos. C	MR		
		c Basement	N/A	N/A	N/A		
	В	Width of staircases			1,711		
		a Upper floor	1.50 mtrs.	1.88 mtrs.	MR		
		b Basement	N/A	N/A	N/A		
]	C	Protection of exits					
- }	_	a Fire check door	N/A	N/A	N/A		
-	D	b Pressurization No. of continuous staircases	N/A	N/A	N/A		
	וש	to terrace	01 nos.	01 nos.	MR		
F	E	Width of corridor	1.50 mtrs.	1.88 mtrs. <	MR		
	F	Door size	01 mtrs.	01 mtrs.	MR		
3	Co	npartmentation:	91 May.	or mus.	IVIK		
	A	Fire check door	NA	NA	NA		
	В	Sealing of electrical shafts	N/A	N/A	N/A		
	C Fire rating of shaft door		N/A	N/A	N/A		
	D Water curtain		N/A	N/A	N/A		
4	E	Fire dampers	N/A	N/A	N/A		
4	707	oke Management System:					
-	A	Basement Linnar floor	N/A	N/A	N/A		
	B	Upper floor	N/A	N/A	N/A		

U)

Sahu International School located at E-1/1097/2, 4 1/2 pusta, Sonia Vihar, Delhi-110090.

5.	Fire Extinguisher:						
	A	Total numbers	04 Nos.	07 Nos.	MR		
	B	Types	CO ₂ & ABC	CO ₂ & ABC	MR		
	C	ISI marking	ISI Marked	ISI Marked	75.55		
6	First-Aid-Hose Reel:						
	A	Total numbers of each floor	N/A	N/A	N/A		
	В	Length of hose reel hose	N/A	N/A	N/A		
	C	Nozzle diameter	N/A	N/A	N/A		
7	Automatic Fire Detection and Alarming System:						
	A	Type of detectors	N/A	N/A	N/A		
	B	Location of main panel	N/A	N/A	N/A		
	C	Location of repeater panel	N/A	N/A	N/A		
	D	Alternate source of power	N/A	N/A	N/A		
	E	Hooters	N/A	N/A	N/A		
8		OEFA:	N/A	N/A	N/A		
9	Pu	blic Address System:	N/A	N/A	N/A		
10	Au	tomatic Sprinkler System:		IVA	IN/A		
	A	Basement	N/A	N/A	N/A		
	В	Upper floor	N/A	N/A	N/A		
	C	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants:			N/A	N/A		
	A	Size of riser/down-comer	N/A	N/A	N/A		
	В	Number of hydrants per floor	N/A	N/A	N/A		
	C	Hose box	N/A	N/A	0505545		
12	Yard Hydrants:						
	A	Total number of hydrants	N/A	N/A	N/A		
	В	Hose box	N/A	N/A	Windered		
13	Pu	mping Arrangements:	- W.A. A.	IVA	N/A		
	Ground level						
	A	Discharge of main pump	N/A	N/A	N/A		
	В	Head of main pump	N/A	N/A	N/A		
	C	Number of main pumps	N/A	N/A			
	D	Jockey pump out put	N/A	N/A	N/A		
	E	Jockey pump head	N/A	N/A	N/A		
	F	Standby pump out put	N/A	N/A	N/A N/A		
	G	Standby pump head	N/A	N/A			
	Н	Auto starting /manual	N/A	N/A N/A	N/A N/A		
		stopping	1.07.1.	WA	IN/A		
	I Pump house access		N/A	N/A	N/A		
2	Terrace Level						
	A	Discharge of pump	N/A	N/A	N/A		
	B	Head of the pump	N/A	N/A	N/A		
	C	Power supply	N/A	N/A	N/A		
	D	Auto starting of pump	N/A	N/A	N/A		

Sahu International School located at E. 1900

14	Captive Water Storage for Fire Fighting: A Underground tool					
	A		ing:			
	В	Bround lank connects.	N/A	N/A	N/A	
	C	Diaw-Oil Connection	N/A	N/A	N/A	
	D	Fire service inlet	N/A	N/A	N/A	
	E	Access to tank	N/A	N/A	N/A	
15		Overhead tank capacity	N/A	N/A	N/A	
15	Exit Signage:		N/A	N/A	N/A	
16	Provision of Lifts:					
	A	Pressurization of lift shaft	N/A	N/A	N/A	
	B	Pressurization of lift lobby	N/A	N/A	N/A	
	C	Communication in lift car	N/A	N/A	N/A	
	D	Firemen's grounding switch	N/A	N/A	N/A	
	E	Lift signage	N/A	N/A	N/A	
17	Sta	ndby Power Supply:	N/A	N/A	N/A	
18	Refuge Area:					
	A	Total area	N/A	N/A	N/A	
	B .	Location	N/A	N/A	N/A	
19	Fire Control Room:					
	A	Detector system panel	N/A	N/A	N/A	
	В	Flow switch panel	N/A	N/A	N/A	
		PA system panel	N/A	N/A	N/A	
	D	Battery backup	N/A	N/A	N/A	
	E	Building floor plans	N/A	N/A	N/A	
20	Special Fire Protection systems for protection of special Risks, if any:		N/A	N/A	N/A	

Note: - Building comprised of ground plus second upper floor but management has given undertaking that they will not use second floor for school purpose and any purpose in any case. FSC is recommended for ground plus one floor only.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no F16/Estate/CC/Fire Safety/2011/3298-3398 dated 01.03.2011, the FSC issued vide letter no. F6/DFS/MS/School/2021/NDZ/523 dated 23/07/2021 is recommended to be renewed.

Signature of the Inspecting Officer
Name Vashwant Single A

Name Yashwant Singh Meena Designation ADO (L.N)

Dy. CFO (NDZ)

3 51 20

Dineter

poolth