## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI LEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2024/SZ 1 366

Dated: 29/04/2024

## FIRE SAFETY CERTIFICATE

Certified that the Shri Narayan International School, Plot No.-45 A, Ram Chander Enclave, Mohan Garden, Uttam Nagar, New Delhi-110059, comprised of ground plus one upper floor only, owned/occupied by Shri Narayan International School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2019/SZ/531 dated 14.03.2019 (for ground floor only). The school building was re-inspected by the officer concerned of this department on 22.04.2024 in the presence of Sh. Mohan Jha (Chairman) and found that School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/premises is fit for occupancy class "Education" (for ground plus one upper floor only) w.e.f. the date of issue the certificate for the period of three years, subject to compliance of the conditions printed as below.

Issued on 29 04 2024 at New Delhi by

Delhi Fire Service

Copy to:-

1. The Chairman, Shri Narayan International School, Plot No.-45A, Ram Chander Enclave, Mohan Garden, Uttam Nagar, New Delhi-110059

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi- 110054.

## Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of

occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized

construction, if any.

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

to its expiry.

## INSPECTION REPORT

1. Name & address of the building : Shri Narayan International School, Plot No.-45 A, Ram Chander Enclave

Mohan Garden, Uttam Nagar, New Delhi-110059.

Ground plus one upper floor only Building Comprised of

3. Type of Occupancy Educational

New/addition alteration 4. Type of Case

: F.6/DFS/MS/School/2019/SZ/531 dated 14.03.2019 (for ground floor only) 5. Details of Previous NOC F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

6. Fire Safety directives letter No

22.04.2024 7. Date of inspection A.D.O. R.K. Yadav (JKP)

8. Name of Inspecting Officer 9. Name and designation of officers

Sh. Mr. Mohan Jha (Chairman) From the building side

Before 2018 10. Year of Construction

SMS/01/2023-24 dated 28.03.2024 11. Applicant's letter No.

. No.	Minimum Standards on fire prevention and fire safety U/R 33	Dir. Of Edu. Circular dt. 01.03.2011	Provided at site	Remarks MR/NMR			
	Access to building						
	<ul> <li>Road width in front of school</li> <li>Gate width</li> <li>Width of internal road</li> </ul>	Accessible (06 mtrs) 4.5 mtrs N/A	Provided Provided N/A	M/R M/R N/A			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases		20	MR			
	Upper Floors	02	02	The Section of			
	Basements	N/A	N/A	N/A			
	b. Width of staircases			MR			
	Upper Floor	1.50 mts each	1.50 mts each	N/A			
	Basements	N/A	N/A	INIM			
	c. Protection of exits  Fire check door		NT/A	N/A			
	• Pressurization	N/A	N/A N/A	N/A			
	d. No. of continuous staircases to	N/A	775, 1189, 109	MR			
	terrace	01	Provided	MK			
	e. Width of Corridor	N/A	N/A	N/A			
	f. Class Room Door Size	100 cms	Provided	M/R			
3.	Compartmentation						
	Fire check door	N/A	N/A	N/A			
	<ul> <li>Sealing of electrical shafts</li> <li>Fire Rating of shaft door</li> <li>Water Curtain</li> <li>Fire Dampers</li> </ul>	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
4.	Smoke Management System						
	Basements	N/A	N/A	N/A			
	Upper floors	Required	Natural ventilation provided	M/R			
5.	Fire Extinguishers						
	Total numbers	06 no's	Provided	M/R			
	• Types	ABC type	Provided	M/R			
	IS marking	ISI marked	ISI marked	M/R			
6.	First-Aid Hose Reels						
	Total numbers on each floor	N/A	N/A	N/A			
	The second second bases	N/A N/A	N/A	N/A			
	• Length of hose reel nose		N/A	N/A			

	Automatic fire detection and alarming s		N/A	N/A			
	Type of detectors	N/A	N/A	N/A			
	Location of Main Panel	N/A	4010000	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	<ul> <li>Alternate source of power</li> <li>Hooters' Location</li> </ul>	N/A	N/A	N/A			
		N/A N/A	N/A N/A	N/A			
3.	MOEFA		N/A	N/A			
9.	Public Address System	N/A	IVA	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
0.	Automatic Sprinkler System			NIA			
	Basement	N/A	N/A	N/A N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements	T <sub>W</sub>					
	Ground Level						
	➤ Discharge of main Pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	> Number of main pumps	N/A	N/A	N/A			
	<ul><li>Jockey Pump out put</li><li>Jockey pump head</li></ul>	N/A	N/A	N/A			
	> Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
	> Auto Starting/Manual Stopping	N/A	N/A	N/A			
		N/A	N/A	N/A			
	N DOWN THE ALLER A	N/A	N/A	N/A			
	<ul> <li>Pump House Access</li> <li>Terrace level</li> </ul>						
	> Discharge of pump	N/A	N/A	N/A			
	➤ Head of the pump	N/A	N/A	N/A			
	<ul><li>Power Supply</li><li>Auto Starting of pump</li></ul>	N/A	N/A N/A	N/A N/A			
	Auto Starting of pump	N/A	N/A	IN/A			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	<ul> <li>Access to tank</li> <li>Overhead Tank capacity</li> </ul>	N/A	N/A	N/A			
		N/A	N/A	N/A			
15.	Exit Signage.	N/A	N/A	N/A			
16.	Provision of Lifts. (No Lift)						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
	Standby power supply	N/A	N/A	N/A			

Refug	e Area.				
>	Total Area	N/A	N/A	N/A	
>	Location	N/A	N/A	N/A	
Fire Control Room					
•	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
•	Battery backup	N/A	N/A	N/A	
•	Building Floor Plans	N/A	N/A	N/A	
	l Fire Protection System for tion of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note:- This department has already issued FSC vide letter number F.6/DFS/MS/School/2019/SZ/531 dated 14.03.2019 for ground floor only. But now the school management apply for ground plus one upper floor only.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/School/2019/SZ/531 dated 14.03.2019, renewal under the Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 is recommended.

Signature of Inspecting Office

Name: - R.K. Yadav Designation:- ADO (JKP)

DO (South West)

1 - 1 W

 $n \sim$