FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE [Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No. F6/DFS/MS/2024/GH 119

Dated: 66 /05/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Hotel Suprabhat, Located at 1st, 2nd, & 3rd floor, 18/24, Abdul Rehman Road, Karol Bagh, New Delhi-110005, in a building comprised of Basement + Ground + 3 Upper Floors using basement as (store & office) Ground floor (office & shop), 1st floor to 3rd floor (09 guest rooms each floor) (Total=27 rooms) was issued FSC vide Letter No. F6/DFS/MS/GH/SZ/2021/151, dated 23/03/2021. The premises was re inspected by the officer concerned of this department on 26/04/2024 in the presence of Sh. Surya Rao (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential" (guest house) at 1st floor to 3rd floor (09 guest rooms each floor) (Total=27 rooms) with effect from 06/05/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .. 0.6. 0.5. 2024. at New Delhi by.

Delhi Fire Ser

Copy to:

- 1. The Joint. Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony,
- 2. The Manager, M/s Hotel Suprabhat, Located at, 1st, 2nd, & 3rd floor, 18/24, Abdul Rehman Road, Karol Bagh, New Delhi-110005.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. The trained staff should be available round the clock.

- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any

6. Basement strictly shall be kept vacant as seen during inspection.

7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

Name & address of the building: M/s Hotel Suprabhat, Located at, 1st, 2nd, & 3rd floor, 18/24, Abdul Rehman Road, Karol Bagh, New Delhi-110005.

2. Type of Occupancy.

:Lodging or rooming "A-1"

 Type of Case : Renewal (Running at 1st, 2nd, & 3rd floor in a building comprised of Basement, Ground + 3 Upper Floor)

4. Details of previous NOC: F6/DFS/MS/GH/SZ/2021/151, dated 23/03/2021

5. Fire Safety directives Letter No.: Nil

6. Date of inspection .

:26/04/2024

7. Name of the Inspecting Officer: ADO (DWK)

8. Name and designation of Officer

from the building side

: Sh. Surya Rao (Manager)

9. Year of Construction

: Before 2000-01

10. Applicant's letter No.

: 2024040904551, dated 12/04/2024

No	Minimum standards on fire prevention and fire safety U/R	33	As per N/27, N/28 & N/29		,	Provided at site			Remarks MR/NMR	
	Access of building								MR	
	Road width					09 mtr			NA	
	 Gate width 	-			Direct accessible f		le fro	m road		
	 Width of internal road 	N	A in	NA			registif	NA		
2.	Number, width, Type & Arran	gen	nents of e	xits	VV.					
	a. Number of staircases		1		0.4) (D	Ф.: a	ld agga)	
	Upper floors :	01 No.		01			MR (Being old case)		id case)	
	Basements		1 No.	. 02 Nos. M		MR	R ·			
	b. Width of staircases		Y	- 27 2				m m :	14	
	Upper floors		old case		1.22 m			MR (Being old case		
280	Basements	Old case 1.2		20m	0m M		IR (Being old case			
•	c. Protection of exits			10	30					
	 Fire check door Pressurization d. No of continuous staircase to terrace e. Width Of Corridor f. Door Size 		Required Provided					MR		
			NA			NA		NA		
			01 01				MR			
			1 m 1.45m		45m	MR (Be		MR (Beir	ng old case	
			lm		0.85m X2.05m			MR (Being old case		
		+	lm	Ι υ.	6JIII A	2.05		(1211)		
3.		+	· · · · · ·		l r	rovi	ded	18	MR	
	Fire check door		Required			Sealed			MR	
	Sealing of electrical		Required			Scarc	u		20000	
	shafts • Fire Rating of shaft	: -	NA		ı	NA			NA	
	door	- -) , , , , , , , , , , , , , , , , , , ,		- ,	NA			NA	
	Water Curtain		NA			NA NA		NA		
	Fire Dampers	_	NA			IAM				
4.	Smoke managements System	1			_ l	, c		ided	MR	
5,000	• Basements 30	a/a	a/c per hour Ex			Exhaust fan provided Vatural Ventilation			MR	
1	• Upper floors 12	12 a/c per hour			Natur	al Ve	entilat	ion	IATIC	





5.	Fire E	extinguishers		7	T		
	•	Total numbers	12	Nos.		Provided	MR
		Types		BC & C	Óż	CO ₂ & ABC	MR
	•	IS marking		equired		Provided	MR
5.	First -	- Aid Hose Reels	-			1101100	
		Total numbers on	01	•		Provided	MR
		each floor	- 1				
. 0	•	Length of hose reel hose	30	mtr	÷	Provided	MR
		Nozzle diameter	5 N	ИM		Provided	MR
7.	Autor	natic fire detection and			em		
<i>'</i> .	Autor	Type of detectors	C	O detect	ors	Provided	MR
	•	Location of Main		Required		Provided	MR
		Panel	NA		NA		NA
12		Location of Repeater Panel	INA	A c	INA		
	, a	Alternate source of	Red	quired	DG	set 72 KVA	MR
		power	I	quirec			
		Hooters' Location	Red	quired	:	Provided	MR
) (OF	THE DECEMBER 20		quired	Provi	ided	MR
3.	MOE	Address System		uired	Provi		MR
9.	Public	natic Sprinkler System	1100				I) (D
0.		Basements	Rec	quired	39	Provided	MR
		Upper Floor	NA			. NA	NA
		Sprinkler above false	NA		777	NA	NA
	•	ceiling			•		
11.	Intern	al Hydrants:				- INTA	NA
11.	Intern	Size of riser/down- cor	mer	NA		NA	
		Number of hydrants pe	er floo	r NA	_	NA	NA
		Hose Box		NA		NA	NA
-	Mand I	Hydrants	Ţ.			1374	NA
12.	Yard	Total number of	NA			NA .	1,1.2
		hydrants			-,	· NA	NA
		Hose Box	NA		-	11/21	
13.	Pumpi	ng Arrangements:	A. WE				
13.	•	Ground Level	1	NA		NA	NA
	•	Discharge of main pum		NA NA	¥	NA	NA
	► Head of main pump			NA NA		· NA	NA
	. 0	Number of main pumps		NA		NA	NA
-	>	Jockey pump out put		NA		NA	NA
	>	Jockey pump head	_	NA		NA	NA
		Standby Pump out put Standby Pump Head		NA		NA	NA
-	2	~ · -/\ (amiia)		NA		NA	NA
	>	stopping	A				
	D	Pump House Access	. 1	NA		. NA	NA
		Terrace level		٠.		100	TO THE RESERVE
	D	Discharge of pump	-	450 lpm		Provided	MR
1	A	Head of the pump		10 mtrs	١.	Provided	MR
	>	Power supply		Require		Provided	MR
		Auto starting of pump	I	Required	1	Provided	MR
		Auto Die C					
		Andrew St.		1			

4.	Captive water Storage for fir	e fighti	ing:					
	 Under ground tank capacity 	. NA		NA	NA			
	> Draw off connection	NA	2	NA .	NA			
	Fire service inlet	NA		Provided	NA			
	> Access to tank	NA		NA	NA			
 :	Overhead Tank capacity	100	00 ltr	Provided	MR			
5	Exit Signage	Req	uired	Provided	MR			
6.	Provision of Lifts							
	> Pressurization of Lift	Shaft	NA	NA	NA			
	Pressurization of lift lo	NA	NA	NA				
	 Communication in lift 	Required	Provided	MR				
	 Fireman's Grounding Switch 	Required	Provided	MR				
į.	➤ Lift Signage	Required	Provided	MR				
ä		-	Required	Provided	MR			
7.	Standby power supply		Require					
18.	Refuge Area	-	NA	NA .	NA			
	Total areaLocation	NA	NA NA	NA				
9.	Fire control room			l NA	NA			
	Detector system panel	'NA		NA NA				
	Flow Switch Panel N			NA NA	NA NA			
	> PA System Panel		Provided	MR				
	➤ Battery backup	Requ	ired	NA NA	NA			
	 Building Floor Plans 	NA	NA	NA NA	NA			
0.	Special Fire Protection System Protection of special Risks, if	s tor anv:	NA					

The fire protection systems provided in the building were test checked and found

functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter No. F6/DFS/MS/GH/SZ/2021/151, as required under the rules the NOC issued vide letter No. F6/DFS/MS/GH/SZ/2021/151, as required under Rule 37 of the Delhi Fire Service Rules 2010 is recommended. If approved FSC may be issued.

Signature of the Inspecting Officer

Name: Sh. Udaivir Singh Designation: ADO (DWK)

Go (52) Which

L Derry

MI

Any m